

**App. B:  
Petrie Decl., Ex. 2  
Part II**

## Confidential

|       |     |            |            |           |   |           |           |                       |   |  |        |  |   |
|-------|-----|------------|------------|-----------|---|-----------|-----------|-----------------------|---|--|--------|--|---|
| 9983  | 700 | 27359      | 308 WIN    | 2-Feb-12  | N | S         | 21-Feb-14 | 21-Feb-14             | Fired on Bolt Opening                                 | Altered Adjustments or Components              | 338474 | F  | Per llion, replace trigger, check over and test fire at no charge |
| 9988  | 700 | 25763      | 22-250 REM | 15-Jan-86 | N | S         | 24-Feb-14 | 24-Feb-14             | Fired on Bolt Closing                                 | AFT MKT TRIGGER ASSM                           | 338618 | F  | Per llion, replace trigger, check over, and test at 50% discount  |
| 9989  | 700 | N/A        | 17 REM     | 6-Apr-73  | N | S         | 24-Feb-14 | 24-Feb-14             | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 338549 | F  | Per llion, quote to repair BLM                                    |
| 9990  | 504 | 26500      | 22 LR      | 22-Feb-04 | N | S         | 24-Feb-14 | 24-Feb-14             | Fired on Safe Release                                 | Altered Adjustments or Components              | 338550 | F  | Per llion, check over, repair as needed, and test at 50% discount |
| 9991  | 700 | N/A        | 270 WIN    | 7-Aug-78  | N | S         | 24-Feb-14 | 11-Mar-14             | Fired on Bolt Closing                                 | Improper Maintenance                           | 340169 | F  | Per llion, quote to repair BLM                                    |
| 9993  | 597 | N/A        | 17 HMR     | 26-Aug-03 | N | PD/S      | 24-Feb-14 | 12-Mar-14             | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 340054 | F  | Replacing with Ramac 70701 in exchange                            |
| 9992  | 597 | 26536      | 17 HMR     | 27-Jan-03 | N | PD/S      | 24-Feb-14 | 15-Apr-15             | My Gun Blew Up  | Not Examined by Product Service                | 495494 | F  | Gun not examined by Product Service in llion                      |
| 9995  | 700 | 84206      | 223 REM    | 26-Jun-09 | N | S         | 25-Feb-14 | 25-Feb-14             | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 338721 | F  | Per llion - Repair at n/c - goodwill                              |
| 10001 | 700 | 84229      | 308 WIN    | 27-Apr-11 | N | S         | 25-Feb-14 | 7-Mar-14              | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 339914 | F  | Per llion, replace trigger, check over, and test at 50% discount  |
| 10002 | 700 | n/a        | 270 WIN    | 9-Apr-69  | N | S         | 25-Feb-14 | 7-Mar-14              | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 339793 | F  | Per llion - Quote to repair under BLM                             |
| 10005 | 700 | 85441      | 3006 SPRG  | 11-Sep-09 | N | S         | 26-Feb-14 | 26-Feb-14             | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 338824 | F  | Replacing with Ramac 87203 in exchange                            |
| 10006 | 700 | 27253      | 270 WSM    | 11-Sep-06 | N | S         | 26-Feb-14 | 26-Feb-14             | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 338764 | F  | Per llion, replace trigger, check over, and test at 50% discount  |
| 10007 | 740 | N/A        | 308 WIN    | 1-Oct-59  | N | S         | 26-Feb-14 | 26-Feb-14             | Fired on Bolt Closing                                 | Sent in for Evaluation                         | 338814 | F  | Per llion, check over, repair as needed, and test at no charge    |
| 10012 | 700 | n/a        | 243 WIN    | 20-May-71 | N | S         | 26-Feb-14 | 19-Mar-14             | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 340886 | F  | Per llion - Quote to repair under BLM                             |
| 10013 | 700 | not avail. | 3006 SPRG  | 17-Jul-75 | N | S         | 27-Feb-14 | 27-Feb-14             | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 338961 | F  | Per llion - Quote to repair under BLM                             |
| 10014 | 700 | 25709      | 308 WIN    | 24-Apr-13 | N | S         | 27-Feb-14 | 27-Feb-14             | Fired on Safe Release                                 | Other - Unspecified or Undetermined - Firearms | 338919 | F  | Per llion - Repair at n/c - warranty                              |
| 10015 | 700 | 27476      | 270 WIN    | 25-May-02 | N | S         | 27-Feb-14 | 27-Feb-14             | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 339015 | F  | Per llion, replace trigger, check over, and test at 50% discount  |
| 10016 | 320 | 24813      | 12 GA      | 4-Nov-94  | N | S         | 27-Feb-14 | 27-Feb-14             | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation                         | 338935 | F  | Per llion, check over, repair as needed, and test at 50% discount |
| 10017 | 700 | not avail. | 270 WIN    | 3-Apr-74  | N | S         | 27-Feb-14 | 27-Feb-14             | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 338938 | F  | Per llion - Quote to repair under BLM                             |
| 10018 | 597 | 26550      | 22 LR      | 20-Nov-98 | N | S         | 27-Feb-14 | 27-Feb-14             | Ammunition Exploded                                   | Other - Unspecified or Undetermined - Firearms | 339007 | F  | Per llion, check over, repair as needed, and test at no charge    |
| 10022 | 700 | n/a        | 8-Jun-73   | N         | S | 27-Feb-14 | 27-Feb-14 | Fired on Safe Release | Not Examined by Product Service                       | n/a  | F      | Referred customer to Gravel Agency in Canada |   |
| 10023 | 700 | 27480      | 7MM REM MA | 3-May-00  | N | S         | 27-Feb-14 | 12-Mar-14             | Fired on Bolt Closing                                 | Improper Maintenance                           | 340289 | F  | Per llion - Quote to repair @ discount                            |
| 10025 | 870 | 25583      | 20 GA      | 11-Sep-13 | N | S         | 28-Feb-14 | 28-Feb-14             | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 339062 | F  | Per llion, check over, repair as needed, and test at no charge    |

RAC001182

## Confidential

|       |       |            |            |           |   |         |           |           |   |  |        |   |   |
|-------|-------|------------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|---|
| 10026 | 660   | N/A        | 308 WIN    | 19-Aug-69 | N | S       | 28-Feb-14 | 28-Feb-14 | Fired With Safe ON                                    | Could Not Duplicate Concern                    | 339218 | F | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10027 | 660   | not avail. | 243 WIN    | 10-Jul-69 | N | S       | 28-Feb-14 | 28-Feb-14 | Fired on Safe Release                                 | Improper Maintenance                           | 339196 | F | Per Ilion - Repair at n/c   |
| 10032 | 700   | n/a        | 3006 SPRG  | 16-May-78 | N | S       | 28-Feb-14 | 7-Oct-14  | Fired on Safe Release                                 | Altered Adjustments or Components              | 470289 | F | Ilion repaired at n/c under BLM                                     |
| 10035 | 700ML | 27588      | 50 CAL     | 12-Nov-01 | Y | S       | 28-Feb-14 | 14-Mar-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 340473 | F | Per Ilion - Quote to repair @ discount                              |
| 10037 | 870   | 25568      | 12 GA      | 7-Feb-14  | N | S       | 3-Mar-14  | 3-Mar-14  | Fired With Safe ON                                    | Improper Assembly by Customer                  | 339357 | F | Per Ilion, check over, repair as needed, and test at no charge      |
| 10038 | 700   | not avail. | 223 REM    |           | N | S       | 3-Mar-14  | 3-Mar-14  | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Consumer does not own the rifle & refused to provide owner's name   |
| 10043 | 700   | not avail. | 7MM MAG    | 8-Jun-80  | N | S       | 3-Mar-14  | 6-Apr-15  | Fired on Bolt Closing                                 | Not Examined by Product Service                | 341099 | F | Not Examined by Product Service                                     |
| 10044 | 721   | N/A        | 270 WIN    | 1-Dec-53  | N | S       | 4-Mar-14  | 4-Mar-14  | Dissatisfied with Service - Firearms                  | Altered Adjustments or Components              | 339458 | F | Replace trigger, check over, and test at no charge                  |
| 10047 | 700   | N/A        | 300 WBY MA | 12-Jun-93 | N | S       | 4-Mar-14  | 14-Mar-14 | Delayed Firing - Firearms                             | Altered Adjustments or Components              | 340521 | F | Per Ilion, replace trigger, check over, and test at 50% discount    |
| 10049 | 710   | 27410      | 3006 SPR   | 30-Nov-05 | Y | PD/S    | 4-Mar-14  | 6-Apr-15  | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Gun not returned to Ilion for exam                                  |
| 10052 | 1911  | 96323      | 45 ACP     | 19-Apr-13 | N | PI/PD/S | 5-Mar-14  | 24-Mar-14 | Personal Injury while using firearm                   | Other - Unspecified or Undetermined - Firearms | 340873 | F | Check over completely, repair as needed, and test fire at no charge |
| 10054 | 700   | not avail. | 22-250 REM | 29-Nov-77 | N | S       | 6-Mar-14  | 6-Mar-14  | Fired on Safe Release                                 | Altered Adjustments or Components              | 339647 | F | Per Ilion - Quote to repair under BLM                               |
| 10058 | 700   | 25787      | 243 WIN    | 5-May-03  | N | PD/S    | 6-Mar-14  | 8-Oct-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 470122 | F | Check over completely, repair as needed, and test fire at no charge |
| 10059 | 700   | 29694      | 300 WIN MA | 23-Apr-93 | N | S       | 6-Mar-14  | 31-Mar-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 341925 | F | Per Ilion, check over, repair as needed, and test at 50% discount   |
| 10061 | 887   | 82502      | 12 GA      | 13-Jan-14 | N | S       | 7-Mar-14  | 7-Mar-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 339812 | F | Per Ilion - Repair at n/c - warranty                                |
| 10074 | 597   | 26536      | 17 HMR     | 26-Mar-03 | N | PD/S    | 10-Mar-14 | 6-Mar-14  | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 342215 | F | Replacing with Ramac 70723 in exchange                              |
| 10076 | 700   | N/A        | 25-06 REM  | 19-Mar-71 | N | S       | 11-Mar-14 | 6-Apr-15  | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Gun not returned to Ilion for exam                                  |
| 10078 | 700   | 84521      | 270 WIN    | 26-Mar-11 | N | S       | 12-Mar-14 | 12-Mar-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 340244 | F | Per Ilion - Quote to repair @ discount                              |
| 10079 | 700   | not avail. | 7MM REM MA | 21-May-75 | N | S       | 12-Mar-14 | 12-Mar-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 340305 | F | Per Ilion - Quote to repair under BLM                               |
| 10083 | 700   | 27512      | 22-250 REM | 3-Mar-03  | N | S       | 14-Mar-14 | 14-Mar-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 340486 | F | Returning as received   |
| 10084 | 7     | 24792      | 17 REM     | 21-May-92 | N | S       | 14-Mar-14 | 16-Apr-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 340476 | F | Repair @ n/c  |
| 10085 | 700   | N/A        | 243 WIN    | 8-Sep-78  | N | S       | 14-Mar-14 | 14-Mar-14 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 340274 | F | Per Ilion, quote to repair BLM                                      |
| 10086 | 700   | not avail. | 270 WIN    | 11-Nov-70 | N | PD/S    | 14-Mar-14 | 31-Mar-14 | Fired With Safe ON                                    | Could Not Duplicate Concern                    | 341408 | F | BLM @ n/c - goodwill gesture  |
| 10088 | 700   | not avail. | 3006 SPRG  | 2-Feb-81  | N | S       | 14-Mar-14 | 27-Mar-14 | Fired on Safe Release                                 | Improper Maintenance                           | 341696 | F | Repair @ n/c - goodwill gesture                                     |
| 10089 | 597   | N/A        | 17 HMR     |           | N | PI/PD/S | 14-Mar-14 | 14-Apr-15 | My Gun Blew Up  | Not Examined by Product Service                | n/a    | F | Gun not returned to Ilion for exam                                  |

RAC001183

## Confidential

|       |         |            |            |           |   |         |           |           |                           |  |                       |                                 |   |   |                                    |
|-------|---------|------------|------------|-----------|---|---------|-----------|-----------|---------------------------|--|-----------------------|---------------------------------|---|---|------------------------------------|
| 10092 | 700     | 84152      | 7MM RUM    | 25-Jan-08 | N | S       | 17-Mar-14 | 17-Mar-14 | Fired on Safe Release     | Could Not Duplicate Concern                    | 340635                | F                               | Per Ilion, replace trigger, check over, and test at 50% discount                              |   |                                    |
| 10097 | 597     | 26516      | 17 HMR     | 4-May-04  | N | PI/PD/S | 17-Mar-14 | 1-Apr-14  | My Gun Blew Up            | Other - Unspecified or Undetermined - Firearms | 342024                | F                               | Replacing with Ramac 70723 in exchange  |   |                                    |
| 10095 | 597     | 26516      | 17 HMR     | 9-Feb-03  | N | PI/PD/S | 17-Mar-14 | 7-Jan-15  | My Gun Blew Up            | Other - Unspecified or Undetermined - Firearms | 479355                | F                               | Replace with Ramac 70743 in exchange  |   |                                    |
| 10101 | 597     | N/A        | 17 HMR     | 7-Feb-03  | N | PD/S    | 18-Mar-14 | 16-Apr-14 | My Gun Blew Up            | Other - Unspecified or Undetermined - Firearms | 343381                | F                               | Converting to 22 WMR as requested by customer, repair and check over completely at no charge. |   |                                    |
| 10098 | XM15E25 | 90391      | 223/5.56   | 24-Jun-13 | N | S       | 19-Mar-14 | 19-Mar-14 | Went Automatic            | Could Not Duplicate Concern                    | 340899                | F                               | Per Ilion - Repair at n/c   |   |                                    |
| 10099 | 700     | 29694      | 300 WIN MA | 26-Aug-94 | N | S       | 19-Mar-14 | 19-Mar-14 | Fail to Fire              | Altered Adjustments or Components              | 340844                | F                               | Per Ilion, replace trigger, check over, and test at 50% discount                              |   |                                    |
| 10100 | 597     | 80852      | 22 LR      | 21-Dec-12 | N | S       | 19-Mar-14 | 19-Mar-14 | Defective Parts           | Could Not Duplicate Concern                    | 340917                | F                               | Per Ilion - Repair at n/c - warranty  |   |                                    |
| 10103 | 870     | 25587      | 12 GA      | 20-Aug-13 | N | S       | 20-Mar-14 | 20-Mar-14 | Fired With Safe ON        | Could Not Duplicate Concern                    | 340992                | F                               | Per Ilion, replace trigger, check over and test fire at no charge                             |   |                                    |
| 10105 | 700     | 85433      | 223 REM    | 8-Feb-11  | N | S       | 20-Mar-14 | 20-Mar-14 | Fired on Safe Release     | Could Not Duplicate Concern                    | 341073                | F                               | Per Ilion - Repair at n/c - warranty  |   |                                    |
| 10110 | 597     | 80910      | 22 LR      | 30-Aug-13 | N | S       | 21-Mar-14 | 21-Mar-14 | Fired Out of Battery      | Other - Unspecified or Undetermined - Firearms | 341151                | F                               | Per Ilion, check over, repair as needed, and test at no charge                                |   |                                    |
| 10112 | 600     | N/A        | 243 WIN    | 18-Jun-71 | N | S       | 24-Mar-14 | 24-Mar-14 | Fired on Bolt Closing     | Improper Maintenance                           | 341310                | F                               | Per Ilion, replace trigger, check over and test fire at no charge                             |   |                                    |
| 10113 | 541     | 29800      | 22 LR      | 7-Jun-76  | N | S       | 24-Mar-14 | 24-Mar-14 | Fired on Safe Release     | Altered Adjustments or Components              | 341323                | F                               | Per Ilion, check over, repair as needed, and test at 50% discount                             |   |                                    |
| 10114 | 700     | N/A        | 6MM REM    | 1-Oct-68  | N | S       | 24-Mar-14 | 24-Mar-14 | Fired on Safe Release     | Improper Maintenance                           | 341320                | F                               | Per Ilion, quote to repair BLM  |   |                                    |
| 10118 | 700     | 29699      | 300 WBY MA | 19-May-90 | N | S       | 25-Mar-14 | 22-Apr-14 | Fired on Bolt Closing     | Could Not Duplicate Concern                    | 343684                | F                               | Replace trigger, check over, and test at no charge  |   |                                    |
| 10119 | 597     | 26536      | 17 HMR     | 31-Mar-03 | N | PD/S    | 25-Mar-14 | 14-Apr-14 | My Gun Blew Up            | Other - Unspecified or Undetermined - Firearms | 343103                | F                               | Converting to 22 WMR as requested by customer, repair and check over completely at no charge. |   |                                    |
| 10124 | 1911    | 96323      | 45 ACP     | 24-May-10 | N | S       | 25-Mar-14 | 13-Apr-15 | Fired on Bolt Closing     | Not Examined by Product Service                | n/a                   | F                               | Gun not returned to Ilion for exam  |   |                                    |
| 10125 | 770     | not avail. | 7MM REM MA |           |   |         | N         | PD/S      | 25-Mar-14                 | 6-Apr-15                                       | Fired on Bolt Closing | Not Examined by Product Service | n/a   | F | Gun not returned to Ilion for exam |
| 10041 | 700     | 84515      | 3006 SPR   | 15-Feb-10 | N | S       | 26-Mar-14 | 2-Apr-14  | Fired on Safe Release     | Could Not Duplicate Concern                    | 341512                | F                               | Per Derek Watkins, gun will be checked over completely at no charge.                          |   |                                    |
| 10120 | 660     | N/A        | 243 WIN    | 9-Feb-70  | N | S       | 26-Mar-14 | 26-Mar-14 | Fired on Bolt Closing     | Could Not Duplicate Concern                    | 341450                | F                               | Per Ilion, quote to repair BLM  |   |                                    |
| 10121 | 700     | 26129      | 3006 SPRG  | 23-Dec-98 | N | S       | 26-Mar-14 | 26-Mar-14 | Delayed Firing - Firearms | Altered Adjustments or Components              | 341498                | F                               | Per Ilion, replace trigger, check over, and test at 50% discount                              |   |                                    |
| 10122 | 700     | 27267      | 270 WIN    | 17-Jun-13 | N | S       | 26-Mar-14 | 26-Mar-14 | Fired on Safe Release     | Could Not Duplicate Concern                    | 341645                | F                               | Per Ilion, replace trigger, check over and test fire at no charge                             |   |                                    |
| 10134 | 722     | N/A        | 222 REM    | 1-Feb-52  | Y | S       | 28-Mar-14 | 16-Apr-14 | Fired on Bolt Closing     | Could Not Duplicate Concern                    | 343372                | F                               | Per Ilion, quote to repair BLM  |   |                                    |

RAC001184

## Confidential

|       |           |            |            |           |   |         |           |           |   |  |        |   |   |
|-------|-----------|------------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|---|
| 10135 | 700       | not avail. | 3006 SPRG  | 1-Sep-69  | N | S       | 28-Mar-14 | 29-May-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 413287 | F | Repair @ n/c  |
| 10136 | 700       | 85375      | 7MM REM MA | 23-Sep-08 | N | S       | 31-Mar-14 | 31-Mar-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 341892 | F | Replace trigger, check over, and test at no charge                |
| 10137 | 700       | 27351      | 223 REM    | 8-Aug-08  | N | S       | 31-Mar-14 | 17-Apr-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 343450 | F | Per llion, replace trigger, check over and test fire at no charge |
| 10140 | 700       | 26039      | 7MM REM MA | 7-Dec-01  | N | S       | 31-Mar-14 | 8-Apr-14  | Fired on Safe Release                                 | Improper Maintenance                             | 342722 | F | Per llion - Quote to repair @ discount                            |
| 10146 | 700       | 27455      | 300 WIN MA | 19-Nov-02 | N | S       | 1-Apr-14  | 1-Apr-14  | Fired With Safe ON                                    | Could Not Duplicate Concern                      | 342058 | F | Repair @ n/c - goodwill gesture                                   |
| 10147 | 700       | 29709      | 270 WIN    | 23-Aug-94 | N | S       | 1-Apr-14  | 17-Apr-14 | Fired on Safe Release                                 | Improper Maintenance                             | 343553 | F | Per llion, replace trigger, check over, and test at 50% discount  |
| 10152 | 597       | N/A        | 17 HMR     | 15-Jun-04 | N | PI/PD/S | 1-Apr-14  | 6-May-14  | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms   | 343645 | F | Replacing with Ramac 70723 in exchange                            |
| 10156 | 700       | 25768      | 2506 REM   | 19-Jan-83 | N | S       | 3-Apr-14  | 3-Apr-14  | Fired on Safe Release                                 | Broken or Missing Parts                          | 342176 | F | Per llion - Quote to repair @ discount                            |
| 10158 | 1911      | 96324      | 45ACP      | 7-Mar-12  | N | S       | 3-Apr-14  | 3-Apr-14  | Went Automatic  | Other - Unspecified or Undetermined - Firearms   | 342298 | F | Per llion, check over, repair as needed, and test at no charge    |
| 10160 | XM15E2S   | N/A        | 223/5.56   | 21-Jul-09 | N | S       | 3-Apr-14  | 3-Apr-14  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 342260 | F | Per llion, check over, repair as needed, and test at no charge    |
| 10161 | 600       | N/A        | 222 REM    | 12-Jul-77 | Y | S       | 3-Apr-14  | 3-Apr-14  | Fired on Bolt Closing                                 | Improper Maintenance                             | 342300 | F | Per llion, quote to repair BLM                                    |
| 10168 | 700       | N/A        | 7MM REM MA | 8-Nov-73  | N | S       | 4-Apr-14  | 4-Apr-14  | Delayed Firing - Firearms                             | Improper Maintenance                             | 342358 | F | Per llion, check over, repair as needed, and test at 50% discount |
| 10169 | 700       | 84466      | 223 REM    | 14-Mar-09 | N | S       | 4-Apr-14  | 1-May-14  | Blowback in Face                                      | Other - Unspecified or Undetermined - Ammunition | 342422 | F | Per llion, check over, repair as needed, and test at no charge    |
| 10171 | 887       | 82500      | 12 GA      | 19-Jul-13 | N | S       | 4-Apr-14  | 4-Apr-14  | Fired With Safe ON                                    | Sent in for Evaluation                           | 342468 | F | Per llion, check over, repair as needed, and test at no charge    |
| 10174 | SP10      | not avail. | 10 GA      |           | Y | S       | 7-Apr-14  | 2-May-14  | Went Automatic  | Could Not Duplicate Concern                      | 342536 | F | Quote to repair at a discount - goodwill gesture                  |
| 10186 | 597       | 26536      | 17 HMR     | 19-Mar-03 | N | PI/PD/S | 8-Apr-14  | 22-Apr-14 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms   | 343680 | F | Sent 5250 rebate coupon as requested by customer                  |
| 10191 | 770       | 85655      | 270 WIN    | 29-Oct-08 | N | S       | 9-Apr-14  | 9-Apr-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 342833 | F | Per llion, replace trigger, check over, and test at 50% discount  |
| 10196 | DPMS A-15 | not avail. | 223 REM    |           | N | PD/S    | 9-Apr-14  | 19-May-14 | Fired With Safe ON                                    | Other - Unspecified or Undetermined - Firearms   | n/a    | F | Per Release - \$2,992.69 reimbursement for gun & damages          |
| 10206 | 700       | 25793      | 3006 SPRG  | 16-Jul-90 | N | S       | 10-Apr-14 | 23-Apr-14 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components                | 343932 | F | Repair @ n/c - goodwill gesture                                   |
| 10207 | 700       | N/A        | 3006 SPRG  | 1-Oct-74  | N | S       | 11-Apr-14 | 11-Apr-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 342998 | F | Per llion, quote to repair BLM                                    |
| 10208 | 541       | 29800      | 22 RF      | 2-Apr-82  | Y | S       | 11-Apr-14 | 11-Apr-14 | Fired on Safe Release                                 | Improper Maintenance                             | 342981 | F | Per llion - Quote to repair @ discount                            |
| 10212 | 700       | 25827      | 6MM REM    | 24-Jan-90 | N | S       | 14-Apr-14 | 14-Apr-14 | Delayed Firing - Firearms                             | Improper Maintenance                             | 343099 | F | Per llion, replace trigger, check over, and test at 50% discount  |

RAC001185

Confidential

|       |           |            |            |           |   |      |           |           |   |  |        |   |   |
|-------|-----------|------------|------------|-----------|---|------|-----------|-----------|---|--|--------|---|---|
| 10217 | 700       | 27169      | 7MM REM MA | 13-Jun-06 | N | S    | 15-Apr-14 | 15-Apr-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 343278 | F | Per Iliion, replace trigger, check over and test fire at no charge                            |
| 10218 | 522       | 29792      | 22 LR      | 11-Jun-93 | N | S    | 15-Apr-14 | 15-Apr-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 343286 | F | Returning as received   |
| 10219 | 700       | 85409      | 7MM08 REM  | 28-May-10 | N | S    | 15-Apr-14 | 15-Apr-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 343294 | F | Per Iliion, replace trigger, check over and test fire at no charge                            |
| 10221 | 887       | 82502      | 12 GA      | 29-Oct-09 | N | S    | 15-Apr-14 | 15-Apr-14 | Fired Out of Battery                                  | Could Not Duplicate Concern                    | 343228 | F | Per Iliion, check over, repair as needed, and test at no charge                               |
| 10222 | 770       | 85633      | 3006 SPRG  | 21-Nov-11 | N | S    | 15-Apr-14 | 15-Apr-14 | Delayed Firing - Firearms                             | Could Not Duplicate Concern                    | 343238 | F | Per Iliion, check over, repair as needed, and test at no charge                               |
| 10228 | 722       | 20000      | 222 REM    | 1-Feb-53  | N | S    | 16-Apr-14 | 16-Apr-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 343428 | F | Per Iliion, quote to repair BLM   |
| 10233 | 700       | N/A        | 270 WIN    | 27-May-81 | N | S    | 17-Apr-14 | 17-Apr-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 343487 | F | Per Iliion, quote to repair BLM   |
| 10234 | 700       | N/A        | 6MM REM    | 27-Sep-73 | N | S    | 17-Apr-14 | 17-Apr-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 343471 | F | Per Iliion, replace trigger, check over and test fire at no charge                            |
| 10235 | 7400      | 24716      | 3006 SPRG  | 18-Jan-90 | Y | PD/S | 17-Apr-14 | 19-Jun-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 417226 | F | Repair @ n/c - goodwill gesture   |
| 10236 | 700       | not avail. | 3006 SPR   | 16-Jun-78 | N | PI/S | 17-Apr-14 | 6-Apr-15  | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Gun not returned to Iliion for exam   |
| 10237 | 700       | N/A        | 7MM REM MA | 17-Jan-73 | N | S    | 21-Apr-14 | 21-Apr-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 343581 | F | Per Iliion, replace trigger, check over and test fire at no charge                            |
| 10239 | 700       | 84371      | 308 WIN    | 6-May-10  | N | S    | 21-Apr-14 | 21-Apr-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 343595 | F | Per Iliion, replace trigger, check over and test fire at no charge                            |
| 10244 | 700       | 27480      | 7MM REM MA | 25-Mar-00 | N | PD/S | 21-Apr-14 | 15-May-14 | Unexplained Discharge Safe ON                         | Could Not Duplicate Concern                    | 401057 | F | Check over completely, repair as needed, and test fire at no charge                           |
| 10247 | CARBON 15 | 90689      | 223/5.56   | 8-Apr-09  | N | S    | 23-Apr-14 | 23-Apr-14 | Went Automatic  | Could Not Duplicate Concern                    | 343919 | F | Per Iliion, replace trigger, check over and test fire at no charge                            |
| 10248 | 597       | 26514      | 17 HMR     | 22-Feb-05 | N | PD/S | 23-Apr-14 | 21-May-14 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 343867 | F | Converting to 22 WMR as requested by customer, repair and check over completely at no charge. |
| 10249 | XM15E2S   | 90641      | 5.56       | 31-Jul-12 | N | S    | 23-Apr-14 | 23-Apr-14 | Went Automatic  | Could Not Duplicate Concern                    | 343901 | F | Per Iliion, check over, repair as needed, and test at no charge                               |
| 10251 | 700       | 25709      | 308 WIN    | 4-Jun-12  | N | S    | 23-Apr-14 | 23-Apr-14 | Light Trigger Pull                                    | Altered Adjustments or Components              | 343978 | F | Per Iliion, replace trigger, check over and test fire at no charge                            |
| 10256 | CARBON 15 | 90689      | 5.56       | 16-May-13 | N | S    | 24-Apr-14 | 24-Apr-14 | Went Automatic  | Sent in for Evaluation                         | 344113 | F | Per Iliion, replace trigger, check over and test fire at no charge                            |
| 10258 | 597       | 26536      | 17 HMR     | 18-Jun-03 | N | PD/S | 24-Apr-14 | 6-May-14  | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 388643 | F | Converting to 22 WMR as requested by customer, repair and check over completely at no charge. |
| 10268 | 700       | 25718      | 300 WIN MA | 14-May-13 | N | S    | 28-Apr-14 | 19-May-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 406340 | F | Per Iliion, replace trigger, check over and test fire at no charge                            |

RAC001186

## Confidential

|       |           |            |            |           |   |         |           |           |   |  |        |   |   |
|-------|-----------|------------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|---|
| 10269 | 597       | 26536      | 17 HMR     | 29-Oct-02 | N | PI/PD/S | 28-Apr-14 | 15-Jul-14 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 436219 | O | Replacing with Ramac 70741 in exchange                            |
| 10273 | 700       | N/A        | 6MM REM    |           | N | S       | 28-Apr-14 | 25-Jun-14 | Unexplained Discharge Safe OFF                        | Could Not Duplicate Concern                    | 429202 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10267 | 600       | N/A        | 308 WIN    | 1-Jun-67  | N | S       | 29-Apr-14 | 29-Apr-14 | Fired on Bolt Closing                                 | Improper Maintenance                           | 344619 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10272 | CARBON 15 | 90689      | 5.56       | 12-Jun-13 | N | S       | 30-Apr-14 | 30-Apr-14 | Went Automatic  | Sent in for Evaluation                         | 353003 | F | Per Ilion, check over, repair as needed, and test at no charge    |
| 10281 | 597       | 26516      | 17 HMR     | 14-Oct-03 | N | S       | 30-Apr-14 | 22-May-14 | Other - Firearms                                      | Other - Unspecified or Undetermined - Firearms | 409019 | F | Replacing with Ramac 70723 in exchange                            |
| 10277 | 597       | 26550      | 22 LR      | 2-Oct-13  | N | S       | 1-May-14  | 1-May-14  | Went Automatic  | Could Not Duplicate Concern                    | 353894 | F | Per Ilion, check over, repair as needed, and test at no charge    |
| 10282 | 597       | 26516      | 17 HMR     | 26-Jul-06 | N | S       | 1-May-14  | 22-Oct-15 | Other - Firearms                                      | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                            |
| 10283 | BACR      | 90838      | 5.56       | 24-Sep-13 | N | S       | 2-May-14  | 2-May-14  | Went Automatic  | Could Not Duplicate Concern                    | 356653 | F | Per Ilion, check over, repair as needed, and test at no charge    |
| 10285 | 700       | not avail. | 7MM REM EX | 1-Sep-79  | N | S       | 2-May-14  | 7-Oct-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 470220 | F | Ilion repaired at n/c under BLM                                   |
| 10288 | CARBON 15 | 90689      | 223/5.56   | 8-Dec-12  | N | S       | 5-May-14  | 5-May-14  | Went Automatic  | Sent in for Evaluation                         | 374504 | F | Per Ilion - Repair at n/c - warranty                              |
| 10290 | 700       | not avail. | 3006 SPR   | 4-Apr-72  | N | S       | 5-May-14  | 16-May-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 406052 | F | Per Ilion - Repair at n/c   |
| 10293 | 700       | not avail. | 3006 SPR   | 7-Mar-79  | N | S       | 5-May-14  | 22-May-14 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 409418 | F | Per Ilion - Quote to repair under BLM & refinish                  |
| 10289 | Seven     | 29559      | 7mm SAUM   | 24-Feb-03 | N | S       | 5-May-14  | 6-Apr-15  | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Gun not returned to Ilion for exam                                |
| 10294 | 700       | 25634      | 3006 SPRG  | 18-Jul-90 | N | S       | 6-May-14  | 6-May-14  | Fired on Bolt Closing                                 | Improper Maintenance                           | 387155 | F | Repair @ n/c  |
| 10295 | 700       | 27475      | 243 WIN    | 9-Jul-09  | N | PI/S    | 6-May-14  | 16-Jun-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 415730 | F | Repair @ n/c  |
| 10296 | 700       | 27099      | 300 WM     | 6-Jun-12  | N | S       | 7-May-14  | 7-May-14  | Fired on Safe Release                                 | Broken or Missing Parts                        | 395609 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10297 | 700       | N/A        | 3006 SPRG  | 27-May-88 | N | S       | 7-May-14  | 7-May-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 395642 | F | Per Ilion, check over, repair as needed, and test at no charge    |
| 10305 | 700       | 27476      | 270 WIN    | 28-Jun-95 | N | S       | 8-May-14  | 8-May-14  | Delayed Firing - Firearms                             | Improper Maintenance                           | 400935 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10306 | LR-308    | 90828      | 308 WIN    | 12-Apr-13 | N | S       | 8-May-14  | 8-May-14  | Went Automatic  | Sent in for Evaluation                         | 401119 | F | Per Ilion, check over, repair as needed, and test at no charge    |
| 10307 | 700       | 84404      | 3006 SPRG  | 13-May-09 | N | S       | 8-May-14  | 8-May-14  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 401067 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10311 | 700       | 84215      | 223 REM    | 10-Jan-11 | N | PD/S    | 9-May-14  | 4-Aug-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 432576 | F | Replace trigger at no charge, Reimburse damage to ceiling \$575.  |
| 10309 | 700       | not avail. | 3006 SPRG  | 3-Feb-81  | N | S       | 12-May-14 | 12-May-14 | Fired With Safe ON                                    | Could Not Duplicate Concern                    | 401789 | F | Per Ilion - Repair at n/c   |

RAC001187

Confidential

|       |           |            |           |           |   |         |           |           |   |  |        |   |   |
|-------|-----------|------------|-----------|-----------|---|---------|-----------|-----------|---|--|--------|---|---|
| 10312 | 597       | 26516      | 17 HMR    | 26-Aug-03 | N | PD/S    | 13-May-14 | 13-May-14 | Fired Out of Battery                                  | Other - Unspecified or Undetermined - Firearms | 402114 | F | Converting to 22 WMR as requested by customer, repair and check over completely at no charge. |
| 10313 | 700       | 85351      | 223 REM   | 5-Mar-08  | N | S       | 13-May-14 | 13-May-14 | Fired on Bolt Closing                                 | AFT MKT TRIGGER ASSM                           | 402151 | F | Per Ilion, replace trigger, check over and test fire at no charge                             |
| 10314 | 700       | 27119      | 243 WIN   | 21-Jul-08 | N | PD/S    | 13-May-14 | 19-Jun-14 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 418453 | F | Repair @ n/c  |
| 10316 | 597       | 26536      | 17 HMR    | 5-Nov-02  | N | PI/PD/S | 13-May-14 | 22-May-14 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 409119 | F | Replacing with Ramac 70723 in exchange  |
| 10319 | CARBON 15 | 90689      | 5.56      | 10-Apr-13 | N | S       | 15-May-14 | 15-May-14 | Went Automatic  | Sent in for Evaluation                         | 404279 | F | Gun replaced by Consumer Service  |
| 10320 | 788       | not avail. | 308 WIN   | 27-Dec-78 | Y | S       | 15-May-14 | 29-May-14 | Fired on Safe Release                                 | Improper Maintenance                           | 413218 | F | Quote to repair at a discount goodwill gesture  |
| 10321 | 700       | N/A        | 3006 SPRG | 28-Feb-74 | N | S       | 16-May-14 | 16-May-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 405188 | F | Per Ilion, replace trigger, check over and test fire at no charge                             |
| 10323 | 700       | 27391      | 7MM-08    | 21-Mar-13 | N | PD/S    | 16-May-14 | 4-Feb-15  | Unexplained Discharge - No Mention of Safety Position | Not Examined by Product Service                | 331089 | F | Gun not examined by Product Service   |
| 10327 | 597       | N/A        | 17 HMR    | 18-Jun-03 | N | PD/S    | 19-May-14 | 3-Jun-14  | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 414850 | F | Converting to 22 WMR as requested by customer, repair and check over completely at no charge. |
| 10328 | 597       | N/A        | 17 HMR    | 26-Mar-04 | N | PD/S    | 19-May-14 | 3-Jun-14  | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 414888 | F | Converting to 22 WMR as requested by customer, repair and check over completely at no charge. |
| 10331 | 700       | 25793      | 3006 SPR  | 14-Oct-94 | N | S       | 19-May-14 | 6-Jun-14  | Fired With Safe ON                                    | Improper Maintenance                           | 417515 | F | Per Ilion, replace trigger, check over and test fire at no charge                             |
| 10330 | 660       | N/A        | 243 WIN   | 1-May-68  | Y | S       | 20-May-14 | 20-May-14 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 407527 | F | Per Ilion, replace trigger, check over and test fire at no charge                             |
| 10332 | 700       | 85478      | 270 WIN   | 18-May-10 | N | S       | 20-May-14 | 20-May-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 407524 | F | Per Ilion - Replace TA @ n/c to restore confidence  |
| 10333 | 700       | 25714      | 223 REM   | 8-May-13  | N | S       | 20-May-14 | 20-May-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 407781 | F | Per Ilion, replace trigger, check over and test fire at no charge                             |
| 10334 | 700       | 84461      | 308 WIN   | 24-Feb-10 | N | S       | 20-May-14 | 20-May-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 407806 | F | Per Ilion, replace trigger, check over and test fire at no charge                             |
| 10335 | 700       | 84207      | 308 WIN   | 13-Feb-12 | N | S       | 20-May-14 | 20-May-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 407834 | F | Per Ilion, replace trigger, check over and test fire at no charge                             |
| 10336 | 700       | N/A        | 3006 SPRG | 22-Jun-81 | N | S       | 20-May-14 | 20-May-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 407510 | F | Per Ilion, replace trigger, check over and test fire at no charge                             |
| 10338 | 700       | 27094      | 270 WIN   | 28-Jul-10 | N | PD/S    | 20-May-14 | 28-Jul-14 | Unexplained Discharge - No Mention of Safety Position | Over pressured shell                           | 420338 | F | Ilion repaired firearm and Lonoke will send customer ammunition replacement.                  |

RAC001188

## Confidential

|       |                |            |            |           |   |      |           |           |                           |   |                                 |        |   |   |
|-------|----------------|------------|------------|-----------|---|------|-----------|-----------|---------------------------|---|---------------------------------|--------|---|---|
| 10342 | 597            | 26516      | 17 HMR     | 14-Jan-04 | N | PD/S | 20-May-14 | 16-Jun-14 | My Gun Blew Up            | Other - Unspecified or Undetermined - Firearms        | 421594                          | O      | Converting to 22 WMR as requested by customer, repair and check over completely at no charge. |   |
| 10340 | CARBON 15      | 90689      | 5.56       | 20-Mar-13 | N | S    | 21-May-14 | 21-May-14 | Went Automatic            | Other - Unspecified or Undetermined - Firearms        | 408652                          | F      | Per Ilion, replace trigger, check over and test fire at no charge                             |   |
| 10343 | 700            | 27516      | 308 WIN    | 17-Nov-01 | N | S    | 21-May-14 | 24-Jul-14 | Fired on Bolt Closing     | Altered Adjustments or Components                     | 416743                          | F      | Per Release - Replace w/29663 in exchange   |   |
| 10346 | 700            | 25798      | 223 REM    | 19-Feb-02 | N | S    | 23-May-14 | 9-Jun-14  | Fired on Bolt Closing     | Could Not Duplicate Concern                           | 417894                          | F      | Per Ilion, replace trigger, check over and test fire at no charge                             |   |
| 10347 | 597            | 26536      | 17 HMR     | 12-Feb-03 | N | PD/S | 27-May-14 | 12-Jun-14 | My Gun Blew Up            | Other - Unspecified or Undetermined - Firearms        | 420329                          | F      | Replacing with Ramac 70723 in exchange  |   |
| 10348 | 700            | 27133      | 223 REM    | 29-Mar-12 | N | S    | 28-May-14 | 28-May-14 | Fired on Bolt Closing     | Could Not Duplicate Concern                           | 411366                          | F      | Per Ilion, replace trigger, check over and test fire at no charge                             |   |
| 10349 | 700            | 27516      | 308 WIN    | 25-May-04 | N | S    | 28-May-14 | 28-May-14 | Fired With Safe ON        | Could Not Duplicate Concern                           | 411772                          | F      | Per Ilion, replace trigger, check over and test fire at no charge                             |   |
| 10352 | 700            | 26129      | 3006 SPR   | 30-Oct-01 | N | S    | 28-May-14 | 6-Apr-15  | Delayed Firing - Firearms | Not Examined by Product Service                       | n/a                             | F      | Gun not returned to Ilion for exam  |   |
| 10354 | 700            | not avail. | 3006 SPR   |           |   | N    | PD/S      | 28-May-14 | 6-Apr-15                  | Fired on Safe Release                                 | Not Examined by Product Service | n/a    | F   | Gun not returned to Ilion for exam                                  |
| 10357 | 700            | 26285      | 7MM 08 REM | 10-Jul-06 | N | S    | 29-May-14 | 29-May-14 |                           | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern     | 413568 | F   | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10359 | 700            | 25933      | 7MM REM MA | 15-Jan-96 | N | S    | 29-May-14 | 29-May-14 | Fired on Safe Release     | Altered Adjustments or Components                     | 413709                          | F      | Per Ilion, replace trigger, check over and test fire at no charge                             |   |
| 10360 | 700            | 84370      | 223 REM    | 11-Aug-08 | N | S    | 29-May-14 | 29-May-14 |                           | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern     | 413519 | F   | Per Ilion, replace trigger, check over, and test at no charge       |
| 10363 | 700            | not avail. | 7MM REM MA | 24-Aug-78 | N | S    | 29-May-14 | 6-Apr-15  | Fired on Bolt Closing     | Not Examined by Product Service                       | n/a                             | F      | Gun not returned to Ilion for exam  |   |
| 10367 | 700            | N/A        | 3006 SPRG  | 1-Dec-80  | N | S    | 30-May-14 | 30-May-14 | Fired on Bolt Closing     | Could Not Duplicate Concern                           | 414197                          | F      | Per Ilion, replace trigger, check over and test fire at no charge                             |   |
| 10368 | 700            | 25773      | 3006 SPRG  | 19-Feb-90 | N | S    | 30-May-14 | 30-May-14 | Fired on Safe Release     | Could Not Duplicate Concern                           | 413883                          | F      | Per Ilion, replace trigger, check over and test fire at no charge                             |   |
| 10371 | 700            | 85434      | 22-250 REM | 28-Dec-12 | N | PD/S | 2-Jun-14  | 22-Oct-15 | Fired on Bolt Closing     | Not Examined by Product Service                       | n/a                             | F      | Firearm not returned to Ilion for exam  |   |
| 10372 | VERSA MAX      | 81054      | 12 GA      | 28-Apr-11 | N | S    | 3-Jun-14  | 3-Jun-14  | Went Automatic            | Broken or Missing Parts                               | 415362                          | F      | Per Ilion, check over, repair as needed, and test at no charge                                |   |
| 10373 | VERSA TACTICAL | 81059      | 12 GA      | 11-Mar-14 | N | S    | 3-Jun-14  | 18-Jun-14 | Went Automatic            | Could Not Duplicate Concern                           | 415353                          | F      | Returning as received   |   |
| 10378 | 700            | 27097      | 7MM REM MA | 24-Jun-06 | N | PD/S | 3-Jun-14  | 24-Jun-14 |                           | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation          | 427312 | F   | Check over completely, repair as needed, and test fire at no charge |
| 10379 | 700            | 25791      | 270 WIN    | 25-Feb-13 | N | S    | 3-Jun-14  | 3-Jul-14  | Fired on Safe Release     | Could Not Duplicate Concern                           | 435004                          | F      | Per Ilion, replace trigger, check over and test fire at no charge                             |   |
| 10383 | 660            | N/A        | 308 WIN    | 1-May-68  | Y | S    | 6-Jun-14  | 6-Jun-14  | Fired on Bolt Closing     | Improper Maintenance                                  | 417162                          | F      | Per Ilion, replace trigger, check over and test fire at no charge                             |   |

RAC001189

## Confidential

|       |           |            |            |           |   |         |           |           |   |  |        |   |   |
|-------|-----------|------------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|---|
| 10384 | CARBON 15 | 90689      | 5.56       | 26-Feb-13 | N | S       | 6-Jun-14  | 6-Jun-14  | Went Automatic  | Other - Unspecified or Undetermined - Firearms | 417246 | F | Per llion, check over, repair as needed, and test at no charge      |
| 10387 | 700       | 25787      | 243 WIN    | 11-Dec-02 | N | S       | 9-Jun-14  | 9-Jun-14  | Fired on Safe Release                                 | Improper Maintenance                           | 418640 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10388 | XP100     | 25387      | 260 REM    | 23-Dec-97 | Y | S       | 9-Jun-14  | 9-Jun-14  | Fired on Safe Release                                 | Altered Adjustments or Components              | 418916 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10389 | 597       | 26550      | 22 LR      | 25-Apr-00 | N | PD/S    | 9-Jun-14  | 9-Jun-14  | Went Automatic  | Other - Unspecified or Undetermined - Firearms | 418531 | F | Per llion, check over, repair as needed, and test at no charge      |
| 10393 | 700       | 27092      | 243 WIN    | 30-Apr-10 | N | S       | 10-Jun-14 | 22-Oct-15 | Fired on Bolt Opening                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to llion for exam                              |
| 10398 | 700       | 27094      | 270 WIN    | 23-Apr-10 | N | S       | 11-Jun-14 | 25-Jun-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 429208 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10397 | 700       | N/A        | 3006 SPRG  | 19-Dec-77 | N | S       | 12-Jun-14 | 12-Jun-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 420100 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10399 | 700       | 25955      | 3006 SPR   | 10-Nov-04 | N | S       | 12-Jun-14 | 3-Jul-14  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 435099 | F | llion repaired at n/c   |
| 10402 | 700       | 84205      | 300 Blacko | 28-Aug-13 | N | S       | 12-Jun-14 | 12-Jun-14 | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Consumer refused to provide his name, address & phone #             |
| 10404 | 700       | not avail. | 243 WIN    | 16-Nov-80 | N | PI/PD/S | 12-Jun-14 | 25-Jul-14 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 430338 | F | Repair @ n/c  |
| 10405 | 770       | 85632      | 270 WIN    | 21-May-13 | N | PD/S    | 13-Jun-14 | 13-Jun-14 | Barrel Burst/Split (Other than Chamber)               | Fired While Obstructed                         | 420752 | F | Replacing with Ramac 85632 in exchange                              |
| 10406 | 700       | 26989      | 3006 SPRG  | 13-Jan-97 | N | S       | 13-Jun-14 | 13-Jun-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 420343 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10408 | 700       | 85374      | 3006 SPRG  | 11-Mar-08 | N | PI/S    | 13-Jun-14 | 25-Jul-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 431629 | F | Repair @ n/c  |
| 10414 | 1911 R1   | 96323      | 45 ACP     | 29-Mar-12 | N | S       | 17-Jun-14 | 17-Jun-14 | Went Automatic  | Could Not Duplicate Concern                    | 423272 | F | Per llion, check over, repair as needed, and test at no charge      |
| 10415 | 700       | N/A        | 7MM REM MA | 14-May-69 | N | PD/S    | 17-Jun-14 | 21-Jul-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 445070 | F | Check over completely, repair as needed, and test fire at no charge |
| 10416 | BACR      | 90838      | 5.56       | 18-Jul-13 | N | S       | 18-Jun-14 | 18-Jun-14 | Went Automatic  | Other - Unspecified or Undetermined - Firearms | 423679 | F | Per llion - Repair at n/c   |
| 10417 | 700       | not avail. | 300 RUM    |           | N | S       | 18-Jun-14 | 18-Jun-14 | Unexplained Discharge - No Mention of Safety Position | Not Examined by Product Service                | n/a    | F | Referred customer to Gravel Agency in Canada                        |
| 10418 | 700       | 25803      | 7MM REM    | 7-Oct-85  | N | S       | 18-Jun-14 | 1-Jul-14  | Fired on Bolt Closing                                 | Improper Maintenance                           | 432835 | F | llion repaired at n/c   |
| 10420 | 700       | N/A        | 6MM REM    | 1-Jan-68  | N | S       | 19-Jun-14 | 19-Jun-14 | Fired on Safe Release                                 | Improper Maintenance                           | 424902 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10423 | 700       | N/A        | 22-250 REM | 22-Dec-94 | N | PD/S    | 19-Jun-14 | 25-Jul-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 450070 | F | Replace trigger, check over, and test at no charge                  |

RAC001190

Confidential

|       |           |       |            |           |   |      |           |           |   |  |        |   |   |
|-------|-----------|-------|------------|-----------|---|------|-----------|-----------|---|--|--------|---|---|
| 10426 | 700       | 27017 | 3006 SPRG  | 17-Mar-05 | N | S    | 20-Jun-14 | 25-Jul-14 | Fired on Safe Release                                 | AFT MKT TRIGGER ASSM                           | 426726 | F | Per Ilion - Repair at n/c - goodwill                                |
| 10428 | 700       | 84216 | 22-250 REM | 22-Dec-11 | N | S    | 20-Jun-14 | 20-Jun-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 426545 | F | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10432 | 700       | 26440 | 300 WIN MA | 20-Jul-04 | N | S    | 23-Jun-14 | 23-Jun-14 | Other - Firearms                                      | Altered Adjustments or Components              | 427465 | O | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10433 | 597       | 26537 | 22 LR      | 5-Sep-08  | N | S    | 23-Jun-14 | 23-Jul-14 | Fired Out of Battery                                  | Other - Unspecified or Undetermined - Firearms | 427439 | F | Replace w/26537 in exchange   |
| 10435 | 700       | n/a   | 270 WIN    | 1-Oct-79  | N | S    | 23-Jun-14 | 23-Jun-14 | Fired With Safe ON                                    | Could Not Duplicate Concern                    | 427325 | F | Ilion repaired at n/c   |
| 10436 | 1911 R1   | 96323 | 45 ACP     | 14-Apr-14 | N | S    | 23-Jun-14 | 23-Jun-14 | Fired With Safe ON                                    | Other - Unspecified or Undetermined - Firearms | 427529 | F | Per Ilion, check over, repair as needed, and test at no charge      |
| 10452 | 7         | N/A   | 243 WIN    | 20-Mar-84 | N | S    | 24-Jun-14 | 15-Jul-14 | Fired on Bolt Closing                                 | Improper Maintenance                           | 443830 | F | Check over completely, repair as needed, and test fire at no charge |
| 10440 | 700       | 84165 | 300 RUM    | 14-Feb-14 | N | S    | 25-Jun-14 | 25-Jun-14 | Fired on Safe Release                                 | Not Examined by Product Service                | 406105 | F | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10441 | 887       | 82500 | 12 GA      | 12-Nov-13 | N | S    | 25-Jun-14 | 25-Jun-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 429143 | F | Per Ilion, check over, repair as needed, and test at no charge      |
| 10443 | 722       | N/A   | 308 WIN    | 1-Jun-55  | Y | S    | 25-Jun-14 | 25-Jun-14 | Fired on Bolt Opening                                 | Altered Adjustments or Components              | 429223 | F | Per Ilion, quote to repair BLM                                      |
| 10453 | 700       | N/A   | 25-06 REM  | 10-Apr-75 | N | S    | 25-Jun-14 | 14-Jul-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 439913 | F | Check over completely, repair as needed, and test fire at no charge |
| 9711  | 700       | 26031 | 25-06 REM  | 27-Jan-98 | N | S    | 26-Jun-14 | 26-Jun-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 430283 | F | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10445 | 700       | N/A   | 3006 SPRG  | 16-Sep-70 | N | S    | 26-Jun-14 | 26-Jun-14 | Fired on Bolt Closing                                 | Improper Maintenance                           | 429231 | F | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10446 | 700       | N/A   | 270 WIN    | 17-Nov-71 | N | S    | 26-Jun-14 | 26-Jun-14 | Fired on Bolt Closing                                 | Improper Maintenance                           | 429265 | F | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10447 | 700       | N/A   | 7MM REM MA | 22-Nov-82 | N | S    | 26-Jun-14 | 26-Jun-14 | Fired on Bolt Closing                                 | Improper Maintenance                           | 430010 | F | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10448 | 600       | N/A   | 35 REM     | 1-Jul-65  | Y | S    | 26-Jun-14 | 26-Jun-14 | Fired on Bolt Closing                                 | Improper Maintenance                           | 430036 | F | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10449 | 700       | 27009 | 2506 REM   | 5-Oct-10  | N | S    | 26-Jun-14 | 26-Jun-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 430533 | F | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10450 | BR 308    | 90702 | 308 WIN    | 18-Dec-13 | N | S    | 26-Jun-14 | 26-Jun-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 430093 | F | Per Ilion, check over, repair as needed, and test at no charge      |
| 10455 | 700       | 26096 | 300 RUM    | 11-Apr-01 | N | S    | 30-Jun-14 | 23-Jul-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 449921 | F | Per Ilion, replace trigger, check over and test fire at no charge   |
| 10456 | 700       | 85374 | 3006 SPRG  | 22-Dec-09 | N | PI/S | 30-Jun-14 | 28-Dec-15 | Fired With Safe ON                                    | Could Not Duplicate Concern                    | 507534 | F | Per Ilion - Replace TA & test @ n/c                                 |
| 10457 | CARBON 15 | 90689 | 5.56       | 21-Feb-11 | N | S    | 1-Jul-14  | 1-Jul-14  | Went Automatic  | Could Not Duplicate Concern                    | 433275 | F | Per Ilion - Repair at n/c   |
| 10458 | XM10      | 90702 | 308 WIN    | 27-Mar-13 | N | S    | 1-Jul-14  | 1-Jul-14  | Went Automatic  | Sent in for Evaluation                         | 431617 | F | Per Ilion - Repair at n/c - warranty                                |

RAC001191

## Confidential

|       |           |            |            |           |   |         |           |           |  |  |                                 |            |   |  |
|-------|-----------|------------|------------|-----------|---|---------|-----------|-----------|--|--|---------------------------------|------------|---|--|
| 10459 | 597       | RECEIVER   | 17 HMR     | 9-Jan-04  | N | PD/S    | 1-Jul-14  | 6-Aug-14  | My Gun Blew Up   | Other - Unspecified or Undetermined - Firearms | 431373                          | F          | Converting to 22 WMR as requested by customer, repair and check over completely at no charge. |  |
| 10465 | CARBON 15 | 90863      | 5.56       | 13-Sep-11 | N | S       | 2-Jul-14  | 2-Jul-14  | Went Automatic   | Sent in for Evaluation                         | 433566                          | F          | Per Ilion - Repair at n/c   |  |
| 10467 | 700       | 26129      | 3006 SPRG  | 13-Jul-00 | N | S       | 2-Jul-14  | 1-Aug-14  | Fired on Safe Release                                      | Could Not Duplicate Concern                    | 453245                          | F          | Ilion repaired at n/c   |  |
| 10468 | 700       | n/a        | 270 WIN    | 18-Mar-70 | N | PD/S    | 3-Jul-14  | 11-Dec-14 | Remington Firearm Damaged while using Remington Ammunition | Improper Maintenance                           | 479117                          | A          | Per Ilion - Repair at n/c   |  |
| 10469 | 770       | 85663      | 3006 SPRG  | 1-Sep-10  | N | S       | 7-Jul-14  | 26-Aug-14 | Unexplained Discharge - No Mention of Safety Position      | Could Not Duplicate Concern                    | 461146                          | F          | Per Ilion, replace trigger, check over and test fire at no charge                             |  |
| 10470 | 700       | N/A        | 3006 SPR   | 16-Jul-76 | N | S       | 7-Jul-14  | 25-Jul-14 | Fired on Safe Release                                      | Could Not Duplicate Concern                    | 450869                          | F          | Per Ilion, replace trigger, check over and test fire at no charge                             |  |
| 10472 | 700       | 25787      | 243 WIN    | 17-May-12 | N | PD/S    | 8-Jul-14  | 26-Mar-15 | Fired on Bolt Closing                                      | Could Not Duplicate Concern                    | 453869                          | F          | Check over completely, repair as needed, and test fire at no charge                           |  |
| 10473 | 552       | not avail. | 22 LR      |           |   | N       | PI/S      | 8-Jul-14  | 7-Aug-15   | Ammunition Exploded                            | Not Examined by Product Service | not avail. | A   | Per Release - Replace gun w/Item# 84218, replace scope & send ammo |
| 10475 | 700       | 85569      | 308 WIN    | 7-Feb-13  | N | PI/PD/S | 10-Jul-14 | 14-Nov-14 | Fired on Bolt Closing                                      | Could Not Duplicate Concern                    | 448967                          | F          |   |  |
| 10477 | 700       | not avail. | 243 WIN    | 13-Feb-70 | N | S       | 11-Jul-14 | 1-Aug-14  | Fired on Bolt Closing                                      | Could Not Duplicate Concern                    | 453355                          | F          | Ilion repaired at n/c   |  |
| 10479 | 700       | N/A        | 35 WHELEN  | 28-Jul-88 | N | S       | 14-Jul-14 | 14-Jul-14 | Fired on Bolt Closing                                      | Altered Adjustments or Components              | 442047                          | F          | Per Ilion, replace trigger, check over and test fire at no charge                             |  |
| 10480 | 700       | N/A        | 270 WIN    | 20-Nov-78 | N | S       | 14-Jul-14 | 14-Jul-14 | Unexplained Discharge - No Mention of Safety Position      | Improper Maintenance                           | 439995                          | F          | Per Ilion, replace trigger, check over and test fire at no charge                             |  |
| 10481 | 710       | 27410      | 3006 SPRG  | 22-May-02 | Y | S       | 14-Jul-14 | 14-Jul-14 | Fired on Bolt Closing                                      | Could Not Duplicate Concern                    | 437401                          | F          | Per Ilion, check over, repair as needed, and test at no charge                                |  |
| 10482 | 700       | n/a        | 3006 SPRG  | 10-Mar-77 | N | S       | 14-Jul-14 | 13-Aug-14 | Fired on Bolt Closing                                      | Improper Maintenance                           | 456454                          | F          | Ilion repaired at n/c   |  |
| 10487 | 700       | not avail. | 3006 SPRG  | 1-Aug-75  | N | PD/S    | 15-Jul-14 | 22-Sep-14 | Fired on Bolt Closing                                      | Improper Maintenance                           | 459616                          | F          | Repair @ n/c - goodwill gesture   |  |
| 10488 | 700       | 85430      | 2506 REM   | 1-Feb-13  | N | S       | 16-Jul-14 | 16-Jul-14 | Unexplained Discharge - No Mention of Safety Position      | Returned due to Recall                         | 415980                          | F          | Cleaned and reset trigger under recall  |  |
| 10489 | 1187      | 83700      | 12 GA      | 5-Sep-13  | N | S       | 16-Jul-14 | 16-Jul-14 | Went Automatic   | Could Not Duplicate Concern                    | 446964                          | F          | Per Release Replacing with Ramac 83700 in exchange  |  |
| 10493 | 700       | n/a        | 7MM REM MA | 26-Sep-73 | N | S       | 17-Jul-14 | 17-Jul-14 | Fired on Safe Release                                      | Could Not Duplicate Concern                    | 447090                          | F          | Per Ilion - Repair at n/c   |  |
| 10495 | 700       | N/A        | 7MM REM EX | 12-Sep-79 | N | PI/S    | 18-Jul-14 | 11-Sep-14 | Fired on Safe Release                                      | Could Not Duplicate Concern                    | 462652                          | F          | Check over completely, repair as needed, and test fire at no charge                           |  |
| 10501 | 700       | N/A        | 270 WIN    | 21-Feb-75 | N | PD/S    | 18-Jul-14 | 14-Aug-14 | Unexplained Discharge - No Mention of Safety Position      | Could Not Duplicate Concern                    | 453367                          | F          | Check over completely, repair as needed, and test fire at no charge                           |  |

RAC001192

## Confidential

|       |     |       |            |           |   |         |           |           |   |  |        |   |   |
|-------|-----|-------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|---|
| 10502 | 700 | 25791 | 270 WIN    | 12-Dec-95 | N | S       | 18-Jul-14 | 1-Aug-14  | Other - Does not trust firearm                        | Could Not Duplicate Concern                    | 453357 | O | Per llion, replace trigger, check over and test fire at no charge   |
| 10504 | 700 | N/A   | 22-250 REM | 22-May-73 | N | PD/S    | 18-Jul-14 | 28-Aug-14 | Fired on Safe Release                                 | Improper Maintenance                           | 461056 | F | Check over completely, repair as needed, and test fire at no charge |
| 10496 | 700 | N/A   | 3006 SPRG  | 12-Aug-75 | N | S       | 21-Jul-14 | 21-Jul-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 448317 | F | Per llion, replace trigger, check over, and test at no charge.      |
| 10497 | 700 | 85566 | 308 WIN    | 8-Apr-09  | N | S       | 21-Jul-14 | 21-Jul-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 447522 | F | llion repaired at n/c   |
| 10513 | 700 | N/A   | 243 WIN    | 19-Apr-72 | N | S       | 21-Jul-14 | 31-Jul-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 453033 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10507 | 700 | n/a   | 17 REM     | 5-Oct-71  | N | S       | 22-Jul-14 | 22-Jul-14 | Fired on Bolt Closing                                 | Broken or Missing Parts                        | 448236 | F | Per llion - Replace TA @ n/c, Quote to replace stock                |
| 10509 | 700 | N/A   | 3006 SPRG  | 24-Oct-73 | N | S       | 22-Jul-14 | 22-Jul-14 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 448242 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10510 | 660 | N/A   | 350 REM MA | 25-Mar-75 | Y | S       | 22-Jul-14 | 22-Jul-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 449302 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10511 | 700 | N/A   | 3006 SPRG  | 25-Apr-75 | N | S       | 22-Jul-14 | 22-Jul-14 | Fired on Safe Release                                 | Improper Maintenance                           | 449258 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10515 | 700 | 29709 | 270 WIN    | 1-Mar-99  | N | S       | 23-Jul-14 | 23-Jul-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 449757 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10516 | 700 | N/A   | 3006 SPRG  | 1-Sep-74  | N | S       | 23-Jul-14 | 23-Jul-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 449735 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10519 | 700 | n/a   | 270 WIN    | 8-Jun-71  | N | S       | 23-Jul-14 | 11-Aug-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 454964 | F | Per llion repaired at n/c   |
| 10521 | 700 | N/A   | 270 WIN    | 1-Apr-74  | N | S       | 23-Jul-14 | 15-Aug-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 457826 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10526 | 700 | N/A   | 3006 SPR   | 7-Jul-77  | N | S       | 23-Jul-14 | 11-Aug-14 | Fired on Safe Release                                 | Improper Maintenance                           | 453922 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10520 | 700 | 20000 | 22-250 REM |           | N | PD/S    | 23-Jul-14 | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to llion for exam                              |
| 10523 | 700 | 25793 | 3006 SPRG  | 24-Aug-12 | N | S       | 24-Jul-14 | 24-Jul-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 428823 | F | Per Release - refund \$804.99                                       |
| 10524 | 7   | 24741 | 7MM/08 REM | 9-Oct-96  | N | S       | 24-Jul-14 | 24-Jul-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 450308 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10530 | 700 | 25634 | 3006 SPRG  | 9-Apr-86  | N | S       | 25-Jul-14 | 25-Jul-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 451479 | F | Per llion, replace trigger, check over and test fire at no charge   |
| 10531 | 700 | 25634 | 3006 SPRG  | 1-Apr-86  | N | S       | 25-Jul-14 | 25-Jul-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 451476 | F | llion repaired at n/c   |
| 10537 | 597 | 26536 | 17 HMR     | 27-Jun-03 | N | PI/PD/S | 28-Jul-14 | 15-Aug-14 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 457576 | O | Replacing with Ramac 70703 in exchange                              |
| 10532 | 700 | 27097 | 7MM MAG    | 3-Oct-11  | N | PD/S    | 28-Jul-14 | 16-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 487889 | F | Repair @ n/c under XMP recall                                       |

RAC001193

## Confidential

|       |              |            |                    |                   |   |      |           |           |   |  |        |   |  |
|-------|--------------|------------|--------------------|-------------------|---|------|-----------|-----------|---|--|--------|---|--|
| 10539 | 700          | 84207      | 308 WIN            | 12-Jan-12         | N | S    | 29-Jul-14 | 29-Jul-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 417972 | F | Ilion repaired at n/c  |
| 10540 | Sportsman 78 | 26162      | 270 WIN            | 27-May-86         | Y | S    | 29-Jul-14 | 29-Jul-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 451914 | F | Ilion repaired at n/c  |
| 10542 | 722          | n/a        | 222 REM            | 1-Dec-51          | Y | S    | 29-Jul-14 | 29-Jul-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 451831 | F | Per Ilion - Quote to repair under BLM  |
| 10543 | 700          | n/a        | 3006 SPRG          | 24-Jun-76         | N | S    | 29-Jul-14 | 29-Jul-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 451830 | F | Ilion repaired at n/c  |
| 10544 | 700          | 27093      | 243 WIN            | 13-Jun-11         | N | S    | 29-Jul-14 | 29-Jul-14 | Light Trigger Pull                                    | Could Not Duplicate Concern                    | 427531 | F | Per Ilion, replace trigger, check over and test fire at no charge                                |
| 10546 | 700          | 26917      | 308 WIN            | 24-Feb-95         | N | S    | 30-Jul-14 | 30-Jul-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 452382 | F | Ilion repaired at n/c  |
| 10548 | 870          | 81150      | 20 GA              | 14-Feb-14         | N | S    | 30-Jul-14 | 30-Jul-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 452217 | F | Per Ilion - Repair at n/c - warranty   |
| 10554 | 700          | 25971      | 300 RUM            | 16-Mar-01         | N | S    | 31-Jul-14 | 31-Jul-14 | Fired With Safe ON                                    | Could Not Duplicate Concern                    | 452951 | F | Per Ilion, replace trigger, check over and test fire at no charge                                |
| 10557 | 700          | N/A        | 3006 SPRG          | 16-Mar-82         | N | S    | 1-Aug-14  | 1-Aug-14  | Delayed Firing - Firearms                             | Improper Maintenance                           | 451942 | F | Per Ilion, replace trigger, check over and test fire at no charge, replace stock at 30% discount |
| 10558 | 700          | 25791      | 270 WIN            | 20-Jun-86         | N | S    | 1-Aug-14  | 1-Aug-14  | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 453158 | F | Per Ilion, replace trigger, check over and test fire at no charge                                |
| 10560 | 721          | not avail. | 270 WIN            | 1-Oct-48          | Y | PD/S | 1-Aug-14  | 19-Aug-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 459344 | F | Per Ilion - Repair at n/c  |
| 10566 | 700          | n/a        | 3006 SPRG          | 3-Apr-69          | N | S    | 6-Aug-14  | 21-Aug-14 | Fired on Bolt Closing                                 | Improper Maintenance                           | 459985 | F | Ilion repaired at n/c  |
| 10569 | 700          | 27333      | 300 WSM            | 13-May-13         | N | S    | 7-Aug-14  | 3-Sep-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 462752 | F | Replaced rifle w/84017 & placed order for 1 case of ammo 29489                                   |
| 10573 | 700          | 84016      | 7MM REM MA         | 23-Mar-07         | N | S    | 11-Aug-14 | 11-Aug-14 | Unexplained Discharge - No Mention of Safety Position | Not Examined by Product Service                | 409260 | F | Per Ilion, XMP update  |
| 10574 | 700          | 27095      | 3006 SPRG          | 2-Jan-13          | N | S    | 11-Aug-14 | 11-Aug-14 | Unexplained Discharge - No Mention of Safety Position | Not Examined by Product Service                | 428132 | F | Per Ilion, repair and test   |
| 10575 | 700          | n/a        | 270 WIN 22/250 REM | 1-Mar-74 8-May-70 | N | S    | 11-Aug-14 | 11-Aug-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 451780 | F | Ilion repaired at n/c  |
| 10576 | 788          | n/a        |                    |                   |   |      | 11-Aug-14 | 11-Aug-14 | Fired With Safe ON                                    | Sent in for Evaluation                         | 455288 | F | Per Ilion - Quote to repair @ discount   |
| 10577 | 700          | N/A        | 3006 SPRG          | 1-Feb-63          | N | S    | 11-Aug-14 | 11-Aug-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 454109 | F | Per Ilion, replace trigger, check over and test fire at no charge                                |
| 10578 | 700          | N/A        | 7MM REM MA         | 1-Aug-67          | N | S    | 11-Aug-14 | 11-Aug-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 453539 | F | Per Ilion, replace trigger, check over and test fire at no charge                                |
| 10579 | 700          | 26963      | 7MM08 REM          | 18-Mar-96         | N | S    | 11-Aug-14 | 11-Aug-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 455233 | F | Per Ilion, replace trigger, check over and test fire at no charge                                |
| 10583 | 597          | 26516      | 17 HMR             | 20-Mar-03         | N | PD/S | 11-Aug-14 | 11-Aug-14 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 454834 | F | Converting to 22 WMR as requested by customer, repair and check over completely at no charge.    |
| 10584 | 700          | 26035      | 3006 SPRG          | 12-Mar-99         | N | S    | 12-Aug-14 | 12-Aug-14 | Fired on Safe Release                                 | Improper Maintenance                           | 454115 | F | Per Ilion, replace trigger, check over and test fire at no charge                                |

RAC001194

Confidential

|       |        |       |            |           |   |      |           |           |                           |   |                                 |     |   |
|-------|--------|-------|------------|-----------|---|------|-----------|-----------|---------------------------|---|---------------------------------|-----|---|
| 10585 | XP 100 | N/A   | 221 FB     | 20-Mar-79 | Y | S    | 12-Aug-14 | 12-Aug-14 | Fired on Bolt Closing     | Improper Maintenance                                  | 454038                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10586 | 700    | N/A   | 308 WIN    | 16-Feb-76 | N | S    | 12-Aug-14 | 12-Aug-14 | Fired on Bolt Closing     | Altered Adjustments or Components                     | 455029                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10587 | BR 308 | 90828 | 308 WIN    | 23-Dec-13 | N | S    | 12-Aug-14 | 12-Aug-14 | Went Automatic            | Could Not Duplicate Concern                           | 453497                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10588 | 700    | N/A   | 3006 SPRG  | 25-Mar-75 | N | S    | 13-Aug-14 | 13-Aug-14 | Fired on Safe Release     | Could Not Duplicate Concern                           | 455794                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10589 | 700    | 84179 | 7MM REM MA | 15-Oct-12 | N | S    | 13-Aug-14 | 13-Aug-14 | Fired on Safe Release     | Could Not Duplicate Concern                           | 457088                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10592 | 700    | 27476 | 270 WIN    | 31-May-00 | N | S    | 14-Aug-14 | 14-Aug-14 | Fired on Safe Release     | Could Not Duplicate Concern                           | 456231                          | F   | llion repaired at n/c   |
| 10593 | 700    | 25871 | 17 REM     | 29-Sep-99 | N | S    | 14-Aug-14 | 14-Aug-14 | Fired on Bolt Closing     | Improper Maintenance                                  | 457537                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10594 | 700    | 25773 | 3006 SPRG  | 13-Feb-01 | N | S    | 14-Aug-14 | 14-Aug-14 | Fired on Safe Release     | Improper Maintenance                                  | 457536                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10595 | 700    | 25777 | 7MM REM MA | 10-Mar-86 | N | S    | 14-Aug-14 | 14-Aug-14 | Fired on Safe Release     | Broken or Missing Parts                               | 457538                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10602 | 700    | 84207 | 308 WIN    | 18-Sep-13 | N | S    | 15-Aug-14 | 15-Aug-14 | Fired on Bolt Closing     | Could Not Duplicate Concern                           | 458082                          | F   | llion repaired at n/c   |
| 10603 | 700    | n/a   | 3006 SPRG  | 2-May-75  | N | S    | 15-Aug-14 | 15-Aug-14 | Fired on Bolt Closing     | Altered Adjustments or Components                     | 457486                          | F   | llion repaired at n/c   |
| 10604 | 710    | 27410 | 3006 SPRG  | 31-Mar-01 | Y | S    | 15-Aug-14 | 15-Aug-14 | Fired on Bolt Closing     | Improper Maintenance                                  | 457998                          | F   | Per llion - Quote to repair @ discount                            |
| 10606 | 700    | N/A   | 25-06 REM  |           | N | S    | 15-Aug-14 | 6-Apr-15  | Fired on Safe Release     | Not Examined by Product Service                       | n/a                             | F   | Gun not returned to llion for exam                                |
| 10608 | 700    | N/A   | 3006 SPR   | 1-Jul-68  | N | S    | 18-Aug-14 | 29-Aug-14 | Fired on Bolt Closing     | Improper Maintenance                                  | 461790                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10611 | 783    | 85836 | 3006 SPRG  | 18-Jun-13 | N | S    | 19-Aug-14 | 19-Aug-14 | Fired With Safe ON        | Broken or Missing Parts                               | 459320                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10612 | 750    | 85684 | 308 WIN    | 12-Feb-08 | N | S    | 19-Aug-14 | 19-Aug-14 |                           | Sent in for Evaluation                                | 459310                          | F   | Per llion, check over, repair as needed, and test at no charge    |
| 10613 | 700    | 85373 | 270 WIN    | 22-Sep-11 | N | PI/S | 19-Aug-14 | 22-Oct-15 |                           | Unexplained Discharge - No Mention of Safety Position | Not Examined by Product Service | n/a | Firearm not returned to llion for exam                            |
| 10619 | 700    | 29701 | 22-250 REM | 20-Feb-01 | N | S    | 21-Aug-14 | 21-Aug-14 | Fired With Safe ON        | Altered Adjustments or Components                     | 459943                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10621 | 700    | 26107 | 300 RUM    | 29-Jan-01 | N | S    | 21-Aug-14 | 21-Aug-14 | Fired on Safe Release     | Could Not Duplicate Concern                           | 459216                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10623 | 870    | 82001 | 20 GA      | 4-Sep-07  | N | S    | 21-Aug-14 | 21-Aug-14 | Delayed Firing - Firearms | Sent in for Evaluation                                | 459696                          | F   | Per llion, replace trigger, check over and test fire at no charge |
| 10627 | 700    | 27094 | 270 WIN    | 12-Mar-14 | N | S    | 21-Aug-14 | 9-Oct-14  | Fired on Safe Release     | Could Not Duplicate Concern                           | 464152                          | F   | TA replaced @ n/c   |

RAC001195

## Confidential

|       |                  |       |            |           |   |         |           |           |   |  |         |   |   |
|-------|------------------|-------|------------|-----------|---|---------|-----------|-----------|---|--|---------|---|---|
| 10628 | 700 trigger only | N/A   |            |           | N | S       | 22-Aug-14 | 26-Sep-14 | Unexplained Discharge - No Mention of Safety Position | No Fault Found                                 | 451536  | F | Customer request do not return trigger.                                   |
| 10629 | 700              | 85491 | 3006 SPRG  | 23-Jul-10 | N | S       | 22-Aug-14 | 22-Aug-14 | Fired With Safe ON                                    | Could Not Duplicate Concern                    | 460471  | F | Per Ilion, replace trigger, check over and test fire at no charge         |
| 10631 | 721              | N/A   | 3006 SPRG  | 1-May-53  | Y | S       | 22-Aug-14 | 22-Aug-14 | Fired With Safe ON                                    | Improper Maintenance                           | 460077  | F | Per Ilion, quote to repair BLM  |
| 10632 | 700              | 84203 | 308 WIN    | 11-Jul-11 | N | S       | 22-Aug-14 | 22-Aug-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 460735  | F | Per Ilion, replace trigger, check over and test fire at no charge         |
| 10634 | 700              | 84373 | 22-250 REM | 18-Feb-08 | N | S       | 25-Aug-14 | 25-Aug-14 | Unexplained Discharge Safe ON                         | Could Not Duplicate Concern                    | 460807  | F | Per Ilion, replace trigger, check over and test fire at no charge         |
| 10635 | ACR              | 90838 | 223/5.56   | 27-Sep-13 | N | S       | 25-Aug-14 | 25-Aug-14 | Went Automatic  | Could Not Duplicate Concern                    | 460758  | F | Per Ilion, check over, repair as needed, and test at no charge            |
| 10636 | SEVEN            | 85952 | 223 REM    | 25-Apr-08 | N | PD/S    | 25-Aug-14 | 17-Nov-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 466342  | F | Repair of rifle and check for \$1,500.00 compensation for property damage |
| 9595  | 7400             | N/A   | 3006 SPR   | 1-Apr-81  | Y | PD/S    | 26-Aug-14 | 3-Sep-14  | Ammunition Exploded                                   | Sent in for Evaluation                         | 462103  | A | Check over completely, repair as needed, and test fire at no charge       |
| 10638 | 710              | 27410 | 3006 SPRG  | 19-Jun-05 | Y | S       | 26-Aug-14 | 23-Sep-14 | Fired on Bolt Closing                                 | Broken or Missing Parts                        | 467027  | F | Per Ilion - Repair at n/c   |
| 10639 | 700              | 26281 | 270 WIN    | 14-Apr-08 | N | PD/S    | 27-Aug-14 | 26-Sep-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 467599  | F | Check over completely, repair as needed, and test fire at no charge       |
| 10642 | 597              | 26516 | 17 HMR     | 31-Jan-05 | N | PI/PO/S | 27-Aug-14 | 17-Dec-14 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | n/a     | F | Replace with Ramac 26581 in exchange                                      |
| 10640 | 700              | 85205 | 308 WIN    | 28-Oct-13 | N | S       | 28-Aug-14 | 28-Aug-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 461697  | F | Ilion repaired at n/c   |
| 10647 | 600              | N/A   | 243 WIN    | 4-Jun-75  | Y | S       | 29-Aug-14 | 29-Aug-14 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 461733  | F | Per Ilion, replace trigger, check over and test fire at no charge         |
| 10649 | 700              | N/A   | 3006 SPRG  | 1-Jun-74  | N | S       | 3-Sep-14  | 3-Sep-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 462403  | F | Per Ilion, replace trigger, check over and test fire at no charge         |
| 10650 | 700              | 84373 | 22-250REM  | 22-Dec-09 | N | S       | 3-Sep-14  | 3-Sep-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 462799  | F | Per Ilion, replace trigger, check over and test fire at no charge         |
| 10651 | 700              | N/A   | 7MM REM MA | 28-May-75 | N | S       | 3-Sep-14  | 3-Sep-14  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 462656  | F | Per Ilion, replace trigger, check over and test fire at no charge         |
| 10654 | 700              | 84218 | 308 WIN    | 22-Nov-13 | N | S       | 3-Sep-14  | 6-Oct-14  | Fired on Bolt Closing                                 | Sent in for Evaluation                         | 464568  | F | Ilion repaired at n/c   |
| 10659 | 700              | N/A   | 7MM REM MA | 12-Jun-75 | N | S       | 5-Sep-14  | 5-Sep-14  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 463260  | F | Per Ilion, replace trigger, check over and test fire at no charge         |
| 10660 | 700              | N/A   | 243 WIN    | 18-Oct-77 | N | S       | 5-Sep-14  | 5-Sep-14  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 4633270 | F | Per Ilion, replace trigger, check over and test fire at no charge         |
| 10661 | 600              | N/A   | 243 WIN    | 22-Sep-76 | N | S       | 5-Sep-14  | 5-Sep-14  | Fired on Safe Release                                 | Broken or Missing Parts                        | 463446  | F | Per Ilion, replace trigger, check over and test fire at no charge         |

RAC001196

## Confidential

|       |              |            |            |           |   |      |           |           |   |  |        |   |   |
|-------|--------------|------------|------------|-----------|---|------|-----------|-----------|---|--|--------|---|---|
| 10662 | 700          | 27478      | 3006 SPRG  | 6-Jun-97  | N | S    | 5-Sep-14  | 5-Sep-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 463383 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10663 | 700          | N/A        | 2506 REM   | 6-Apr-76  | N | S    | 5-Sep-14  | 5-Sep-14  | Fired on Safe Release                                 | Altered Adjustments or Components              | 463319 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10672 | 700          | N/A        | 7MM REM MA | 8-Nov-75  | N | S    | 5-Sep-14  | 30-Sep-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 468590 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10667 | 700          | not avail. | 3006 SPRG  |           | N | S    | 5-Sep-14  | 6-Apr-15  | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Gun not returned to Ilion for exam                                |
| 10670 | 700          | 27167      | 30-06 SPRG | 9-Aug-05  | N | S    | 8-Sep-14  | 8-Sep-14  | Fail to Fire  | Could Not Duplicate Concern                    | 463695 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10675 | 700          | N/A        | 3006SPR    | 13-Jul-77 | N | S    | 9-Sep-14  | 9-Sep-14  | Delayed Firing - Firearms                             | Improper Maintenance                           | 463623 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10676 | 700          | N/A        | 3006SPRG   | 17-Mar-75 | N | S    | 9-Sep-14  | 9-Sep-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 463844 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10677 | VersaMax     | 81049      | 12GA       | 7-May-13  | N | S    | 9-Sep-14  | 9-Sep-14  | Unexplained Discharge Safe ON                         | Could Not Duplicate Concern                    | 464060 | F | Replacing with Ramac 81049 in exchange                            |
| 10679 | 700          | N/A        | 243 WIN    | 17-Oct-80 | N | S    | 9-Sep-14  | 3-Oct-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 469555 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10680 | 700          | N/A        | 243 WIN    | 1-Feb-79  | N | S    | 9-Sep-14  | 6-Oct-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 469560 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10684 | 700          | 26425      | 3006 SPRG  | 7-Sep-06  | N | PD/S | 10-Sep-14 | 1-Oct-14  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 467572 | F | Replace TA & test   |
| 10687 | SPORTSMAN 78 | 26162      | 270 WIN    | 3-Jul-84  | N | S    | 11-Sep-14 | 11-Sep-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 464436 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10688 | 700          | 85478      | 270WIN     | 18-Aug-11 | N | S    | 11-Sep-14 | 11-Sep-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 464429 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10691 | 700          | 29696      | 338WINMA G | 19-Jul-04 | N | S    | 12-Sep-14 | 12-Sep-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 464979 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10692 | 700          | 85414      | 3006 SPRG  | 13-May-09 | N | S    | 12-Sep-14 | 12-Sep-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 465357 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10693 | 700          | N/A        | 3006SPRG   | 1-Oct-65  | N | S    | 12-Sep-14 | 11-Sep-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 465356 | F | Per Ilion, replace trigger, check over and test fire at no charge |
| 10695 | 887          | 82500      | 12 GA      | 23-Jun-14 | N | S    | 15-Sep-14 | 15-Sep-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 465571 | F | Per Ilion - Repair at n/c   |
| 10700 | 700          | not avail. | 3006 SPR   | 28-Oct-81 | N | S    | 15-Sep-14 | 6-Apr-15  | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Gun not returned to Ilion for exam                                |
| 10702 | 700          | 27007      | 243 WIN    | 12-Apr-06 | N | S    | 16-Sep-14 | 16-Sep-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 465538 | F | Ilion repaired at n/c   |
| 10704 | 660          | n/a        | 243WIN     | 24-Aug-73 | Y | S    | 16-Sep-14 | 16-Sep-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 465931 | F | Per Ilion - Repair at n/c   |
| 10706 | CARBON 15    | 91037      | 5.56 NATO  | 25-Feb-14 | N | S    | 16-Sep-14 | 16-Sep-14 | Went Automatic  | Other - Unspecified or Undetermined - Firearms | 465734 | F | Ilion repaired at n/c   |

RAC001197

## Confidential

|       |                 |       |            |           |   |      |           |           |   |  |               |   |   |
|-------|-----------------|-------|------------|-----------|---|------|-----------|-----------|---|--|---------------|---|---|
| 10707 | BACR            | 90704 | 5.56 NATO  | 28-Jul-10 | N | S    | 16-Sep-14 | 16-Sep-14 | Went Automatic  | Other - Unspecified or Undetermined - Firearms | 465878        | F | Per ilion, check over, repair as needed, and test at no charge    |
| 10711 | 700             | N/A   | 3006 SPRG  | 7-Oct-82  | N | S    | 17-Sep-14 | 17-Sep-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 466074        | F | Per ilion, replace trigger, check over and test fire at no charge |
| 10712 | 770             | 85630 | 243 WIN    | 3-Mar-09  | N | S    | 17-Sep-14 | 17-Sep-14 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 466071        | O | Per ilion, replace trigger, check over and test fire at no charge |
| 10716 | 870             | 81111 | 12GA       | 10-Mar-10 | N | PD/S | 19-Sep-14 | 30-Oct-14 | Fired Out of Battery                                  | Sent in for Evaluation                         | 466318        | F | Check over completely, repair as needed, and test at no charge    |
| 10717 | 700             | n/a   | 243 WIN    | 3-Jun-76  | N | S    | 19-Sep-14 | 19-Sep-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 466418        | F | Ilion repaired at n/c under BLM                                   |
| 10718 | 600             | N/A   | 308WIN     | 20-Mar-72 | N | S    | 19-Sep-14 | 19-Sep-14 | Unexplained Discharge - No Mention of Safety Position | Improper Maintenance                           | 466333        | F | Per ilion, replace trigger, check over and test fire at no charge |
| 10719 | 700             | 85373 | 270 WIN    | 23-Jan-08 | N | S    | 19-Sep-14 | 19-Sep-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 466384        | F | Per ilion - Repair at n/c under recall                            |
| 10724 | 700             | n/a   | 270 WIN    | 27-Apr-76 | N | S    | 19-Sep-14 | 3-Oct-14  | Fired on Bolt Opening                                 | Altered Adjustments or Components              | 469553        | F | Per ilion - Repair at n/c   |
| 10726 | 700             | 29694 | 300 WIN    | 8-Mar-94  | N | PI/S | 22-Sep-14 | 13-Oct-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 470562        | F | Ilion repaired at n/c   |
| 10728 | 700             | 84362 | 223 REM    | 4-Feb-10  | N | S    | 23-Sep-14 | 23-Sep-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 467130        | F | Per ilion - Repair at n/c   |
| 10729 | 700             | n/a   | 270 WIN    | 1-Oct-76  | N | S    | 23-Sep-14 | 23-Sep-14 | Fired With Safe ON                                    | Could Not Duplicate Concern                    | 467143        | F | Ilion repaired at n/c under BLM                                   |
| 10731 | BACR            | n/a   | 5.56       |           | N | S    | 23-Sep-14 | 23-Sep-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 467419        | F | Ilion repaired at n/c   |
| 10732 | 700             | n/a   | 3006 SPRG  |           | N | S    | 23-Sep-14 | 23-Sep-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 467413        | F | Per ilion - Repair at n/c   |
| 10733 | Spartan SPR 310 | 89716 | 20GA       | 20-May-08 | Y | S    | 23-Sep-14 | 23-Sep-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 467221        | F | Returned as Received - Ilion cannot repair                        |
| 10734 | 870             | 25103 | 12 GA      | 1-Oct-13  | N | S    | 23-Sep-14 | 16-Jan-15 | Failed to Extract                                     | Could Not Duplicate Concern                    | 472904/484864 | F | Replace with Ramac 25103 in exchange                              |
| 10735 | XM15-E2S        | n/a   | 5.56       | 14-Jan-09 | N | S    | 24-Sep-14 | 24-Sep-14 | Went Automatic  | Could Not Duplicate Concern                    | 467437        | F | Ilion repaired at n/c   |
| 10736 | 700             | 27502 | 7MM STW    | 22-May-98 | N | S    | 24-Sep-14 | 24-Sep-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 467591        | F | Ilion repaired at n/c   |
| 10739 | 7               | 24774 | 243 WIN    | 24-Jan-97 | N | S    | 25-Sep-14 | 25-Sep-14 | Fired With Safe ON                                    | Could Not Duplicate Concern                    | 467704        | F | Ilion repaired at n/c   |
| 10740 | 788             | N/A   | 243 WIN    | 8-Apr-79  | N | S    | 25-Sep-14 | 25-Sep-14 | Fired on Safe Release                                 | Improper Maintenance                           | 467693        | F | Returning as received   |
| 10743 | 700             | 27478 | 3006 SPR   | 23-Jun-98 | N | S    | 26-Sep-14 | 17-Oct-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 471452        | F | Per ilion replace trigger at no charge.                           |
| 10744 | 887             | 82501 | 12 GA      | 28-May-14 | N | S    | 29-Sep-14 | 29-Sep-14 | Fired on Bolt Closing                                 | fired on bolt closing                          | 467456        | F | Per ilion - Repair at n/c   |
| 10747 | 700             | 27097 | 7MM REM MA | 26-Apr-12 | N | PD/S | 29-Sep-14 | 10-Nov-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 472867        | F | Replace trigger assembly,check over and test fire at no charge    |
| 10749 | 700             | 27516 | 308 WIN    | 6-Mar-02  | N | S    | 30-Sep-14 | 30-Sep-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 468189        | F | Ilion repaired at n/c   |
| 10751 | 700             | n/a   | 3006 SPRG  | 3-Sep-76  | N | S    | 30-Sep-14 | 30-Sep-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 468664        | F | Ilion repaired at n/c   |

RAC001198

## Confidential

|       |       |       |            |           |   |      |          |           |   |  |        |   |  |
|-------|-------|-------|------------|-----------|---|------|----------|-----------|---|--|--------|---|--|
| 10754 | 700   | 27522 | 270WIN     | 20-Jun-03 | N | S    | 1-Oct-14 | 1-Oct-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 469038 | F | Ilion repaired at n/c  |
| 10755 | 700   | n/a   | 270WIN     | 12-May-76 | N | S    | 1-Oct-14 | 1-Oct-14  | Delayed Firing - Firearms                             | Improper Maintenance                           | 468748 | F | Ilion repaired at n/c  |
| 10756 | 750   | 27059 | 270WIN     | 30-Jul-10 | N | S    | 1-Oct-14 | 1-Oct-14  | Fired Out of Battery                                  | Sent in for Evaluation                         | 468908 | F | Per Ilion, check over completely, repair as needed, and test at no charge. |
| 10757 | 700   | n/a   | 270 WIN    | 17-Nov-81 | N | S    | 1-Oct-14 | 1-Oct-14  | Fired on Safe Release                                 | Altered Adjustments or Components              | 469168 | F | Ilion repaired at n/c under BLM  |
| 10760 | 700   | n/a   | 7MM REM MA | 18-May-76 | N | PI/S | 1-Oct-14 | 15-Dec-14 | Fired on Bolt Opening                                 | Altered Adjustments or Components              | 477211 | F | Repair @ n/c   |
| 10761 | 700   | n/a   | 3006SPRG   | 20-Jan-77 | N | S    | 2-Oct-14 | 2-Oct-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 468962 | F | Ilion repaired at n/c under BLM  |
| 10762 | 78    | 26164 | 3006SPRG   | 24-Jan-85 | Y | S    | 2-Oct-14 | 2-Oct-14  | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 469278 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10763 | 597   | 26536 | 17 HMR     | 28-Mar-03 | N | PD/S | 2-Oct-14 | 2-Oct-14  | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 469266 | F | Per Ilion, converting to 22 WMR as requested by customer.                  |
| 10764 | 700ML | 86950 | 50 CAL     | 11-Aug-14 | Y | S    | 2-Oct-14 | 2-Oct-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 469316 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10765 | 700   | 84601 | 22-250REM  | 4-Dec-12  | N | S    | 2-Oct-14 | 2-Oct-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 469128 | F | Per Ilion - Repair at n/c under recall                                     |
| 10766 | 700ML | 86950 | 50 CAL     | 22-Jul-14 | Y | S    | 2-Oct-14 | 2-Oct-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 469322 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10767 | 700   | 85372 | 243 WIN    | 9-May-12  | N | S    | 2-Oct-14 | 2-Oct-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 469237 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10772 | 700ML | 27572 | 50CAL      | 23-Apr-97 | Y | S    | 3-Oct-14 | 3-Oct-14  | Fired on Safe Release                                 | Broken or Missing Parts                        | 469546 | F | Ilion repaired at n/c  |
| 10775 | 700   | n/a   | 6MM REM    | 13-Sep-78 | N | S    | 3-Oct-14 | 3-Oct-14  | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 469588 | F | Ilion repaired at n/c under BLM  |
| 10778 | 700ML | 27572 | 50 CAL     | 7-Feb-97  | Y | S    | 6-Oct-14 | 6-Oct-14  | Broken Part   | Broken or Missing Parts                        | 469399 | F | Per Ilion - Repair at n/c  |
| 10779 | 700   | n/a   | 308 WIN    |           | N | S    | 6-Oct-14 | 29-Oct-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 469896 | F | Ilion replaced the TA at n/c. Ilion repaired at n/c under BLM              |
| 10780 | 700   | n/a   | 3006 SPRG  | 9-Sep-70  | Y | S    | 6-Oct-14 | 6-Oct-14  | Fired on Safe Release                                 | Improper Maintenance                           | 469814 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10781 | 700   | N/A   | 7MM REM MA | 25-Jun-75 | N | S    | 6-Oct-14 | 6-Oct-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 469787 | F | Ilion repaired at n/c under BLM  |
| 10783 | 700   | n/a   | 17 REM     | 7-Nov-73  | N | S    | 7-Oct-14 | 7-Oct-14  | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 470165 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10784 | 700   | 27482 | 338RUM     | 16-Feb-99 | N | S    | 7-Oct-14 | 7-Oct-14  | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 470168 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10785 | 597   | 26514 | 17 HMR     | 22-Feb-05 | N | S    | 8-Oct-14 | 10-Nov-14 | Other - Firearms                                      | Other - Unspecified or Undetermined - Firearms | 474959 | F | Converting to 22 WMR as requested by customer                              |
| 10786 | 700   | n/a   | 3006 SPRG  | 3-Mar-72  | N | PD/S | 9-Oct-14 | 18-Nov-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 476145 | F | Repair @ n/c   |
| 10790 | 700   | N/A   | 7MM REM MA | 24-Jan-14 | N | S    | 9-Oct-14 | 28-Oct-14 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 472545 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |

RAC001199

## Confidential

|       |                 |       |            |           |   |         |           |           |   |  |        |   |   |
|-------|-----------------|-------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|---|
| 10797 | 700             | 25851 | 270 WIN    | 8-Sep-00  | N | S       | 13-Oct-14 | 13-Oct-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 470682 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 10798 | 700             | 26096 | 300 RUM    | 27-Nov-01 | N | S       | 13-Oct-14 | 13-Oct-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 470563 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 10796 | 700             | 84524 | 7MM MAG    | 21-Sep-10 | N | PD/S    | 13-Oct-14 | 12-Jan-15 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 475151 | F | Per Release - \$1,106.91 reimbursement for truck & camper repair          |
| 10799 | 870             | 25569 | 12 GA      | 20-May-96 | N | S       | 14-Oct-14 | 14-Oct-14 | Delayed Firing - Firearms                             | Sent in for Evaluation                         | 471231 | F | Per Ilion - Quote to repair @ discount                                    |
| 10800 | 700             | 27480 | 7MM REM MA | 28-Feb-97 | N | S       | 14-Oct-14 | 14-Oct-14 | Unexplained Discharge - No Mention of Safety Position | Improper Maintenance                           | 470958 | F | Ilion repaired at n/c   |
| 10801 | 597             | 26562 | 22 LR      | 10-May-06 | N | S       | 14-Oct-14 | 14-Oct-14 | Cartridge Cases Damaged during firing                 | Could Not Duplicate Concern                    | 471143 | F | Per Ilion - Repair at n/c   |
| 10804 | 700             | 27351 | 223 REM    | 16-Dec-09 | N | S       | 14-Oct-14 | 15-Oct-14 | Fired on Bolt Closing                                 | Sent in for Evaluation                         | 455171 | F | Per Ilion - Repair at n/c under recall                                    |
| 10803 | 700             | 26331 | 7MM RUM    | 9-Apr-02  | N | S       | 15-Oct-14 | 15-Oct-14 | Fired on Safe Release                                 | Improper Maintenance                           | 471435 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 10810 | 700             | 27009 | 2506 REM   | 8-Feb-11  | N | S       | 17-Oct-14 | 17-Oct-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 471470 | F | Per Ilion - Repair at n/c under recall                                    |
| 10811 | 700             | 27011 | 270 WIN    | 29-Jun-04 | N | S       | 17-Oct-14 | 17-Oct-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 471687 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 10813 | 700             | N/A   | 222 REM    | 14-Feb-69 | N | S       | 17-Oct-14 | 17-Oct-14 | Fired on Bolt Opening                                 | Improper Maintenance                           | 471786 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 10818 | 1911            | 96323 | 45 ACP     | 16-Sep-11 | N | PI/S    | 21-Oct-14 | 22-Oct-14 | Broken Part   | Sent in for Evaluation                         | 470915 | F | Ilion checked over & tested at no charge                                  |
| 10817 | 1911            | 96323 | 45 ACP     | 13-Feb-13 | N | S       | 22-Oct-14 | 22-Oct-14 | Fired on Bolt Closing                                 | Broken or Missing Parts                        | 470440 | F | Per Ilion - Repair at n/c - warranty                                      |
| 10820 | 7               | 24728 | 223 REM    | 26-Aug-02 | N | S       | 22-Oct-14 | 22-Oct-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 472221 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 10822 | 700             | N/A   | 3006 SPRG  | 29-May-80 | N | S       | 22-Oct-14 | 22-Oct-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 472001 | O | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 10824 | 700             | N/A   | 270 WIN    | 13-Mar-70 | N | PD/S    | 23-Oct-14 | 12-Dec-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 477344 | F | Check over completely, repair as needed, and test at no charge            |
| 10828 | 700             | N/A   | 7MM REM MA | 25-May-76 | N | S       | 23-Oct-14 | 23-Oct-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 471931 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 10829 | H&R Handi-Rifle | 72560 | 243 WIN    | 23-Oct-07 | N | S       | 23-Oct-14 | 3-Dec-14  | Action Opened on Firing                               | Could Not Duplicate Concern                    | 472440 | F | Repair @ n/c  |
| 10830 | 700             | N/A   | 308 WIN    | 23-Jul-79 | N | S       | 23-Oct-14 | 23-Oct-14 | Delayed Firing - Firearms                             | Improper Maintenance                           | 472488 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 10833 | 597             | N/A   | 17 HMR     | 17-Mar-03 | N | PI/PD/S | 24-Oct-14 | 24-Nov-14 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 477177 | F | Converting to 22 WMR as requested by customer                             |
| 10845 | 700             | n/a   | 222 REM    | 1-Jan-75  | N | PD/S    | 28-Oct-14 | 15-Dec-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 477685 | F | Repair @ n/c  |

RAC001200

Confidential

|       |       |            |             |           |   |      |           |           |   |                                   |        |   |   |
|-------|-------|------------|-------------|-----------|---|------|-----------|-----------|---|-----------------------------------|--------|---|---|
| 10846 | 700   | N/A        | 7MM RM      | 13-May-76 | N | PD/S | 28-Oct-14 | 10-Dec-14 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 478868 | F | Check over completely, repair as needed, and test at no charge                  |
| 10843 | 700   | 27053      | 300 RUM     | 15-Jul-05 | N | PI/S | 28-Oct-14 | 18-May-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components | 498064 | F | Replace in exchange with Ramac 27061  |
| 10844 | 700   | 27095      | 3006 SPRG   | 7-Mar-12  | N | PI/S | 28-Oct-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 10847 | 700   | 84205      | 300 BEK OU  | 28-Aug-13 | N | PD/S | 30-Oct-14 | 31-Oct-14 | Delayed Firing - Firearms                             | Could Not Duplicate Concern       | 455135 | F | Per Ilion - Repair at n/c under recall  |
| 10850 | 1187  | 83612      | 12GA        | 6-Aug-12  | N | PD/S | 3-Nov-14  | 3-Nov-14  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 473580 | F | Per Ilion - Repair at n/c   |
| 10851 | 700ML | 27572      | 50 CAL      | 21-Jun-97 | Y | S    | 3-Nov-14  | 3-Nov-14  | Fired on Safe Release                                 | Broken or Missing Parts           | 473529 | F | Per Ilion - Repair at n/c   |
| 10852 | 870   | 24907      | 12 GA       | 4-Jun-97  | N | PD/S | 3-Nov-14  | 3-Nov-14  | Fired Out of Battery                                  | Fired Out of Battery              | 473528 | F | Per Ilion, check over completely, repair as needed, and test at a 50% discount. |
| 10853 | 770   | 85635      | 7MM REM MA  | 9-Feb-13  | N | S    | 3-Nov-14  | 3-Nov-14  | Delayed Firing - Firearms                             | Sent in for Evaluation            | 473424 | F | Per Ilion - Repair at n/c - warranty  |
| 10855 | 700   | N/A        | 308 WIN     | 17-Jun-76 | N | PD/S | 3-Nov-14  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 10860 | 770   | 85635      | 7MM REM MA  | 30-Oct-13 | N | S    | 4-Nov-14  | 4-Nov-14  | Fired With Safe ON                                    | Could Not Duplicate Concern       | 470461 | F | Ilion replaced w/85635 at no charge   |
| 10869 | 700   | 27476      | 270 WIN     | 27-Sep-97 | N | PI/S | 4-Nov-14  | 10-Jul-15 | Fired With Safe ON                                    | Could Not Duplicate Concern       | 499696 | F | Check over completely, repair as needed, and test at no charge                  |
| 10857 | 700   | N/A        | 25-06 REM   | 4-Apr-78  | N | PD/S | 4-Nov-14  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 10862 | 1187  | 83609      | 12GA        | 3-Oct-12  | N | S    | 5-Nov-14  | 5-Nov-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 474156 | F | Per Ilion - Repair/adjust at n/c  |
| 10868 | 700   | 84216      | REM         | 14-Mar-08 | N | S    | 5-Nov-14  | 5-Nov-14  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 473891 | F | Per Ilion - Repair at n/c   |
| 10870 | 700ML | 27580      | 50 CAL      | 29-Oct-97 | N | S    | 5-Nov-14  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 10872 | 700   | 27529      | 3006 SPR    | 18-Oct-99 | N | S    | 7-Nov-14  | 7-Nov-14  | Unexplained Discharge Safe OFF                        | Could Not Duplicate Concern       | 473362 | F | Ilion repaired at n/c   |
| 10873 | 700   | 27482      | 300 WIN     | 28-Jan-04 | N | S    | 7-Nov-14  | 7-Nov-14  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 474009 | F | Ilion repaired at n/c   |
| 10874 | 7     | 24741      | 7MM-08 REM  | 23-Jul-97 | N | S    | 7-Nov-14  | 7-Nov-14  | Fired on Safe Release                                 | Altered Adjustments or Components | 474454 | F | Ilion repaired at n/c   |
| 10875 | 700   | not avail. | 3006 SPR    | 1-Jan-68  | N | S    | 7-Nov-14  | 7-Nov-14  | Fired on Safe Release                                 | Altered Adjustments or Components | 474504 | F | Ilion repaired at n/c   |
| 10877 | 700   | 27387      | 300 WIN     | 12-May-11 | N | S    | 7-Nov-14  | 7-Nov-14  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 474542 | F | Ilion repaired at n/c   |
| 10879 | SEVEN | 24788      | 308 WIN     | 23-Jul-96 | N | PI/S | 7-Nov-14  | 21-Jan-15 | Fired on Safe Release                                 | Improper Maintenance              | 485583 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge       |
| 10890 | 700   | N/A        | 3006 SPRG   | 19-May-75 | N | S    | 7-Nov-14  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 10884 | 700ML | 27580      | 50 CA 6.5MM | 2-Aug-96  | Y | S    | 10-Nov-14 | 10-Nov-14 | Fired on Bolt Closing                                 | Worn parts or components          | 475094 | F | Per Ilion - Repair at n/c   |
| 10885 | 600   | not avail. | REM         | 1-Jul-66  | Y | S    | 10-Nov-14 | 10-Nov-14 | Fired on Safe Release                                 | Altered Adjustments or Components | 475368 | F | Ilion repaired at n/c   |
| 10886 | 887   | 82501      | 12GA        | 28-May-14 | N | S    | 10-Nov-14 | 10-Nov-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 475356 | F | Per Ilion - Repair at n/c - warranty  |
| 10896 | 770   | 85634      | 308 WIN     | 4-Sep-13  | N | S    | 10-Nov-14 | 2-Dec-14  | Delayed Firing - Firearms                             | Could Not Duplicate Concern       | 477914 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge       |

RAC001201

## Confidential

|       |     |            |            |           |   |      |           |           |                                |  |        |   |  |
|-------|-----|------------|------------|-----------|---|------|-----------|-----------|--------------------------------|--|--------|---|--|
| 10892 | 770 | 85637      | 243 WIN    | 7-Feb-14  | N | PI/S | 10-Nov-14 | 7-Jan-15  | Fired on Safe Release          | Could Not Duplicate Concern                    | 481626 | F | Per Ilion, replace with Ramac 85832 in exchange                            |
| 10894 | 887 | 82500      | 12 GA      | 9-Apr-14  | N | S    | 11-Nov-14 | 11-Nov-14 | Fired With Safe ON             | Sent in for Evaluation                         | 475875 | F | Per Ilion - Repair at n/c - warranty                                       |
| 10898 | 700 | 29708      | 270 WIN    | 19-May-93 | N | S    | 11-Nov-14 | 9-Dec-14  | Fired on Safe Release          | Improper Maintenance                           | 478896 | F | Per Ilion - Repair at n/c  |
| 10899 | 700 | not avail. | 3006 SPRG  | 20-Sep-77 | N | PD/S | 11-Nov-14 | 17-Dec-14 | Fired With Safe ON             | Could Not Duplicate Concern                    | 478078 | F | Repair @ n/c - goodwill gesture  |
| 10903 | 887 | 82500      | 12 GA      | 6-Jun-14  | N | PD/S | 12-Nov-14 | 8-Dec-14  | Fired With Safe ON             | Fired on safe                                  | 478055 | F | Replace with Ramac 81046 in exchange                                       |
| 10907 | 700 | 27478      | 3006 SPR   | 30-Aug-95 | N | S    | 13-Nov-14 | 13-Nov-14 | Fired on Bolt Closing          | Could Not Duplicate Concern                    | 475628 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10908 | 660 | not avail. | 243 WIN    | 1-Jan-68  | Y | S    | 13-Nov-14 | 13-Nov-14 | Fired on Safe Release          | Could Not Duplicate Concern                    | 474049 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10909 | 700 | 87268      | 300 WBV MA | 25-Sep-14 | N | S    | 13-Nov-14 | 13-Nov-14 | Fired on Bolt Closing          | Could Not Duplicate Concern                    | 476068 | F | Repair @ n/c under XMP recall  |
| 10910 | 700 | not avail. | 6MM REM    | 6-Jul-76  | N | S    | 13-Nov-14 | 13-Nov-14 | Fired on Bolt Closing          | Altered Adjustments or Components              | 476200 | F | Ilion repaired at n/c  |
| 10911 | 700 | not avail. | 270 WIN    | 29-Apr-77 | N | S    | 13-Nov-14 | 13-Nov-14 | Fired on Safe Release          | Altered Adjustments or Components              | 476161 | F | Ilion repaired at n/c  |
| 10912 | 700 | 25771      | 270 WIN    | 21-Sep-84 | N | S    | 13-Nov-14 | 13-Nov-14 | Fired With Safe ON             | Could Not Duplicate Concern                    | 476204 | F | Ilion repaired at n/c  |
| 10921 | 700 | 84401      | 25-06 REM  | 16-Feb-09 | N | S    | 13-Nov-14 | 12-Dec-14 | Unexplained Discharge Safe OFF | Could Not Duplicate Concern                    | 479540 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10929 | 700 | N/A        | 3006 SPRG  | 9-Jul-76  | N | S    | 13-Nov-14 | 22-Oct-15 | Fired on Safe Release          | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 10919 | 887 | 82500      | 12 GA      | 6-Jun-14  | N | PD/S | 14-Nov-14 | 31-Dec-14 | Fired With Safe ON             | Other - Unspecified or Undetermined - Firearms | 478567 | F | Replace w/82500 in exchange  |
| 10930 | 700 | 25771      | 270 WIN    | 31-May-00 | N | S    | 14-Nov-14 | 16-Jan-15 | Fired on Safe Release          | Could Not Duplicate Concern                    | 485527 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10938 | 700 | 25800      | 7MM-08     | 11-Dec-93 | N | S    | 14-Nov-14 | 23-Jan-15 | Fired on Safe Release          | Could Not Duplicate Concern                    | 487076 | F | Per Ilion - Repair at n/c - goodwill                                       |
| 10934 | 700 | N/A        | 7MM REM MA | 1-Jun-62  | N | S    | 14-Nov-14 | 12-Feb-15 | Fired on Bolt Closing          | Could Not Duplicate Concern                    | 492388 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 10926 | 742 | N/A        | 3006 SPRG  | 27-Jan-78 | Y | PD/S | 14-Nov-14 | 27-Feb-15 | Unexplained Discharge Safe ON  | Could Not Duplicate Concern                    | 478676 | F | clean and check over trigger assembly at no charge as a goodwill gesture   |
| 10922 | 700 | not avail. | 222 REM    | 4-Feb-88  | N | S    | 17-Nov-14 | 17-Nov-14 | Fired on Safe Release          | Could Not Duplicate Concern                    | 476575 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 10923 | 770 | 85637      | 243 WIN    | 19-Jan-09 | N | S    | 17-Nov-14 | 17-Nov-14 | Delayed Firing - Firearms      | Sent in for Evaluation                         | 476548 | F | Per Ilion, check over completely, repair as needed, and test at no charge. |
| 10924 | 770 | 85637      | 243 WIN    | 5-Dec-12  | N | S    | 17-Nov-14 | 17-Nov-14 | Fail to Fire                   | Sent in for Evaluation                         | 476253 | F | Per Ilion, check over completely, repair as needed, and test at no charge. |
| 10925 | 700 | n/a        | 3006 SPRG  | 11-Jun-69 | N | S    | 17-Nov-14 | 5-Dec-14  | Fired on Bolt Opening          | Improper Maintenance                           | 478503 | F | Ilion repaired at n/c under BLM  |
| 10927 | 700 | 26967      | 308 WIN    | 28-Dec-95 | N | S    | 17-Nov-14 | 9-Dec-14  | Delayed Firing - Firearms      | Could Not Duplicate Concern                    | 478756 | F | Per Ilion - Replace TA & test @ n/c  |

RAC001202

## Confidential

|       |           |            |           |           |   |         |           |           |   |                                   |        |   |   |
|-------|-----------|------------|-----------|-----------|---|---------|-----------|-----------|---|-----------------------------------|--------|---|---|
| 10996 | 660       | not avail. | 243 WIN   | 24-Jul-69 | Y | S       | 17-Nov-14 | 12-Dec-14 | Fired on Safe Release                                 | Altered Adjustments or Components | 479426 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge       |
| 10957 | 788       | N/A        | 7MM-08    | 5-Nov-81  | Y | S       | 17-Nov-14 | 21-Jan-15 | Fired on Safe Release                                 | Improper Maintenance              | 481500 | F | Per Ilion, check over completely, repair as needed, and test at a 50% discount. |
| 10959 | 700       | N/A        | 3006 SPRG | 31-Mar-88 | N | S       | 17-Nov-14 | 8-Jan-15  | Fired on Safe Release                                 | Altered Adjustments or Components | 483961 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge       |
| 10928 | 700       | N/A        | 3006 SPRG |           | N | PI/PD/S | 17-Nov-14 | 22-Oct-15 | Unexplained Discharge - No Mention of Safety Position | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 10994 | 700       | N/A        | 270 WIN   | 25-Nov-70 | N | S       | 17-Nov-14 | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 10931 | 700       | not avail. | 243 WIN   | 18-Sep-80 | N | S       | 18-Nov-14 | 18-Dec-14 | Fired on Safe Release                                 | Altered Adjustments or Components | 480785 | F | Ilion repaired at n/c   |
| 10935 | 700       | 85421      | 3006 SPRG | 28-Aug-09 | N | S       | 18-Nov-14 | 19-Dec-14 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 481322 | F | Per Ilion - Repair at n/c under recall  |
| 10937 | 700       | 25791      | 270 WIN   | 22-Apr-04 | N | S       | 18-Nov-14 | 4-Dec-14  | Fired on Safe Release                                 | Improper Maintenance              | 478407 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge       |
| 10948 | 700       | N/A        | 6MM REM   | 23-Jun-77 | N | PD/S    | 18-Nov-14 | 16-Dec-14 | Fired on Bolt Opening                                 | Altered Adjustments or Components | 479440 | F | Check over completely, repair as needed, and test at no charge                  |
| 10955 | 700       | N/A        | 3006 SPRG | 27-Jul-73 | N | S       | 18-Nov-14 | 18-Dec-14 | Fired on Safe Release                                 | Altered Adjustments or Components | 480875 | F | Replace trigger assembly,check over and test fire at no charge                  |
| 10997 | 700       | N/A        | 3006 SPRG | 12-Aug-75 | N | S       | 18-Nov-14 | 18-Dec-14 | Fired on Safe Release                                 | Altered Adjustments or Components | 480700 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge       |
| 10998 | 700       | N/A        | 243 WIN   | 27-Feb-70 | N | S       | 18-Nov-14 | 18-Dec-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components | 480857 | F | Replace trigger assembly,check over and test fire at no charge                  |
| 11080 | 700       | 25775      | 308 WIN   | 13-Feb-86 | N | S       | 18-Nov-14 | 3-Feb-15  | Delayed Firing - Firearms                             | Improper Maintenance              | 489347 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge      |
| 10933 | 700       | 85336      | 3006 SPRG | 22-Jul-13 | N | S       | 18-Nov-14 | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 10999 | 700       | N/A        | 7MM REM   |           | N | MA      | 18-Nov-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 10939 | 770       | 85632      | 270 WIN   | 13-Mar-13 | N | S       | 19-Nov-14 | 19-Nov-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 475965 | F | Per Ilion - Repair at n/c - warranty  |
| 10940 | CARBON 15 | 90689      | 5.56      | 5-Jun-13  | N | S       | 19-Nov-14 | 19-Nov-14 | Went Automatic  | Sent in for Evaluation            | 474723 | F | Per Ilion - Repair at n/c   |
| 10941 | 700       | 27480      | 7MM REM   | 30-Nov-01 | N | S       | 19-Nov-14 | 19-Nov-14 | Fired on Safe Release                                 | Altered Adjustments or Components | 476727 | F | Ilion repaired at n/c   |
| 10942 | 700       | not avail. | 3006 SPR  | 25-Oct-76 | N | S       | 19-Nov-14 | 19-Nov-14 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 476729 | F | Ilion repaired at n/c   |
| 10944 | 770       | 85632      | 270 WIN   | 17-Oct-12 | N | S       | 19-Nov-14 | 19-Nov-14 | Fired With Safe ON                                    | Could Not Duplicate Concern       | 476780 | F | Per Ilion - Repair at n/c - goodwill  |
| 10949 | 700       | N/A        | 3006 SPRG | 24-Feb-69 | N | S       | 19-Nov-14 | 9-Dec-14  | Delayed Firing - Firearms                             | Improper Maintenance              | 478810 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge      |
| 11083 | 700       | N/A        | 25-06 REM |           | N | S       | 19-Nov-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 11081 | 700       | N/A        | 3006 SPRG | 26-Feb-76 | N | S       | 19-Nov-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam  |
| 10954 | 700       | 27389      | 300 RUM   | 22-Sep-08 | N | S       | 20-Nov-14 | 20-Nov-14 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Not Examined by Product Service   |

RAC001203

Confidential

|       |       |            |           |           |   |      |           |           |   |  |        |  |  |
|-------|-------|------------|-----------|-----------|---|------|-----------|-----------|---|--|--------|--|--|
| 10956 | 700   | n/a        | 3006 SPRG | 8-Feb-79  | N | PD/S | 20-Nov-14 | 30-Dec-14 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 481793 | F                                      | Repair @ n/c   |
| 10958 | 700   | 25802      | 7MM RM    | 22-Apr-92 | N | PD/S | 20-Nov-14 | 11-Dec-14 | Fired on Safe Release                                 | Improper Maintenance                           | 478803 | F                                      | Repair @ n/c - goodwill gesture  |
| 10960 | 597   | 26516      | 17 HMR    | 8-Dec-04  | N | PD/S | 20-Nov-14 | 9-Dec-14  | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 478755 | F                                      | Per Ilion, converting to 22 WMR as requested by customer.                  |
| 10953 | SEVEN | 24741      | 7MM-08    | 18-Jul-97 | N | S    | 20-Nov-14 | 22-Oct-15 | Delayed Firing - Firearms                             | Not Examined by Product Service                | n/a    | F                                      | Firearm not returned to Ilion for exam                                     |
| 10082 | 700   | 25634      | 3006 SPR  | 27-Feb-86 | N | S    | 21-Nov-14 | 21-Nov-14 | Fired on Bolt Closing                                 | Improper Maintenance                           | 477209 | F                                      | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 10961 | 887   | 82500      | 12 GA     | 23-Jun-14 | N | S    | 21-Nov-14 | 21-Nov-14 | Fired on Bolt Closing                                 | Sent in for Evaluation                         | 475737 | F                                      | Per Ilion - Repair at n/c - warranty                                       |
| 10962 | 700   | 84370      | 223 REM   | 11-Jan-08 | N | S    | 21-Nov-14 | 21-Nov-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 476988 | F                                      | Per Ilion, replace trigger assembly, check over and test fire at no charge |
|       |       |            |           |           |   |      |           |           | Unexplained Discharge - No Mention of Safety Position |  |        |  |  |
| 10963 | 700   | not avail. | 270 WIN   | 22-Mar-79 | N | S    | 21-Nov-14 | 21-Nov-14 | Improper Maintenance                                  | 477154   | F      | Ilion repaired at n/c                  |  |
| 10964 | 700   | not avail. | 243 WIN   | 24-Jan-69 | N | S    | 21-Nov-14 | 21-Nov-14 | Altered Adjustments or Components                     | 477208   | F      | Ilion repaired at n/c                  |  |
| 10965 | 700   | 27476      | 270 WIN   | 5-Feb-97  | N | S    | 21-Nov-14 | 21-Nov-14 | Altered Adjustments or Components                     | 477212   | F      | Ilion repaired at n/c                  |  |
| 10966 | 770   | 85633      | 3006 SPRG | 29-Jan-08 | N | S    | 21-Nov-14 | 21-Nov-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 477210 | F                                      | Per Ilion - Repair at n/c - goodwill                                       |
| 10972 | 660   | not avail. | 6MM       | 1-Jan-68  | Y | S    | 21-Nov-14 | 12-Dec-14 | Fired on Safe Release                                 | Improper Maintenance                           | 479593 | F                                      | Per Ilion - Repair at n/c under recall                                     |
| 10969 | 870   | 25098      | 12 GA     | 19-Sep-12 | N | PD/S | 21-Nov-14 | 6-Jan-15  | Fired on Bolt Closing                                 | Fired from Contact with Foreign Object         | 482828 | F                                      | Per Ilion - Repair at n/c  |
|       |       |            |           |           |   |      |           |           | Unexplained Discharge - No Mention of Safety Position |  |        |  |  |
| 10970 | 700   | not avail. | 3006 SPRG | 1-Mar-68  | N | PD/S | 21-Nov-14 | 27-Jan-15 | Could Not Duplicate Concern                           | 481503   | F      | Repair @ n/c                           |  |
| 10971 | 700   | 84126      | 3006 SPRG | 26-Jul-11 | N | S    | 21-Nov-14 | 16-Jan-15 | Could Not Duplicate Concern                           | 485631   | F      | Per Ilion - Repair at n/c              |  |
| 10973 | 700   | 25787      | 243 WIN   | 23-Feb-84 | N | S    | 21-Nov-14 | 17-Apr-15 | Fired on Bolt Closing                                 | Improper Maintenance                           | 489643 | F                                      | Per Ilion: Repair at no charge   |
| 10968 | 700   | n/a        | 7MM MAG   | 6-Jun-75  | N | S    | 21-Nov-14 | 22-Oct-15 | Not Examined by Product Service                       | n/a  | F      | Firearm not returned to Ilion for exam |  |
| 10982 | 700   | 25773      | 3006 SPRG | 11-Sep-85 | N | S    | 24-Nov-14 | 18-Dec-14 | Fired on Safe Release                                 | Improper Maintenance                           | 480844 | F                                      | Ilion repaired at n/c  |
| 10985 | 700   | 27502      | 7MM STW   | 14-Apr-97 | N | S    | 24-Nov-14 | 12-Dec-14 | Altered Adjustments or Components                     | 479563   | F      | Per Ilion - Replace TA & test @ n/c    |  |
| 10986 | 700   | n/a        | 7MM RM    | 3-Jun-75  | N | S    | 24-Nov-14 | 18-Dec-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 480784 | F                                      | Ilion repaired at n/c  |
|       |       |            |           |           |   |      |           |           |   |  |        |  |  |
| 10992 | 700   | 25935      | 300 WIN M | 23-Feb-96 | N | S    | 24-Nov-14 | 11-Dec-14 | Unexplained Discharge Safe OFF                        | Improper Maintenance                           | 479104 | F                                      | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 10993 | 700   | N/A        | 3006 SPRG | 13-Jul-71 | N | S    | 24-Nov-14 | 11-Dec-14 | Delayed Firing - Firearms                             | Could Not Duplicate Concern                    | 478986 | F                                      | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 10977 | 887   | 82500      | 12 GA     | 6-Jun-14  | N | PD/S | 24-Nov-14 | 12-Feb-15 | Fired on Bolt Closing                                 | Sent in for Evaluation                         | 485319 | F                                      | Replace with Ramac 81054 in exchange and \$875 for damage to house         |
| 10984 | 700   | 27361      | 270 WIN   | 19-Apr-12 | N | S    | 24-Nov-14 | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F                                      | Firearm not returned to Ilion for exam                                     |

RAC001204

Confidential

|       |     |            |            |           |   |      |           |           |   |                                   |        |   |  |
|-------|-----|------------|------------|-----------|---|------|-----------|-----------|---|-----------------------------------|--------|---|--|
| 10987 | 700 | N/A        | 308 WIN    | 10-Mar-77 | N | S    | 25-Nov-14 | 25-Nov-14 | Unexplained Discharge - No Mention of Safety Position | Improper Maintenance              | 477227 | F | Per Ilion, check over completely, repair as needed, and test at no charge.                   |
| 10988 | 700 | N/A        | 3006 SPR   | 15-Apr-74 | N | S    | 25-Nov-14 | 25-Nov-14 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 477324 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                   |
| 10990 | 700 | 27094      | 270 WIN    | 9-Jun-12  | N | S    | 25-Nov-14 | 25-Nov-14 | Delayed Firing - Firearms                             | Could Not Duplicate Concern       | 477348 | F | Per Ilion - Repair at n/c  |
| 10991 | 700 | N/A        | 3006 SPR   | 22-Jun-71 | N | S    | 25-Nov-14 | 25-Nov-14 | Fired on Safe Release                                 | Fired on Safe Release             | 477347 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                   |
| 10995 | 700 | 84461      | 308 WIN    | 25-Feb-10 | N | S    | 25-Nov-14 | 18-Dec-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 480674 | F | Per Ilion - Repair at n/c under recall   |
| 11000 | 700 | n/a        | 3006 SPRG  | 23-Jun-71 | N | S    | 25-Nov-14 | 11-Dec-14 | Unexplained Discharge Safe OFF                        | Altered Adjustments or Components | 479321 | F | Ilion repaired at n/c  |
| 11001 | 700 | n/a        | GMM        | 16-Mar-70 | N | S    | 25-Nov-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Rifle not returned to Ilion for exam   |
| 11004 | 700 | 85478      | 270 WIN    | 18-May-10 | N | S    | 26-Nov-14 | 26-Nov-14 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 477691 | F | Refunded purchase price in Consumer Service.   |
| 11085 | 700 | 26121      | 25-06 REM  | 25-Apr-97 | N | S    | 26-Nov-14 | 6-Jan-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 483612 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                   |
| 11008 | 700 | 25791      | 270 WIN    | 22-Jun-12 | N | S    | 26-Nov-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam   |
| 11009 | 700 | N/A        | 3006 SPRG  | 28-Jun-76 | N | S    | 26-Nov-14 | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam   |
| 11010 | 710 | 27414      | 300 WM     | 25-Oct-06 | Y | S    | 1-Dec-14  | 1-Dec-14  | Fired on Safe Release                                 | Altered Adjustments or Components | 477868 | F | Per Ilion - Quote to repair @ discount - goodwill  |
| 11011 | 700 | not avail. | 243 WIN    | 30-Apr-74 | N | S    | 1-Dec-14  | 1-Dec-14  | Delayed Firing - Firearms                             | Improper Maintenance              | 477823 | F | Ilion repaired at n/c  |
| 11012 | 700 | not avail. | 270 WIN    | 9-May-74  | N | S    | 1-Dec-14  | 1-Dec-14  | Delayed Firing - Firearms                             | Sent in for Evaluation            | 477840 | F | Per Ilion - Quote to repair @ discount for main spring                                       |
| 11013 | 700 | 25630      | 270 WIN    | 15-May-92 | N | S    | 1-Dec-14  | 1-Dec-14  | Fired on Safe Release                                 | Improper Maintenance              | 477855 | F | Ilion repaired at n/c  |
| 11032 | 700 | 29713      | 280 REM    | 25-May-94 | N | S    | 1-Dec-14  | 18-Dec-14 | Fired on Bolt Opening                                 | Altered Adjustments or Components | 480831 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                   |
| 11016 | 700 | 85433      | 223 REM    | 23-Feb-11 | N | PD/S | 1-Dec-14  | 23-Jan-15 | Unexplained Discharge Safe OFF                        | Could Not Duplicate Concern       | 481499 | F | Check over completely, repair as needed, and test at no charge                               |
| 11020 | 700 | not avail. | 25-06 REM  | 14-Mar-74 | N | S    | 1-Dec-14  | 8-Jan-15  | Fired on Bolt Closing                                 | Improper Maintenance              | 484074 | F | Ilion repaired at n/c  |
| 11033 | 700 | N/A        | 243 WIN    | 1-Jun-66  | N | S    | 1-Dec-14  | 12-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 484759 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                   |
| 11021 | 770 | 85630      | 243 WIN    | 14-May-08 | N | S    | 1-Dec-14  | 13-Feb-15 | Fired With Safe ON                                    | Altered Adjustments or Components | 493037 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                   |
| 11023 | 700 | 85492      | 7MM REM MA | 4-Jan-13  | N | S    | 1-Dec-14  | 9-Feb-15  | Fired With Safe ON                                    | Could Not Duplicate Concern       | 481490 | F | Check over completely, repair as needed, and test at no charge and reimburse PD of \$1113.94 |
| 11093 | 700 | 26033      | 270 WIN    | 17-Apr-98 | N | S    | 1-Dec-14  | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam   |
| 11017 | 700 | not avail. | 3006 SPRG  | 21-Mar-69 | N | S    | 1-Dec-14  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam   |

RAC001205

Confidential

|       |      |            |            |           |   |      |          |           |   |  |        |   |   |
|-------|------|------------|------------|-----------|---|------|----------|-----------|---|--|--------|---|---|
| 11022 | 700  | N/A        | 3006 SPRG  | 20-Mar-69 | N | S    | 1-Dec-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam  |
| 11018 | 770  | 85633      | 3006 SPRG  | 14-Feb-08 | Y | S    | 1-Dec-14 | 22-Oct-15 | Unexplained Discharge Safe OFF                        | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam  |
| 11025 | 597  | 26537      | 22LR       | 29-May-08 | N | PD/S | 2-Dec-14 | 2-Dec-14  | Fired Out of Battery                                  | Other - Unspecified or Undetermined - Firearms | 478023 | F | Per Ilion - Repair at n/c - goodwill  |
| 11027 | 700  | not avail. | 243 WIN    | 23-Aug-88 | N | S    | 2-Dec-14 | 2-Dec-14  | Fired on Safe Release                                 | Improper Maintenance                           | 478056 | F | Ilion repaired at n/c   |
| 11028 | 700  | 25851      | 270 WIN    | 10-Feb-04 | N | S    | 2-Dec-14 | 2-Dec-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 478042 | F | Ilion repaired at n/c   |
| 11029 | 700  | 25767      | 243 WIN    | 31-Jul-89 | N | S    | 2-Dec-14 | 2-Dec-14  | Delayed Firing - Firearms                             | Could Not Duplicate Concern                    | 477995 | F | Ilion repaired at n/c   |
| 11030 | 700  | 27508      | 300 WIN MA | 12-May-04 | N | S    | 2-Dec-14 | 2-Dec-14  | Fired on Bolt Closing                                 | Improper Maintenance                           | 478021 | F | Ilion repaired at n/c   |
| 11031 | 600  | N/A        | 6MM        | 1-Dec-65  | N | S    | 2-Dec-14 | 2-Dec-14  | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 477908 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                          |
| 11044 | 700  | 84213      | 17 FIREBAL | 8-Aug-07  | N | PD/S | 2-Dec-14 | 23-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 481489 | F | Check over completely, repair as needed, and test at no charge                                      |
| 11045 | 700  | N/A        | 7MM REM MA | 1-Aug-67  | N | S    | 2-Dec-14 | 6-Jan-15  | Fired on Safe Release                                 | Altered Adjustments or Components              | 482807 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                          |
| 11046 | 700  | 85435      | 308 WIN    | 6-Aug-10  | N | S    | 2-Dec-14 | 18-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 481682 | F | Check over completely, repair as needed, and test at N/C, reimburse vehicle damage                  |
| 11034 | 700  | 85463      | 270 WIN    | 8-Aug-13  | N | PD/S | 2-Dec-14 | 16-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 488804 | F | Per Release - Check for \$1,194 & replace gun w/27499 in exchange                                   |
| 11058 | 700  | N/A        | 3006 SPRG  | 25-Mar-79 | N | PD/S | 2-Dec-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam  |
| 11059 | 1187 | 29917      | 20 GA      | 20-Jun-11 | N | PD/S | 2-Dec-14 | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam  |
| 11056 | 700  | 25819      | 243 WIN    | 10-Aug-89 | N | S    | 2-Dec-14 | 13-Oct-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 504692 | F | Per Ilion, quote to check over completely, repair as needed, and test, replace trigger at no charge |
| 11038 | 700  | 27144      | 300 WSM    | 30-Jun-06 | N | S    | 2-Dec-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam  |
| 11039 | 700  | 27478      | 3006 SPRG  | 12-Mar-99 | N | S    | 3-Dec-14 | 22-Dec-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 481494 | F | Ilion repaired at n/c   |
| 11048 | 700  | not avail. | 300 RUM    | 1-May-99  | N | S    | 3-Dec-14 | 22-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 486666 | F | Per Ilion - Repair at n/c - goodwill  |
| 11049 | 700  | not avail. | 7MM MAG    | 7-Feb-69  | N | S    | 3-Dec-14 | 16-Jan-15 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 485521 | F | Per Ilion - Repair at n/c - goodwill  |
| 11051 | 700  | 27478      | 3006 SPRG  | 10-Mar-99 | N | S    | 3-Dec-14 | 7-Jan-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 483703 | F | Per Ilion - Repair at n/c   |
| 11076 | 700  | N/A        | 222 REM    | 20-Feb-69 | N | S    | 3-Dec-14 | 6-Jan-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 482806 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                          |
| 11047 | 887  | 82502      | 12 GA      | 26-Feb-11 | N | S    | 3-Dec-14 | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam  |
| 11052 | 7    | 24786      | 7MM08 REM  | 31-Oct-84 | N | S    | 4-Dec-14 | 4-Dec-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 478090 | F | Ilion repaired at n/c   |

RAC001206

Confidential

|       |       |            |            |           |   |      |           |           |   |  |        |   |  |
|-------|-------|------------|------------|-----------|---|------|-----------|-----------|---|--|--------|---|--|
| 11053 | 7     | 24779      | 243 WIN    | 6-Apr-00  | N | S    | 4-Dec-14  | 4-Dec-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 478077 | F | Per Ilion - Quote to repair @ discount                                     |
| 11054 | 700   | 27478      | 3006 SPR   | 12-Dec-01 | N | S    | 4-Dec-14  | 4-Dec-14  | Fired With Safe ON                                    | Altered Adjustments or Components              | 478402 | F | Ilion repaired at n/c  |
| 11055 | 700   | 27225      | 308 WIN    | 19-Oct-11 | N | S    | 4-Dec-14  | 4-Dec-14  | Fired on Safe Release                                 | Altered Adjustments or Components              | 478390 | F | Per Ilion - Repair at n/c - goodwill                                       |
| 11061 | 700   | N/A        | 3006 SPRG  | 9-Jul-73  | N | S    | 4-Dec-14  | 6-Jan-15  | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 482804 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 11063 | 710   | 27408      | 270 WIN    | 28-Jun-02 | N | PD/S | 4-Dec-14  | 6-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 483672 | F | Replace with Ramac 85844 in exchange                                       |
| 11066 | 887   | 82502      | 12 GA      | 4-Apr-13  | N | S    | 4-Dec-14  | 7-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 491819 | F | Ilion repaired at n/c  |
| 11095 | 700   | N/A        | 243 WIN    | 11-Oct-72 | N | S    | 4-Dec-14  | 27-Mar-15 | Fired on Safe Release                                 | Altered Adjustments or Components              | 497370 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11060 | 700   | 27480      | 7MM REM MA | 22-Jul-95 | N | S    | 4-Dec-14  | 22-Oct-15 | Delayed Firing - Firearms                             | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11069 | 700   | not avail. | 3006SPR    | 17-Feb-81 | N | S    | 5-Dec-14  | 5-Dec-14  | Fired With Safe ON                                    | Improper Maintenance                           | 478481 | F | Ilion repaired at n/c  |
| 11070 | 700   | not avail. | 3006SPR    | 4-Mar-82  | N | S    | 5-Dec-14  | 5-Dec-14  | Fired on Bolt Closing                                 | Improper Maintenance                           | 478475 | F | Ilion repaired at n/c  |
| 11071 | 700   | 25793      | 3006 SPRG  | 30-Apr-03 | N | S    | 5-Dec-14  | 5-Dec-14  | Unexplained Discharge - No Mention of Safety Position | Improper Maintenance                           | 478559 | F | Ilion repaired at n/c  |
| 11072 | 700   | 27361      | 270 WIN    | 12-Sep-07 | N | S    | 8-Dec-14  | 12-Jan-15 | Fired on Safe Release                                 | Altered Adjustments or Components              | 484635 | F | Per Ilion - Repair at n/c - goodwill                                       |
| 11075 | 700   | N/A        | 3006 SPRG  | 1-Nov-74  | N | S    | 8-Dec-14  | 22-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 486374 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge  |
| 11077 | 721   | not avail. | 270 WIN    | 1-Nov-71  | Y | S    | 8-Dec-14  | 9-Jan-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 484241 | F | Ilion repaired at n/c  |
| 11078 | 700   | 25803      | 7MM MAG    | 22-Sep-89 | N | S    | 8-Dec-14  | 6-Jan-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 482803 | F | Per Ilion - Repair at n/c  |
| 11079 | 700   | 26033      | 270 WIN    | 10-Feb-98 | N | S    | 8-Dec-14  | 12-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 484518 | F | Per Ilion - Repair at n/c - goodwill                                       |
| 11082 | 700ML | 27572      | 50 CAL     | 28-Aug-96 | Y | S    | 8-Dec-14  | 21-Jan-15 | Fired on Safe Release                                 | Sent in for Evaluation                         | 486367 | F | Per Ilion - Repair at n/c - goodwill                                       |
| 11103 | 700   | not avail. | 270 WIN    | 3-May-76  | N | S    | 8-Dec-14  | 22-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 486694 | F | Per Ilion - Repair at n/c  |
| 11073 | 700   | 25793      | 3006 SPRG  | 16-Apr-03 | N | S    | 8-Dec-14  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11090 | 700   | 84203      | 308 WIN    | 22-Jun-12 | N | S    | 9-Dec-14  | 9-Dec-14  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 478812 | F | Per Ilion - Repair at n/c under recall                                     |
| 11091 | 700   | not avail. | 270 WIN    | 1-Jul-65  | N | S    | 9-Dec-14  | 9-Dec-14  | Fired on Safe Release                                 | Improper Maintenance                           | 478752 | F | Ilion - repair at n/c  |
| 11089 | 597   | 26516      | 17 HMR     | 11-Dec-02 | N | PD/S | 9-Dec-14  | 24-Feb-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 478819 | F | Replace with Ramac 70723 in exchange                                       |
| 11098 | 700   | not avail. | 7MM MAG    | 28-Apr-77 | N | PI/S | 9-Dec-14  | 23-Feb-15 | Fired on Safe Release                                 | Improper Maintenance                           | 485292 | F | Repair @ n/c   |
| 11101 | 700   | 25860      | 243 WIN    | 14-Dec-82 | N | S    | 9-Dec-14  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11099 | 700   | N/A        | 3006 SPRG  |           | N | S    | 9-Dec-14  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11100 | 700   | N/A        | 243 WIN    |           | N | S    | 9-Dec-14  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11111 | 700   | N/A        | 270 WIN    | 23-Apr-76 | N | S    | 10-Dec-14 | 23-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 487068 | F | Check over completely, repair as needed, and test at no charge             |

RAC001207

## Confidential

|       |             |            |            |           |   |      |           |           |                                      |                                   |        |   |  |
|-------|-------------|------------|------------|-----------|---|------|-----------|-----------|--------------------------------------|-----------------------------------|--------|---|--|
| 11108 | 700         | 29692      | 7MM REM MA | 20-Mar-96 | N | S    | 10-Dec-14 | 22-Oct-15 | Fired on Safe Release                | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam   |
| 11110 | 700         | 27355      | 243 WIN    | 6-Aug-09  | N | S    | 11-Dec-14 | 11-Dec-14 | Fired on Safe Release                | Could Not Duplicate Concern       | 479326 | F | Per Ilion - Repair at n/c under recall   |
| 11115 | 700         | not avail. | 3006 SPRG  | 1-Dec-83  | N | PD/S | 11-Dec-14 | 21-Jan-15 | Fired on Safe Release                | Could Not Duplicate Concern       | 485290 | F | Per Ilion - Repair at n/c - goodwill   |
| 11119 | 700         | 25771      | 270 WIN    | 25-Mar-92 | N | S    | 11-Dec-14 | 26-Jan-15 | Fired on Safe Release                | Could Not Duplicate Concern       | 487348 | F | Check over completely, repair as needed, and test at no charge                                     |
| 11122 | 770         | 85632      | 270 WIN    | 3-Oct-12  | Y | PD/S | 11-Dec-14 | 20-Jan-15 | Ammunition Exploded                  | Sent in for Evaluation            | 485838 | A | Per Ilion, replace in exchange with Ramac 85632 at no charge. Lonoke sent customer 2 boxes of ammo |
| 11126 | 700         | N/A        | 7MM REM MA | 26-Jul-71 | N | S    | 11-Dec-14 | 15-Jan-15 | Fired on Bolt Closing                | Could Not Duplicate Concern       | 485231 | F | Check over completely, repair as needed, and test at no charge                                     |
| 11127 | 700         | 27453      | 7MM-08 REM | 28-Mar-02 | N | S    | 11-Dec-14 | 3-Feb-15  | Fired on Safe Release                | Could Not Duplicate Concern       | 489176 | F | Per Ilion, check over completely, repair as needed, and test at no charge.                         |
| 11123 | 770         | 85657      | 7MM REM MA | 3-Feb-09  | Y | PD/S | 11-Dec-14 | 22-Oct-15 | Fired With Safe ON                   | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam   |
| 11118 | 700         | N/A        | 300 WIN M  | 23-Apr-81 | N | S    | 11-Dec-14 | 22-Oct-15 | Fired on Safe Release                | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam   |
| 11124 | 7400        | 29759      | 270 WIN    | 11-Jun-97 | Y | S    | 12-Dec-14 | 12-Dec-14 | Went Automatic                       | Could Not Duplicate Concern       | 479591 | F | Returned as Received - customer request  |
| 11125 | 700         | 26259      | 3006 SPR   | 14-Oct-97 | N | S    | 12-Dec-14 | 12-Dec-14 | Fired on Safe Release                | Improper Maintenance              | 479435 | F | Ilion repaired at n/c  |
| 11128 | Handi Rifle | 72652      | 243 WIN    | 6-Nov-13  | N | PD/S | 12-Dec-14 | 30-Jan-15 | Ammunition Exploded                  | Sent in for Evaluation            | 487638 | F | Check over completely, repair as needed, and test at no charge                                     |
| 11130 | 710         | 27408      | 270 WIN    | 14-May-03 | N | S    | 12-Dec-14 | 15-Jan-15 | Fail to Fire                         | Could Not Duplicate Concern       | 485191 | F | Quote to repair at 50% discount  |
| 11132 | 887         | 82500      | 12 GA      | 8-Nov-13  | N | S    | 12-Dec-14 | 6-Feb-15  | Fired on Bolt Closing                | Could Not Duplicate Concern       | 484778 | F | Replace with Ramac 26927 in exchange and check for \$625 for damage to house                       |
| 11129 | 700         | 84179      | 7MM REM MA | 26-Jul-12 | N | S    | 12-Dec-14 | 22-Oct-15 | Fired on Safe Release                | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam   |
| 11135 | 700         | N/A        | 6MM REM    | 27-Oct-77 | N | PI/S | 15-Dec-14 | 23-Jan-15 | Fired on Safe Release                | Could Not Duplicate Concern       | 485729 | F | Check over completely, repair as needed, and test at no charge                                     |
| 11138 | 700         | 27476      | 270 WIN    | 18-Aug-97 | N | S    | 15-Dec-14 | 16-Feb-15 | Unexplained Discharge Safe ON        | Could Not Duplicate Concern       | 488301 | F | Check over completely, repair as needed, and test at no charge                                     |
| 11139 | 700         | not avail. | 243 WIN    | 11-Apr-72 | N | PD/S | 15-Dec-14 | 25-Mar-15 | Fired on Safe Release                | Could Not Duplicate Concern       | 487643 | F | Repair @ n/c - goodwill  |
| 11136 | 700         | 27269      | 3006 SPRG  | 28-Mar-07 | N | PD/S | 15-Dec-14 | 22-Oct-15 | Fired on Safe Release                | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam   |
| 11140 | 700         | 84076      | 270 WIN    | 9-Oct-13  | N | S    | 16-Dec-14 | 16-Dec-14 | Dissatisfied with Service - Firearms | Could Not Duplicate Concern       | 480313 | F | Per Ilion - Repair at n/c  |
| 11142 | 770         | 85646      | 270 WIN    | 28-Nov-12 | N | S    | 16-Dec-14 | 16-Dec-14 | Fired on Bolt Closing                | Could Not Duplicate Concern       | 480293 | F | Call Center issued a refund to customer  |
| 11143 | 700         | not avail. | 2506 REM   | 24-Aug-72 | N | S    | 16-Dec-14 | 16-Dec-14 | Fired With Safe ON                   | Could Not Duplicate Concern       | 479634 | F | Ilion repaired at n/c  |
| 11144 | 700         | N/A        | 7MM RUM    | 25-Jun-02 | N | PI/S | 16-Dec-14 | 23-Jan-15 | Fired on Safe Release                | Altered Adjustments or Components | 486275 | F | Check over completely, repair as needed, and test at no charge                                     |

RAC001208

## Confidential

|       |       |            |            |           |   |         |           |           |   |  |        |   |  |
|-------|-------|------------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|--|
| 11145 | 700   | N/A        | 3006 SPRG  | 5-Sep-79  | N | PD/S    | 16-Dec-14 | 21-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 485415 | F | Check over completely, repair as needed, and test at no charge |
| 11149 | 700   | N/A        | 3006 SPRG  | 17-Oct-69 | N | PD/S    | 16-Dec-14 | 9-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 488780 | F | Check over completely, repair as needed, and test at no charge |
| 11150 | 597   | 26516      | 17 HMR     | 28-Aug-03 | N | PI/PD/S | 16-Dec-14 | 3-Feb-15  | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 488714 | F | Replace with Ramac 70723 in exchange                           |
| 11148 | 597   | 26536      | 17 HMR     | 21-Mar-03 | N | PI/PD/S | 16-Dec-14 | 2-Mar-15  | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 492361 | O | Replace with Ramac 70723 in exchange                           |
| 11147 | 770   | 85633      | 3006 SPRG  | 22-May-07 | Y | PD/S    | 16-Dec-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                         |
| 11153 | 700   | not avail. | 243 WIN    | 12-Apr-72 | N | PD/S    | 17-Dec-14 | 4-Mar-15  | Fired on Safe Release                                 | Altered Adjustments or Components              | 488061 | F | Repair @ n/c - goodwill  |
| 11155 | 597   | 80854      | 22 LR      | 9-Oct-08  | N | PD/S    | 17-Dec-14 | 8-Apr-15  | Unexplained Discharge Safe OFF                        | Other - Unspecified or Undetermined - Firearms | 491724 | F | Replace w/80854 in exchange                                    |
| 11157 | 770   | 85633      | 3006 SPRG  | 9-Apr-13  | Y | PD/S    | 17-Dec-14 | 10-Jul-15 | Fired With Safe ON                                    | Could Not Duplicate Concern                    | 500343 | F | Replace w/85846 in exchange                                    |
| 11156 | 700   | 27361      | 270 WIN    | 16-Jan-06 | N | PD/S    | 17-Dec-14 | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                         |
| 11158 | 700   | not avail. | 6MM REM    | 18-Nov-77 | N | S       | 18-Dec-14 | 18-Dec-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 480673 | F | Per Ilion - Repair at n/c                                      |
| 11159 | 700   | N/A        | 25-06 REM  | 1-Oct-74  | N | S       | 18-Dec-14 | 18-Dec-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 480832 | F | Per Ilion - replace trigger at no charge.                      |
| 11162 | 700   | 84218      | 308 WIN    | 9-May-08  | N | S       | 18-Dec-14 | 18-Dec-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 480758 | F | Per Ilion - Repair at n/c under recall                         |
| 11163 | 700   | not avail. | 243 WIN    | 27-Jan-72 | N | S       | 18-Dec-14 | 18-Dec-14 | Fired on Safe Release                                 | AFT MKT TRIGGER ASSM                           | 480828 | F | Per Ilion - Quote to repair @ discount                         |
| 11181 | 700   | N/A        | 3006 SPRG  | 24-Jun-71 | N | S       | 18-Dec-14 | 26-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 487184 | F | Check over completely, repair as needed, and test at no charge |
| 11161 | 700   | 27009      | 2506 REM   | 7-Feb-13  | N | PI/S    | 18-Dec-14 | 27-Feb-15 | Fired on Safe Release                                 | Altered Adjustments or Components              | 480752 | F | Check over completely, repair as needed, and test at no charge |
| 11179 | 710   | 27425      | 3006 SPRG  | 20-Apr-04 | Y | PD/S    | 18-Dec-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                         |
| 11171 | 710   | 27410      | 3006 SPR   | 23-Mar-05 | Y | S       | 19-Dec-14 | 19-Dec-14 | Fired on Safe Release                                 | Altered Adjustments or Components              | 481310 | F | Per Ilion - Quote to repair @ discount                         |
| 11172 | 700   | not avail. | 300 WIN    | 16-Nov-78 | N | S       | 19-Dec-14 | 19-Dec-14 | Fired on Safe Release                                 | Improper Maintenance                           | 481317 | F | Ilion repaired at n/c  |
| 11173 | Seven | 85953      | 22-250 REM | 20-Aug-10 | N | S       | 19-Dec-14 | 19-Dec-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 481293 | F | Per Ilion- Repair at no charge under recall                    |
| 11174 | 700   | 27361      | 270 WIN    | 27-Jan-12 | N | S       | 19-Dec-14 | 19-Dec-14 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 481192 | F | Per Ilion: Repair at no charge                                 |
| 11175 | 700   | not avail. | 3006 SPR   | 18-Mar-74 | N | S       | 19-Dec-14 | 19-Dec-14 | Delayed Firing - Firearms                             | Improper Maintenance                           | 481309 | F | Per Ilion: Repair at no charge                                 |
| 11176 | 1187  | 83626      | 20 GA      | 20-May-14 | N | S       | 19-Dec-14 | 19-Dec-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 481333 | F | Per Ilion: Repair at no charge                                 |
| 11177 | 700   | 84150      | 243 WIN    | 27-Jan-10 | N | S       | 19-Dec-14 | 19-Dec-14 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 481331 | F | Per Ilion- Repair at no charge under recall                    |
| 11182 | 700   | 27140      | 300 RUM    | 14-Dec-10 | N | PI/S    | 19-Dec-14 | 19-Dec-14 | Fired on Safe Release                                 | Other - Unexamined                             | n/a    | F | Consumer refused to send rifle in for exam                     |
| 11196 | 700   | N/A        | 3006 SPRG  | 25-May-78 | N | S       | 19-Dec-14 | 28-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 488164 | F | Replace trigger assembly,check over and test fire at no charge |

RAC001209

## Confidential

|       |          |            |            |           |          |      |           |           |   |                                   |                             |        |  |                       |
|-------|----------|------------|------------|-----------|----------|------|-----------|-----------|---|-----------------------------------|-----------------------------|--------|--|-----------------------|
| 11197 | 700      | N/A        | 243 WIN    | 1-Jun-76  | N        | S    | 19-Dec-14 | 27-Jan-15 | Fired on Bolt Opening                                 | Could Not Duplicate Concern       | 488032                      | F      | Replace trigger assembly,check over and test fire at no charge                 |                       |
| 11195 | 887      | 82500      | 12 GA      | 26-May-10 | N        | PI/S | 19-Dec-14 | 4-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 488059                      | F      | Check over completely, repair as needed, and test at no charge                 |                       |
| 11180 | 700      | N/A        | 7MM REM MA |           | N        | PI/S | 19-Dec-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a                         | F      | Firearm not returned to Ilion for exam   |                       |
| 11186 | 770      | 85651      | 243 WIN    | 25-Mar-13 | Y        | S    | 22-Dec-14 | 22-Dec-14 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 481497                      | F      | Per Ilion: Repair at no charge   |                       |
| 11187 | XM15-E2S | 90829      | 5.56 MM    | 12-Mar-13 | N        | S    | 22-Dec-14 | 22-Dec-14 | Receiver Damaged                                      | Sent in for Evaluation            | 481375                      | F      | Per Ilion: Repair at no charge   |                       |
| 11188 | 1100     | 82800      | 12 GA      | 30-May-12 | N        | S    | 22-Dec-14 | 22-Dec-14 | Failed to Extract                                     | Sent in for Evaluation            | 481408                      | F      | Per Ilion: Repair at no charge   |                       |
| 11184 | SP10     | 24809      | 10GA       | 3-Jun-99  | Y        | PI/S | 22-Dec-14 | 4-Mar-15  | Fired Out of Battery                                  | Sent in for Evaluation            | 481632                      | F      | Check over & test @ n/c  |                       |
| 11194 | 770      | 85637      | 243 WIN    | 7-Oct-13  | Y        | PI/S | 22-Dec-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a                         | F      | Firearm not returned to Ilion for exam   |                       |
| 11198 | 700      | not avail. | 7MM MAG    | 7-Mar-72  | N        | S    | 23-Dec-14 | 15-Jan-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components | 485289                      | F      | Per Ilion - Repair at n/c-goodwill   |                       |
| 11202 | 700      | not avail. | 7MM RM     | 1-Apr-67  | N        | S    | 26-Dec-14 | 26-Dec-14 | Firing Pin Follows Down                               | AFT MKT TRIGGER ASSM              | 481824                      | F      | Per Ilion: Repair at no charge   |                       |
| 11205 | 7        | 24791      | 300 SAUM   | 26-Sep-02 | N        | S    | 26-Dec-14 | 26-Dec-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components | 481810                      | F      | Per Ilion: Repair at no charge   |                       |
| 11206 | 600      | not avail. | 6MM REM    | 1-May-64  | Y        | S    | 26-Dec-14 | 26-Dec-14 | Fired on Bolt Closing                                 | Improper Maintenance              | 481788                      | F      | Per Ilion - Repair at no charge under recall.                                  |                       |
| 11207 | 700      | not avail. | 6MM REM    | 9-Aug-72  | N        | S    | 26-Dec-14 | 26-Dec-14 | Fired on Bolt Closing                                 | Altered Adjustments or Components | 481828                      | F      | Per Ilion - Replace TA & test @ n/c  |                       |
| 11208 | 700      | not avail. | 3006 SPRG  | 1-Aug-66  | N        | S    | 26-Dec-14 | 26-Dec-14 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 481877                      | F      | Per Ilion: Repair at no charge   |                       |
| 11211 | 770      | 85652      | 270 WIN    | 24-Jun-08 | N        | S    | 29-Dec-14 | 27-Jan-15 | Fired With Safe ON                                    | Could Not Duplicate Concern       | 487896                      | F      | Per Ilion - Replace w/Item# 85652 at n/c                                       |                       |
| 11214 | 700      | 27011      | 270 WIN    | 26-Apr-04 | N        | PD/S | 29-Dec-14 | 28-Jan-15 | Fired on Safe Release                                 | Altered Adjustments or Components | 486986                      | F      | Repair @ n/c - goodwill gesture  |                       |
| 11217 | 600      | not avail. | 35 REM     | 1-Jul-65  | Y        | S    | 29-Dec-14 | 26-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 487640                      | F      | Per Ilion - Repair at n/c-goodwill   |                       |
| 11212 | 700      | not avail. | 270 WIN    | 10-Nov-72 | N        | PD/S | 29-Dec-14 | 25-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 487078                      | F      | Repair @ n/c - goodwill  |                       |
| 11218 | 700      | 26436      | 300 SAUM   | 27-Aug-02 | N        | PD/S | 29-Dec-14 | 23-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 488019                      | F      | Repair @ n/c - goodwill gesture  |                       |
| 11215 | 700      | 26035      | 3006 SPRG  | 30-Jul-01 | N        | PI/S | 29-Dec-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a                         | F      | Firearm not returned to Ilion for exam   |                       |
| 11220 | 710      | 27410      | 3006 SPRG  | 19-May-05 | Y        | PD/S | 30-Dec-14 | 23-Feb-15 | Fired on Bolt Opening                                 | Could Not Duplicate Concern       | 487938                      | F      | Repair @ n/c - goodwill gesture  |                       |
| 11223 | 700      | 84079      | 300 WIN    | MA        | 8-May-13 | N    | S         | 30-Dec-14 | 4-Feb-15  | Fired on Bolt Closing             | Could Not Duplicate Concern | 490509 | F  | Ilion repaired at n/c |
| 11222 | 700      | 27095      | 3006 SPRG  | 2-Mar-12  | N        | PD/S | 30-Dec-14 | 9-Apr-15  | Fired With Safe ON                                    | Could Not Duplicate Concern       | 486364                      | F      | Per Release - Check for \$589.55 & repair rifle @ n/c                          |                       |
| 11224 | 700      | 27097      | 7MM MAG    | 18-Sep-08 | N        | PD/S | 30-Dec-14 | 8-Oct-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 490123                      | F      | Repair rifle @ n/c under XMP recall, Release for Gilliland - Ck for \$2,943.18 |                       |
| 11229 | 700      | not avail. | 7mm Expre  | 25-Sep-79 | N        | S    | 31-Dec-14 | 27-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 487886                      | F      | Ilion repaired at n/c - goodwill   |                       |
| 11226 | 700      | 27476      | 270 WIN    | 27-Jun-02 | N        | S    | 31-Dec-14 | 13-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 493081                      | F      | Ilion repaired at n/c  |                       |
| 11228 | 700      | not avail. | 3006 SPRG  | 19-Jul-72 | N        | S    | 31-Dec-14 | 4-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 490081                      | F      | Ilion repaired at n/c  |                       |
| 11225 | 700      | 85446      | 243 WIN    | 20-May-11 | N        | PD/S | 31-Dec-14 | 22-Oct-15 | Unexplained Discharge - No Mention of Safety Position | Not Examined by Product Service   | n/a                         | F      | Firearm not returned to Ilion for exam   |                       |

RAC001210

## Confidential

|       |         |            |            |           |   |      |           |           |   |  |        |   |   |
|-------|---------|------------|------------|-----------|---|------|-----------|-----------|---|--|--------|---|---|
| 11230 | 700     | 27389      | 300 RUM    | 11-Aug-06 | N | S    | 31-Dec-14 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                    |
| 11233 | 700     | 27474      | 243 WIN    | 7-Apr-03  | N | S    | 2-Jan-15  | 19-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 493689 | F | Ilion repaired at n/c   |
| 11234 | 597     | 26536      | 17 HMR     | 1-Apr-03  | N | PD/S | 2-Jan-15  | 19-Mar-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 496641 | F | Replace with Ramac 70723 in exchange                                      |
| 11232 | 700     | 29725      | 338 WIN    | 8-Oct-92  | N | PI/S | 2-Jan-15  | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                    |
| 11237 | 7       | 24780      | 223 REM    | 22-Aug-83 | N | S    | 5-Jan-15  | 5-Jan-15  | Fired on Bolt Closing                                 | Improper Maintenance                           | 483051 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 11238 | 770     | 85630      | 243 WIN    | 19-Sep-12 | N | S    | 5-Jan-15  | 5-Jan-15  | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 483314 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 11240 | 870     | 25133      | 12 GA SM   | 1-Oct-12  | N | S    | 5-Jan-15  | 5-Jan-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 483318 | F | Per Ilion: Repair at no charge  |
| 11241 | 700     | not avail. | 270 WIN    | 1-Jan-80  | N | S    | 5-Jan-15  | 5-Jan-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 483322 | F | Per Ilion: Repair at no charge  |
| 11242 | 721     | not avail. | 270WIN     | 1-Jan-67  | Y | S    | 5-Jan-15  | 5-Jan-15  | Fired on Safe Release                                 | Improper Maintenance                           | 483212 | F | Per Ilion: Repair at no charge  |
| 11255 | 770     | 85633      | 3006 SPRG  | 10-Jul-08 | N | S    | 5-Jan-15  | 26-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 487760 | F | Per Ilion, replace trigger assembly,check over and test fire at no charge |
| 11245 | 700     | not avail. | 3006 SPR   | 9-May-73  | Y | S    | 6-Jan-15  | 6-Jan-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 483640 | F | Per Ilion- Replace TA under BLP   |
| 11246 | 721     | not avail. | 3006SPR    | 1-Jan-68  | Y | S    | 6-Jan-15  | 6-Jan-15  | Fired on Safe Release                                 | Improper Maintenance                           | 482812 | F | Per Ilion: Repair at no charge  |
| 11254 | 700     | 25803      | 7MM REM    | 6-Oct-86  | N | S    | 6-Jan-15  | 6-Jan-15  | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 483675 | F | Per Ilion: Repair at no charge  |
| 11256 | 541     | not avail. | 22 RF      | 13-Nov-73 | Y | S    | 6-Jan-15  | 6-Jan-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 482336 | F | Per Ilion: Repair at no charge  |
| 11260 | 700     | 26287      | 3006 SPRG  | 29-Jun-04 | N | S    | 6-Jan-15  | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                    |
| 11262 | 700     | not avail. | 3006 SPRG  | 18-Jul-75 | N | S    | 6-Jan-15  | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                    |
| 11249 | 700     | 20000      |            |           | N | S    | 6-Jan-15  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                    |
| 11261 | 887     | 82500      | 12 GA      | 21-Oct-09 | N | S    | 6-Jan-15  | 22-Oct-15 | Unexplained Discharge - No Mention of Safety Position | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                    |
| 11264 | 700     | 85591      | 7MM08 REM  | 24-Jun-11 | N | S    | 7-Jan-15  | 7-Jan-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 483751 | F | Per Ilion- Repair at no charge under recall.                              |
| 11266 | SPR 310 | 89564      | 12 GA      | 3-Sep-07  | Y | S    | 7-Jan-15  | 7-Jan-15  | Unexplained Discharge Safe OFF                        | Could Not Duplicate Concern                    | 483741 | F | Per Customer- Return as received  |
| 11275 | 700     | not avail. | 22-250 REM | 12-Jan-79 | N | PD/S | 7-Jan-15  | 7-Jan-15  | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Gun not returned to Ilion for exam  |
| 11271 | 700     | not avail. | 3006 SPR   | 13-Jul-73 | N | S    | 8-Jan-15  | 8-Jan-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 484158 | F | Per Ilion: Repair at no charge  |
| 11273 | 770     | 85635      | MA         | 3-Nov-10  | Y | S    | 8-Jan-15  | 8-Jan-15  | Fired With Safe ON                                    | Altered Adjustments or Components              | 483967 | F | Per Ilion: Repair at no charge  |
| 11274 | 722     | not avail. | 243 WIN    | 1-Jul-61  | Y | S    | 8-Jan-15  | 8-Jan-15  | Fired on Bolt Closing                                 | Improper Maintenance                           | 483960 | F | Per Ilion- Replace TA under BLP   |
| 11276 | 770     | 85649      | 243 WIN    | 21-Nov-12 | N | S    | 8-Jan-15  | 3-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 489177 | F | Ilion repaired at n/c   |

RAC001211

## Confidential

|       |             |            |            |           |   |         |           |           |   |                                   |        |   |  |
|-------|-------------|------------|------------|-----------|---|---------|-----------|-----------|---|-----------------------------------|--------|---|--|
| 11278 | 700         | 27389      | 300 RUM    | 9-Aug-06  | N | PD/S    | 8-Jan-15  | 24-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 490807 | F | Repair @ n/c   |
| 11279 | 700         | 25771      | 270 WIN    | 19-Nov-85 | N | S       | 9-Jan-15  | 9-Jan-15  | Safety not working properly                           | Sent in for Evaluation            | 484238 | F | Per Ilion: Repair at no charge   |
| 11280 | 870         | not avail. | 12 GA      | 6-Feb-88  | N | S       | 9-Jan-15  | 9-Jan-15  | Broken Part   | Sent in for Evaluation            | 484221 | F | Per Ilion: Repair at no charge   |
| 11283 | 700         | 27337      | 3006 SPRG  | 7-Feb-07  | N | S       | 9-Jan-15  | 29-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 488846 | F | Ilion repaired at n/c  |
| 11286 | 700         | not avail. | 3006 SPRG  | 11-Sep-75 | N | S       | 9-Jan-15  | 29-Jan-15 | Fired on Bolt Opening                                 | Could Not Duplicate Concern       | 488906 | F | Ilion repaired at n/c  |
| 11303 | 700         | N/A        | 25-06 REM  | 23-Mar-81 | N | PD/S    | 9-Jan-15  | 12-Feb-15 | Fired on Safe Release                                 | Improper Maintenance              | 491859 | F | Check over completely, repair as needed, and test at no charge             |
| 11302 | 700         | N/A        | 3006 SPRG  | 8-Jun-78  | N | PD/S    | 9-Jan-15  | 26-May-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 499481 | F | Check over completely, repair as needed, and test at no charge             |
| 11292 | 700         | N/A        | 22-250 REM | 12-Jul-77 | N | PD/S    | 9-Jan-15  | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11291 | 700         | 25767      | 243 WIN    | 13-Nov-86 | N | PD/S    | 9-Jan-15  | 22-Oct-15 | Unexplained Discharge - No Mention of Safety Position | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11293 | 700         | not avail. | 3006 SPR   | 24-Mar-75 | N | S       | 12-Jan-15 | 12-Jan-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components | 484779 | F | Per Ilion- Replace TA under BLP  |
| 11294 | 700         | 27476      | 270 WIN    | 16-May-96 | N | S       | 12-Jan-15 | 12-Jan-15 | Delayed Firing - Firearms                             | Improper Maintenance              | 484774 | F | Per Ilion: Repair at no charge   |
| 11295 | 788         | not avail. | 243 WIN    | 20-Aug-81 | Y | S       | 12-Jan-15 | 12-Jan-15 | Fired on Safe Release                                 | Improper Maintenance              | 484506 | F | Per Ilion: Repair at no charge   |
| 11296 | 700         | 26253      | 270 WIN    | 23-Mar-01 | N | S       | 12-Jan-15 | 12-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 484491 | F | Per Ilion: Repair at no charge   |
| 11297 | 721         | not avail. | 270WIN     | 1-Apr-71  | Y | S       | 12-Jan-15 | 12-Jan-15 | Fired on Safe Release                                 | Sent in for Evaluation            | 484514 | F | Per Ilion- Replace TA under BLP  |
| 11298 | 700         | 25791      | 270 WIN    | 30-Oct-95 | N | S       | 12-Jan-15 | 12-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 484534 | F | Per Ilion: Repair at no charge   |
| 11299 | 660         | not avail. | 243 WIN    | 1-Feb-68  | Y | S       | 12-Jan-15 | 12-Jan-15 | Fired on Safe Release                                 | Improper Maintenance              | 484511 | F | Per Ilion- Replace TA under BLP  |
| 11306 | 700         | N/A        | 3006 SPRG  | 29-May-74 | N | PD/S    | 12-Jan-15 | 12-Feb-15 | Fired on Bolt Opening                                 | Could Not Duplicate Concern       | 492377 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11300 | 700         | not avail. | 3006 SPRG  | 17-Jun-81 | N | PI/PD/S | 12-Jan-15 | 8-Apr-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 491734 | F | Repair @ n/c - goodwill  |
| 11308 | 700         | not avail. | 243 WIN    | 3-Nov-83  | N | S       | 13-Jan-15 | 13-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 484800 | F | Per Ilion: Repair at no charge   |
| 11309 | EXCELL AUTO | 72350      | 12GA VT    | 26-May-10 | N | S       | 13-Jan-15 | 13-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation            | 484861 | F | Per Ilion- Replace under warranty with Ramac R72350                        |
| 11310 | 700         | 25803      | 7M REM MAG | 26-Oct-89 | N | S       | 13-Jan-15 | 13-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 484796 | F | Per Ilion: Repair at no charge   |
| 11311 | 700         | not avail. | 270 WIN    | 24-Jun-80 | N | S       | 13-Jan-15 | 13-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 484817 | F | Per Ilion- Replace TA under BLP  |
| 11312 | 700         | 85577      | 300 WIN MA | 27-May-10 | N | S       | 13-Jan-15 | 13-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 484971 | F | Per Ilion- Repair at no charge under recall.                               |
| 11313 | R15         | 60018      | 5.56MM     | 9-Jan-14  | N | S       | 13-Jan-15 | 13-Jan-15 | Went Automatic  | Could Not Duplicate Concern       | 484844 | F | Per Ilion: Repair at no charge   |

RAC001212

## Confidential

|       |       |            |            |           |   |      |           |           |   |  |        |   |  |
|-------|-------|------------|------------|-----------|---|------|-----------|-----------|---|--|--------|---|--|
| 11315 | 700   | 25815      | 7MM REM MA | 20-Apr-91 | N | PI/S | 13-Jan-15 | 19-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 492563 | F | Check over completely, repair as needed, and test at no charge             |
| 11317 | 700   | 26285      | 7MM-08     | 31-Jul-02 | N | S    | 14-Jan-15 | 12-Feb-15 | Dissatisfied with Service - Firearms                  | Sent in for Evaluation                         | 493039 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11319 | 700   | 26039      | 7MM REM MA | 22-Jul-00 | N | S    | 14-Jan-15 | 9-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 490763 | F | Per Ilion, check over completely, repair as needed, and test at no charge. |
| 11320 | 700   | not avail. | 3006 SPRG  | 14-Feb-76 | N | S    | 14-Jan-15 | 5-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 490501 | F | Ilion repaired at n/c  |
| 11322 | 700   | 25834      | 300 RUM    | 17-Aug-00 | N | S    | 15-Jan-15 | 15-Jan-15 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 485392 | F | Per Ilion: Repair at no charge   |
| 11324 | 700   | not avail. | 308 WIN    | 17-Feb-83 | N | S    | 15-Jan-15 | 15-Jan-15 | Fired on Safe Release                                 | Improper Maintenance                           | 485404 | F | Per Ilion: Repair at no charge   |
| 11326 | 700   | not avail. | 243WIN     | 30-Jun-75 | N | S    | 15-Jan-15 | 15-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 485239 | F | Per Ilion- Replace TA under BLP  |
| 11327 | 700   | not avail. | 3006SPR    | 23-May-80 | N | S    | 15-Jan-15 | 15-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 485291 | F | Per Ilion- Replace TA under BLP  |
| 11328 | 700   | 27011      | 270 WIN    | 14-May-04 | N | S    | 15-Jan-15 | 15-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 485230 | F | Per Ilion: Repair at no charge   |
| 11329 | 887   | 82540      | 12 GA      | 24-Feb-14 | N | S    | 15-Jan-15 | 15-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 485293 | F | Per Ilion- Repair under 887 recall   |
| 11330 | 700   | 84216      | 22-250REM  | 24-May-13 | N | S    | 15-Jan-15 | 15-Jan-15 | Fired on Bolt Opening                                 | Could Not Duplicate Concern                    | 485312 | F | Per Ilion: Repair at no charge   |
| 11331 | 770   | 85636      | 300 WIN MA | 15-Aug-14 | Y | S    | 15-Jan-15 | 15-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 485237 | F | Per Ilion- Replace under warranty with Ramac #85636                        |
| 11337 | 700   | N/A        | 243 WIN    | 1-Jul-65  | N | S    | 15-Jan-15 | 16-Jan-15 | Fired on Safe Release                                 | Improper Maintenance                           | 485655 | F | Per Ilion, replace trigger and test at no charge.                          |
| 11334 | 700   | 25773      | 3006 SPRG  | 29-Jun-94 | N | S    | 15-Jan-15 | 9-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 490761 | F | Per Ilion: Repair at no charge   |
| 11335 | 700   | not avail. | 3006 SPR   | 29-May-75 | N | S    | 16-Jan-15 | 16-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 485529 | F | Per Ilion- Replace TA under BLP  |
| 11336 | 700   | N/A        | 3006 SPR   | 20-Mar-69 | N | S    | 16-Jan-15 | 16-Jan-15 | Other - Firearms                                      | Sent in for Evaluation                         | 485567 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11338 | 700   | not avail. | 3006 SPRG  |           | N | S    | 16-Jan-15 | 16-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 485525 | F | Repair @ n/c - goodwill gesture  |
| 11339 | 700   | N/A        | 25-06 REM  | 6-May-70  | N | S    | 16-Jan-15 | 16-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 485569 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11340 | 700   | N/A        | 7MM REMMAG | 31-Oct-78 | N | S    | 16-Jan-15 | 16-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 485474 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11341 | SEVEN | 27297      | 308 WIN    | 27-Mar-07 | N | S    | 16-Jan-15 | 16-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 485649 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11345 | 700   | N/A        | 222 REM    | 4-Mar-74  | N | PD/S | 16-Jan-15 | 16-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 490751 | F | Check over completely, repair as needed, and test at no charge             |
| 11347 | 597   | 26536      | 17 HMR     | 29-Jan-03 | N | PD/S | 16-Jan-15 | 11-Feb-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 492056 | F | Converting to 22 WMR as requested by customer                              |

RAC001213

Confidential

|       |           |            |                    |           |   |         |           |           |   |  |        |   |  |
|-------|-----------|------------|--------------------|-----------|---|---------|-----------|-----------|---|--|--------|---|--|
| 11349 | 700       | not avail. | 270 WIN            | 24-May-72 | N | PD/S    | 16-Jan-15 | 9-Feb-15  | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 491618 | F | Ilion repaired at n/c - goodwill   |
| 11351 | 700       | not avail. | 3006 SPRG          | 13-Jul-73 | N | S       | 16-Jan-15 | 10-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 490800 | F | Per Ilion- Replace TA under BLP  |
| 11352 | 700       | not avail. | 3006 SPRG          | 23-Oct-87 | N | S       | 16-Jan-15 | 12-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 493030 | F | Per Ilion: Replace TA at no charge   |
| 11350 | 700       | 27093      | 243 WIN 22-250 REM | 11-Jun-08 | N | S       | 16-Jan-15 | 2-Mar-15  | Fired on Safe Release                                 | Sent in for Evaluation                         | 494556 | F | Replace with Ramac 27355 in exchange                                       |
| 11346 | 700       | 25854      | REM                | 23-Apr-86 | N | PD/S    | 16-Jan-15 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11344 | 700       | not avail. | 3006 SPRG          |           | N | PD/S    | 16-Jan-15 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11348 | 700       | 27299      | 25-06 REM          | 20-May-09 | N | PI/PD/S | 16-Jan-15 | *         | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 491875 | F |  |
| 11362 | 887       | 82500      | 12 GA              | 16-Jul-14 | N | S       | 19-Jan-15 | 25-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 493967 | F | Refunded purchase price.   |
| 11363 | 597       | 26516      | 17 HMR             | 30-Sep-03 | N | PI/PD/S | 19-Jan-15 | 18-Feb-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 492132 | F | Sending \$200 coupon in exchange for gun.                                  |
| 11353 | 700       | 27476      | 270 WIN            | 18-Mar-04 | N | S       | 20-Jan-15 | 20-Jan-15 | Fired on Safe Release                                 | Improper Maintenance                           | 485042 | F | Per Ilion: Repair at no charge   |
| 11355 | Seven     | not avail. | 223 REM            | 8-Mar-88  | N | S       | 20-Jan-15 | 20-Jan-15 | Safety not working properly                           | Altered Adjustments or Components              | 486204 | F | Per Ilion: Repair at no charge   |
| 11358 | 700       | 27387      | MAG                | 29-Nov-05 | N | S       | 20-Jan-15 | 20-Jan-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 486103 | F | Per Ilion: Repair at no charge   |
| 11359 | 700       | not avail. | 3006 SPR           | 4-Mar-80  | N | S       | 20-Jan-15 | 20-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 485875 | F | Per Ilion- Replace TA under BLP  |
| 11360 | 700       | not avail. | 25-06REM           | 4-May-70  | N | S       | 20-Jan-15 | 20-Jan-15 | Other - Firearms                                      | Sent in for Evaluation                         | 486145 | F | Per Ilion- Replace TA under BLP  |
| 11361 | 770       | 85633      | 3006 SPR           | 3-Dec-13  | Y | S       | 20-Jan-15 | 20-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 485821 | F | Per Ilion: Repair at no charge   |
| 11364 | 700       | 20000      | 7MM MAG            |           | N | PD/S    | 20-Jan-15 | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11366 | 1911 R1   | 96323      | 45 ACP             | 19-Apr-13 | N | S       | 21-Jan-15 | 21-Jan-15 | Fired With Safe ON                                    | Sent in for Evaluation                         | 485982 | F | Per Ilion: Repair at no charge   |
| 11367 | VERSA MAX | 81048      | 12 GA              | 27-Jan-14 | N | S       | 21-Jan-15 | 21-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 486404 | F | Per Ilion: Replace with Ramac #81048                                       |
| 11368 | 870       | 81136      | 12 GA              | 5-Aug-13  | N | S       | 21-Jan-15 | 21-Jan-15 | Fails to Eject  | Could Not Duplicate Concern                    | 486362 | F | Per Ilion: Repair at no charge   |
| 11370 | 700       | 25801      | 17 REM             | 13-Feb-02 | N | S       | 21-Jan-15 | 21-Jan-15 | Fired on Safe Release                                 | Altered Adjustments or Components              | 486245 | F | Per Ilion: Repair at no charge   |
| 11371 | 783       | 85837      | 308 WIN            | 23-Sep-13 | N | S       | 21-Jan-15 | 21-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 486695 | F | Per Ilion: Repair at no charge   |
| 11372 | 700       | not avail. | 270 WIN            | 23-Feb-72 | N | S       | 21-Jan-15 | 21-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 486690 | F | Per Ilion: Repair at no charge   |
| 11373 | 700       | not avail. | 3006 SPR           | 1-Jun-64  | N | S       | 21-Jan-15 | 21-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 486248 | F | Per Ilion- Replace TA under BLP  |
| 11374 | 700       | not avail. | 7MM REM MA         | 13-Sep-77 | N | S       | 21-Jan-15 | 21-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 486232 | F | Per Ilion- Replace TA under BLP  |
| 11375 | 700       | not avail. | 6MM REM            | 19-Apr-80 | N | S       | 21-Jan-15 | 21-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 486691 | F | Per Ilion- Replace TA under BLP  |
| 11391 | 597       | 26536      | 17 HMR             | 19-Nov-02 | N | PD/S    | 21-Jan-15 | 25-Feb-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 493023 | F | Replace with Ramac 70723 in exchange                                       |
| 11388 | 700       | N/A        | 270 WIN            | 22-Jul-78 | N | PD/S    | 21-Jan-15 | 24-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 498765 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11384 | 700       | N/A        | 3006 SPRG          | 1-Apr-71  | N | PD/S    | 21-Jan-15 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |

RAC001214

Confidential

|       |           |            |            |           |   |   |           |           |   |                                   |        |   |   |
|-------|-----------|------------|------------|-----------|---|---|-----------|-----------|---|-----------------------------------|--------|---|---|
| 11377 | DPMS A-15 | not avail. | 5.56MM     | 1-Jan-14  | N | S | 22-Jan-15 | 22-Jan-15 | Unknown Claim   | Sent in for Evaluation            | 486660 | F | Per Iion: Repair at no charge   |
| 11378 | 700       | not avail. | 270 WIN    | 6-Apr-72  | N | S | 22-Jan-15 | 22-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 486373 | F | Per Iion- Replace TA under BLP  |
| 11379 | 700       | 85619      | 270 WIN    | 7-Mar-13  | N | S | 22-Jan-15 | 22-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 486639 | F | Per Iion- Repair at no charge under recall.                               |
| 11380 | 700       | not avail. | 3006 SPR   | 31-Oct-73 | N | S | 22-Jan-15 | 22-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 486382 | F | Per Iion- Replace TA under BLP  |
| 11381 | 700       | not avail. | 22-250REM  | 28-Feb-73 | N | S | 22-Jan-15 | 22-Jan-15 | Fired With Safe ON                                    | Altered Adjustments or Components | 486431 | F | Per Iion- Replace TA under BLP  |
| 11382 | 700       | 27480      | 7MM REM MA | 31-Oct-96 | N | S | 22-Jan-15 | 22-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 486351 | F | Per Iion: Repair at no charge   |
| 11385 | 770       | 85633      | 3006 SPR   | 27-Apr-12 | N | S | 22-Jan-15 | 22-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 486380 | F | Per Iion, check over completely, repair as needed, and test at no charge. |
| 11386 | 710       | 27410      | 3006 SPR   | 20-Sep-06 | Y | S | 22-Jan-15 | 22-Jan-15 | Fail to Fire  | Could Not Duplicate Concern       | 486738 | F | Check over completely, repair as needed, and test at no charge            |
| 11389 | 700       | 25789      | 2506 REM   | 20-Feb-92 | N | S | 22-Jan-15 | 22-Jan-15 | Delayed Firing - Firearms                             | Could Not Duplicate Concern       | 486735 | F | Per Iion, replace trigger assembly, check over and test fire at no charge |
| 11390 | 700       | 27165      | 270 WIN    | 17-Sep-07 | N | S | 22-Jan-15 | 22-Jan-15 | Fired With Safe ON                                    | Could Not Duplicate Concern       | 486795 | F | Per Iion- Repair at no charge under recall.                               |
| 11393 | 700       | 25803      | 7MM REM MA | 26-Feb-86 | N | S | 23-Jan-15 | 23-Jan-15 | Fired on Safe Release                                 | Altered Adjustments or Components | 486996 | F | Per Iion: Repair at no charge   |
| 11394 | 788       | not avail. | 243 WIN    | 26-Mar-81 | Y | S | 23-Jan-15 | 23-Jan-15 | Fired on Safe Release                                 | Improper Maintenance              | 486819 | F | Per Iion- Repair at 1/2 cost good will gesture                            |
| 11395 | 700       | not avail. | 6MM REM    | 4-Dec-75  | N | S | 23-Jan-15 | 23-Jan-15 | Other - Firearms                                      | Could Not Duplicate Concern       | 486994 | F | Per Iion- Replace TA under BLP  |
| 11396 | 700       | 27474      | 243 WIN    | 6-Mar-98  | N | S | 23-Jan-15 | 23-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 487066 | F | Per Iion: Repair at no charge   |
| 11397 | 700       | not avail. | 270 WIN    | 10-Oct-80 | N | S | 23-Jan-15 | 23-Jan-15 | Fired on Safe Release                                 | Improper Maintenance              | 487061 | F | Per Iion- Replace TA under BLP  |
| 11399 | 700       | 25845      | 260 REM    | 10-May-01 | N | S | 23-Jan-15 | 23-Jan-15 | Barrel Damaged/Bulged (Other than Burst)              | Sent in for Evaluation            | 487072 | F | Per Iion: Repair at no charge   |
| 11400 | 700       | 25709      | 308 WIN    | 28-Feb-07 | N | S | 23-Jan-15 | 23-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 487080 | F | Per Iion: Repair at no charge   |
| 11401 | 700       | 25709      | 308 WIN    | 14-Jan-03 | N | S | 23-Jan-15 | 23-Jan-15 | Fired With Safe ON                                    | Could Not Duplicate Concern       | 487081 | F | Per Iion: Repair at no charge   |
| 11403 | 700       | 25711      | 308 WIN    | 9-Nov-00  | N | S | 23-Jan-15 | 23-Jan-15 | Fired With Safe ON                                    | Could Not Duplicate Concern       | 487064 | F | Per Iion: Repair at no charge   |
| 11405 | CARBON 15 | 90872      | 5.56MM     | 3-Dec-13  | N | S | 25-Jan-15 | 25-Jan-15 | Went Automatic  | Could Not Duplicate Concern       | 487531 | F | Per Iion: Repair at no charge   |
| 11406 | 770       | 85633      | 3006 SPR   | 8-Sep-10  | N | S | 25-Jan-15 | 25-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 487156 | F | Per Iion: Repair at no charge   |
| 11410 | 700       | 25632      | 280 REM    | 14-May-90 | N | S | 26-Jan-15 | 26-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 487167 | F | Per Iion: Repair at no charge   |
| 11412 | 700       | not avail. | 3006 SPR   | 27-Aug-82 | N | S | 26-Jan-15 | 26-Jan-15 | Delayed Firing - Firearms                             | Could Not Duplicate Concern       | 487565 | F | Per Iion: Repair at no charge   |
| 11413 | 700       | 25709      | 308 WIN    | 5-Dec-01  | N | S | 26-Jan-15 | 26-Jan-15 | Fired on Safe Release                                 | Altered Adjustments or Components | 487457 | F | Per Iion: Repair at no charge   |
| 11414 | 700       | not avail. | 3006 SPR   | 7-Dec-70  | N | S | 26-Jan-15 | 26-Jan-15 | Fired on Safe Release                                 | Altered Adjustments or Components | 487456 | F | Per Iion- Replace TA under BLP  |
| 11415 | SEVEN     | 29543      | 7MM REM SA | 3-Feb-03  | N | S | 26-Jan-15 | 26-Jan-15 | Fired on Safe Release                                 | Improper Maintenance              | 487642 | F | Per Iion: Repair at no charge   |
| 11417 | 700       | 85373      | 270 WIN    | 19-Jan-10 | N | S | 26-Jan-15 | 26-Jan-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components | 487503 | F | Per Iion: Repair at no charge   |
| 11419 | 700       | not avail. | 3006 SPR   | 9-Apr-75  | N | S | 26-Jan-15 | 26-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 487639 | F | Per Iion- Replace TA under BLP  |

RAC001215

Confidential

|       |       |            |            |           |   |      |           |           |   |  |        |   |  |
|-------|-------|------------|------------|-----------|---|------|-----------|-----------|---|--|--------|---|--|
| 11424 | 700   | 25767      | 243 WIN    | 10-Aug-95 | N | S    | 26-Jan-15 | 20-Mar-15 | Fired on Bolt Closing                                 | Other - Unspecified or Undetermined - Firearms | 495879 | F | Ilion replaced trigger assemb.<br>@ n/c                                    |
| 11426 | 700   | N/A        | 3006 SPR   | 21-Sep-71 | N | S    | 27-Jan-15 | 27-Jan-15 | Unexplained Discharge - No                            | Sent in for Evaluation                         | 487644 | F | Per Ilion, check over completely, repair as needed,                        |
| 11427 | 600   | not avail. | 6MM REM    | 1-Mar-67  | Y | S    | 27-Jan-15 | 27-Jan-15 | Fired on Safe Release                                 | Altered Adjustments or Components              | 487929 | F | Per Ilion: Repair at no charge   |
| 11429 | 700   | 27478      | 3006 SPR   | 5-Feb-01  | N | S    | 27-Jan-15 | 27-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 487974 | F | Per Ilion- Repair at 1/2 cost<br>good will gesture                         |
| 11430 | 887   | 82500      | 12 GA      | 23-Jun-14 | N | S    | 27-Jan-15 | 27-Jan-15 | Fired on Bolt Closing                                 | Sent in for Evaluation                         | 487691 | F | Per Ilion- Repair at no charge<br>under recall.                            |
| 11428 | 700   | not avail. | 7MM REM MA | 26-Oct-78 | N | PD/S | 27-Jan-15 | 2-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 487651 | F | Repair @ n/c - goodwill gesture  |
| 11439 | 700   | not avail. | 243 WIN    | 13-Dec-75 | N | PD/S | 27-Jan-15 | 8-Apr-15  | Fired on Safe Release                                 | Improper Maintenance                           | 492392 | F | Repair @ n/c - goodwill  |
| 11436 | 700   | N/A        | 3006 SPRG  | 2-Jun-71  | N | PI/S | 27-Jan-15 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11443 | 870   | 25133      | 12 GA SMAG | 16-Aug-13 | N | S    | 28-Jan-15 | 28-Jan-15 | Action works hard                                     | Fired from Contact with Foreign Object         | 488036 | F | Per Ilion: Repair at no charge<br>Per Ilion- Replace TA under BLP          |
| 11444 | 700   | not avail. | 243 WIN    | 18-Sep-81 | N | S    | 28-Jan-15 | 28-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 488013 | F | Per Ilion- Replace TA under BLP  |
| 11446 | 700   | not avail. | 243 WIN    | 1-May-68  | N | S    | 28-Jan-15 | 28-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 488123 | F | Per Ilion - Repair at n/c - goodwill                                       |
| 11447 | 700   | 25935      | 300 WIN MA | 30-Nov-99 | N | S    | 28-Jan-15 | 28-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 488104 | F | Per Ilion: Repair at no charge   |
| 11448 | 700   | not avail. | 3006 SPR   | 30-Sep-88 | N | S    | 28-Jan-15 | 28-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 488077 | F | Per Ilion- Replace TA under BLP  |
| 11449 | 700   | not avail. | 25-06 REM  | 12-Apr-76 | N | S    | 28-Jan-15 | 28-Jan-15 | Fired on Safe Release                                 | Altered Adjustments or Components              | 488092 | F | Per Ilion: Repair at no charge<br>BLP                                      |
| 11453 | 700   | not avail. | 25-06 REM  | 18-May-70 | N | S    | 28-Jan-15 | 28-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 488242 | F | Per Ilion- Replace TA under BLP  |
| 11454 | 700   | 25803      | 7MM REM MA | 12-Nov-03 | N | S    | 28-Jan-15 | 28-Jan-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 488361 | F | Per Ilion: Repair at no charge   |
| 11456 | 700   | not avail. | 7MM REM MA | 1-Nov-68  | N | S    | 28-Jan-15 | 28-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 488234 | F | Per Ilion: Repair at no charge   |
| 11457 | 700   | not avail. | 7MM MAG    |           | N | S    | 28-Jan-15 | 28-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 488277 | F | Per Ilion- Replace TA under BLP  |
| 11459 | 770   | 85666      | 308 WIN    | 14-May-13 | N | S    | 28-Jan-15 | 28-Jan-15 | Delayed Firing - Firearms                             | Sent in for Evaluation                         | 488389 | F | Per Ilion: Repair at no charge   |
| 11460 | 700   | N/A        | 3006 SPR   | 10-Mar-76 | N | S    | 28-Jan-15 | 28-Jan-15 | Fired on Bolt Opening                                 | Altered Adjustments or Components              | 488279 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11455 | 700   | not avail. |            | 9-May-74  | N | PD/S | 28-Jan-15 | 22-Oct-15 | Fired on Bolt Opening                                 | Not Examined by Product Service                | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11463 | SEVEN | 24786      | REM        | 6-Nov-98  | N | S    | 29-Jan-15 | 29-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 488637 | F | Per Ilion: Repair at no charge   |
| 11465 | 700   | not avail. | 3006 SPR   | 1-Oct-74  | N | S    | 29-Jan-15 | 29-Jan-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 488720 | F | Per Ilion- Replace TA under BLP  |
| 11466 | 700   | not avail. | 3006 SPR   | 1-Sep-78  | N | S    | 29-Jan-15 | 29-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 488683 | F | Per Ilion- Replace TA under BLP  |
| 11467 | 700   | 25846      | 300 WIN MA | 23-Jun-83 | N | S    | 29-Jan-15 | 29-Jan-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 488593 | F | Per Ilion: Repair at no charge   |
| 11469 | 725   | not avail. | 222 REM    | 1-Feb-61  | Y | S    | 29-Jan-15 | 29-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 488807 | F | Per Ilion- Repair at 1/2 cost  |
| 11470 | 700   | 26342      | 7MM-08 REM | 26-Feb-01 | N | S    | 29-Jan-15 | 29-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 488912 | F | Per Ilion: Repair at no charge<br>Per Ilion- Replace TA under BLP          |
| 11471 | 700   | not avail. | 3006 SPR   | 3-Mar-71  | N | S    | 29-Jan-15 | 29-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 488781 | F |  |

RAC001216

## Confidential

|       |     |            |            |           |   |         |           |           |   |                                   |        |   |   |
|-------|-----|------------|------------|-----------|---|---------|-----------|-----------|---|-----------------------------------|--------|---|---|
| 11472 | 700 | not avail. | 3006 SPR   | 14-Jun-79 | N | S       | 29-Jan-15 | 29-Jan-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 488777 | F | Per Ilion- Replace TA under BLP                                 |
| 11473 | 700 | not avail. | 3006 SPR   | 1-Jan-68  | N | S       | 29-Jan-15 | 29-Jan-15 | Fired on Safe Release                                 | Improper Maintenance              | 488938 | F | Per Ilion- Replace TA under BLP                                 |
| 11474 | 700 | 27009      | 25-06 REM  | 18-Nov-04 | N | PD/S    | 29-Jan-15 | 16-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 493880 | F | Repair @ n/c - goodwill gesture                                 |
| 11475 | 700 | 27136      | 308 WIN    | 29-Mar-11 | N | S       | 30-Jan-15 | 3-Feb-15  | Fired on Safe Release                                 | Other - Unexamined                | n/a    | F | Dealer offered to replace the trigger for the consumer          |
| 11480 | 700 | N/A        | 22-250 REM | 20-Mar-78 | N | PD/S    | 30-Jan-15 | 11-Mar-15 | Fired on Bolt Opening                                 | Improper Maintenance              | 493900 | F | Replace trigger assembly, check over and test fire at no charge |
| 11481 | 700 | 84203      | 308 WIN    | 18-Jun-12 | N | PI/PD/S | 2-Feb-15  | 22-Oct-15 | Unexplained Discharge - No Mention of Safety Position | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam                          |
| 11482 | 700 | 27095      | 3006 SPR   | 8-Jan-13  | N | S       | 3-Feb-15  | 3-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 489367 | F | Per Ilion: Repair at no charge                                  |
| 11483 | 770 | 85633      | 3006 SPR   | 8-Oct-08  | Y | S       | 3-Feb-15  | 3-Feb-15  | Fired on Bolt Closing                                 | Altered Adjustments or Components | 489363 | F | Per Ilion: Repair at no charge                                  |
| 11486 | 700 | not avail. | 243 WIN    | 19-Jun-75 | N | S       | 3-Feb-15  | 3-Feb-15  | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation            | 489102 | F | Per Ilion- Replace TA under BLP                                 |
| 11487 | 700 | 84100      | 280 REM    | 12-Mar-07 | N | S       | 3-Feb-15  | 3-Feb-15  | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components | 489037 | F | Per Ilion- Repair at no charge under recall.                    |
| 11488 | 700 | not avail. | 3006 SPR   | 13-Sep-79 | N | S       | 3-Feb-15  | 3-Feb-15  | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation            | 489157 | F | Per Ilion- Replace TA under BLP                                 |
| 11490 | 700 | not avail. | 7MM REM MA | 1-Sep-84  | N | S       | 3-Feb-15  | 3-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 489149 | F | Per Ilion- Replace TA under BLP                                 |
| 11492 | 700 | 25773      | 3006 SPR   | 12-Oct-89 | N | S       | 3-Feb-15  | 3-Feb-15  | Fired on Safe Release                                 | Altered Adjustments or Components | 488954 | F | Per Ilion: Repair at no charge                                  |
| 11493 | 600 | not avail. | 308 WIN    | 1-Jul-65  | Y | S       | 3-Feb-15  | 3-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 489370 | F | Per Ilion- Replace TA under BLP                                 |
| 11495 | 700 | 29679      | 7MM REM MA | 17-Jul-96 | N | S       | 3-Feb-15  | 3-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 489362 | F | Per Ilion: Repair at no charge                                  |
| 11496 | 700 | not avail. | 3006 SPR   | 2-May-77  | N | S       | 3-Feb-15  | 3-Feb-15  | Fired on Bolt Closing                                 | Altered Adjustments or Components | 489361 | F | Per Ilion- Replace TA under BLP                                 |
| 11497 | 700 | 25813      | 3006 SPR   | 25-Aug-89 | N | S       | 3-Feb-15  | 3-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 489360 | F | Per Ilion: Repair at no charge                                  |
| 11499 | 700 | not avail. | 3006 SPRG  | 1-Apr-71  | N | PD/S    | 3-Feb-15  | 25-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 493806 | F | Ilion repaired at n/c   |
| 11491 | 700 | 85272      | 243 WIN    | 9-May-12  | N | S       | 3-Feb-15  | 13-Mar-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 495467 | F | Check over completely, repair as needed, and test at no charge  |
| 11542 | 700 | 85598      | 7MM MAG    | 3-Feb-12  | N | PI/S    | 3-Feb-15  | 3-Mar-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 494674 | F | Per Ilion- Repair at no charge under recall.                    |
| 11501 | 600 | not avail. | 6MM REM    | 1-May-64  | Y | S       | 4-Feb-15  | 4-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 490350 | F | Per Ilion- Replace TA under BLP                                 |
| 11503 | 700 | not avail. | 270 WIN    | 27-Oct-70 | N | S       | 4-Feb-15  | 4-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 490477 | F | Per Ilion- Replace TA under BLP                                 |
| 11504 | 700 | 25903      | 300 WBY MA | 20-Jun-89 | N | S       | 4-Feb-15  | 4-Feb-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 490218 | F | Per Ilion: Repair at no charge                                  |
| 11505 | 700 | 27480      | 7MM REM MA | 27-Jul-00 | N | S       | 4-Feb-15  | 4-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 490085 | F | Per Ilion: Repair at no charge                                  |

RAC001217

Confidential

|       |       |            |            |           |   |      |          |           |   |                                   |        |   |   |
|-------|-------|------------|------------|-----------|---|------|----------|-----------|---|-----------------------------------|--------|---|---|
| 11506 | 700   | not avail. | 270 WIN    | 27-Apr-72 | N | S    | 4-Feb-15 | 4-Feb-15  | Fired on Safe Release                                 | Improper Maintenance              | 490405 | F | Per Iion: Repair at no charge<br>Per Iion- Replace TA under BLP |
| 11508 | 600   | not avail. | 308 WIN    | 1-Apr-68  | N | S    | 4-Feb-15 | 4-Feb-15  | Fired on Safe Release                                 | Improper Maintenance              | 489851 | F | Per Iion- BLP   |
| 11509 | 600   | not avail. | 308 WIN    | 1-Jul-66  | N | S    | 4-Feb-15 | 4-Feb-15  | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation            | 489776 | F | Per Iion- Replace TA under BLP                                  |
| 11510 | 700   | not avail. | 3006 SPR   | 1-Oct-74  | N | S    | 4-Feb-15 | 4-Feb-15  | Delayed Firing - Firearms                             | Could Not Duplicate Concern       | 490543 | F | Per Iion- Replace TA under BLP                                  |
| 11513 | 700   | not avail. | 243 WIN    | 21-Jul-72 | N | S    | 4-Feb-15 | 4-Feb-15  | Fired on Bolt Closing                                 | Altered Adjustments or Components | 490467 | F | Per Iion- Replace TA under BLP                                  |
| 11514 | 700   | not avail. | 3006 SPR   | 21-Aug-75 | N | S    | 4-Feb-15 | 4-Feb-15  | Fired on Bolt Closing                                 | Altered Adjustments or Components | 489763 | F | Per Iion- Replace TA under BLP                                  |
| 11515 | SEVEN | 24788      | 308 WIN    | 26-Apr-99 | N | S    | 4-Feb-15 | 4-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 490315 | F | Per Iion: Repair at no charge<br>Per Iion- Replace TA under BLP |
| 11516 | 700   | not avail. | 3006 SPR   | 11-Apr-75 | N | S    | 4-Feb-15 | 4-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 489685 | F | Per Iion- Replace TA under BLP                                  |
| 11518 | SEVEN | 24734      | 260 REM    | 11-Jan-00 | N | S    | 4-Feb-15 | 4-Feb-15  | Fired on Bolt Closing                                 | Altered Adjustments or Components | 489603 | F | Per Iion: Repair at no charge<br>Firearm not returned to Iion   |
| 11512 | 700   | 27105      | 270 WIN    | 6-Sep-07  | N | PD/S | 4-Feb-15 | 22-Oct-15 | Fired on Safe Release                                 | Not Examined by Product Service   | n/a    | F | for exam  |
| 11522 | 700   | 29692      | 7MM REM MA | 9-Jan-95  | N | S    | 5-Feb-15 | 5-Feb-15  | Wrong Ammunition Fired in Gun                         | Sent in for Evaluation            | 489771 | F | Per Iion- Repair at 1/2 cost                                    |
| 11523 | 700   | 27357      | 7MM-08 REM | 22-Sep-05 | N | S    | 5-Feb-15 | 5-Feb-15  | Unknown Claim   | Sent in for Evaluation            | 489403 | F | Per Iion: Repair at no charge<br>Per Iion- Replace TA under BLP |
| 11524 | 700   | not avail. | 243 WIN    | 10-Feb-72 | N | S    | 5-Feb-15 | 5-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 489399 | F | Per Iion- Replace TA under BLP                                  |
| 11525 | 700   | not avail. | 3006 SPR   | 1-Sep-85  | N | S    | 5-Feb-15 | 5-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 489833 | F | Per Iion: Repair at no charge                                   |
| 11526 | 700   | 29694      | 300 WIN MA | 16-Jan-95 | N | S    | 5-Feb-15 | 5-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 490540 | F | Per Iion: Repair at no charge<br>Per Iion- Replace TA under BLP |
| 11527 | 700   | not avail. | 3006 SPR   | 24-Aug-76 | N | S    | 5-Feb-15 | 5-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 489401 | F | Per Iion- Replace TA under BLP                                  |
| 11530 | 700   | not avail. | 308 WIN    | 16-Jun-76 | N | S    | 5-Feb-15 | 5-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 489552 | F | Per Iion- Replace TA under BLP                                  |
| 11533 | 887   | 82530      | 12 GA      | 9-Apr-10  | N | S    | 5-Feb-15 | 5-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 491852 | F | Per Iion: Repair at no charge                                   |
| 11534 | 870   | 25100      | 12 GA SMAG | 20-Oct-99 | N | S    | 5-Feb-15 | 5-Feb-15  | Fired With Safe ON                                    | Could Not Duplicate Concern       | 491536 | F | Per Iion- Repair at 1/2 cost                                    |
| 11535 | 700   | 27249      | 338 LAPUA  | 7-Feb-11  | N | S    | 6-Feb-15 | 6-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 490873 | F | Per Iion: Repair at no charge                                   |
| 11540 | 870   | 25102      | 12 GA SMAG | 19-May-00 | N | S    | 6-Feb-15 | 6-Feb-15  | Fired With Safe ON                                    | Could Not Duplicate Concern       | 491863 | F | Per Iion- Repair at 1/2 cost                                    |
| 11543 | 700   | not avail. | 3006 SPRG  | 20-May-83 | N | S    | 6-Feb-15 | 6-Feb-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 491662 | F | Per Iion: Repair at no charge                                   |
| 11545 | 700   | not avail. | 35 WHELEN  | 25-Jul-88 | N | S    | 7-Feb-15 | 7-Feb-15  | Fired on Bolt Closing                                 | Improper Maintenance              | 490828 | F | Per Iion: Repair at no charge                                   |
| 11547 | 700   | 25783      | 22-250 REM | 13-Oct-03 | N | S    | 7-Feb-15 | 7-Feb-15  | Fired on Safe Release                                 | Altered Adjustments or Components | 491733 | F | Per Iion: Repair at no charge<br>Per Iion- Replace TA under BLP |
| 11549 | 700   | not avail. | 3006 SPRG  | 19-Feb-82 | N | S    | 7-Feb-15 | 7-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 491866 | F | Per Iion- Replace TA under BLP                                  |
| 11550 | 700   | not avail. | 3006 SPRG  | 13-Jul-73 | N | S    | 7-Feb-15 | 7-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 491850 | F | Per Iion- Replace TA under BLP                                  |
| 11551 | 660   | not avail. | 308 WIN    | 1-Oct-68  | Y | S    | 7-Feb-15 | 7-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 491861 | F | Per Iion- Replace TA under BLP                                  |
| 11553 | 700   | not avail. | 25-06 REM  | 30-Mar-71 | N | S    | 8-Feb-15 | 8-Feb-15  | Fired on Safe Release                                 | Could Not Duplicate Concern       | 491870 | F | Per Iion- Replace TA under BLP                                  |
| 11555 | 700   | 25791      | 270 WIN    | 26-Feb-86 | N | S    | 8-Feb-15 | 8-Feb-15  | Fired on Bolt Closing                                 | Sent in for Evaluation            | 491735 | F | Per Iion: Repair at no charge                                   |

RAC001218

## Confidential

|       |       |            |            |           |   |      |           |           |                       |   |                                   |        |  |  |
|-------|-------|------------|------------|-----------|---|------|-----------|-----------|-----------------------|---|-----------------------------------|--------|--|--|
| 11556 | 700   | not avail. | 270 WIN    | 8-May-74  | N | S    | 8-Feb-15  | 8-Feb-15  | Fired on Bolt Closing | Could Not Duplicate Concern                           | 491862                            | F      | Per ilion- Replace TA under BLP              |  |
| 11557 | 700   | 25773      | 3006 SPRG  | 22-Jan-86 | N | S    | 8-Feb-15  | 8-Feb-15  | Fired on Bolt Closing | Could Not Duplicate Concern                           | 491872                            | F      | Per ilion: Repair at no charge               |  |
| 11558 | 600   | not avail. | 243 WIN    |           | Y | S    | 9-Feb-15  | 9-Feb-15  | Fired on Bolt Closing | Could Not Duplicate Concern                           | 491440                            | F      | Per ilion- Replace TA under BLP              |  |
| 11559 | 600   | not avail. | 222 REM    | 1-Mar-67  | Y | S    | 9-Feb-15  | 9-Feb-15  | Other - Firearms      | Sent in for Evaluation                                | 491441                            | F      | Per ilion- Replace TA under BLP              |  |
| 11560 | 700   | not avail. | 3006 SPRG  | 5-Apr-73  | N | S    | 9-Feb-15  | 9-Feb-15  | Fired on Bolt Closing | Could Not Duplicate Concern                           | 490864                            | F      | Per ilion- Replace TA under BLP              |  |
| 11561 | 700   | not avail. | 270 WIN    | 14-May-74 | N | S    | 9-Feb-15  | 9-Feb-15  | Fired on Safe Release | Could Not Duplicate Concern                           | 490984                            | F      | Per ilion- Replace TA under BLP              |  |
| 11562 | 700   | 27359      | 308 WIN    | 22-Jun-05 | N | S    | 9-Feb-15  | 9-Feb-15  | Fired on Safe Release | Improper Maintenance                                  | 491018                            | F      | Per ilion: Repair at no charge               |  |
| 11563 | 700   | not avail. | 7MM REM MA | 1-Jun-75  | N | S    | 9-Feb-15  | 9-Feb-15  |                       | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 491745 | F  | Per ilion- Replace TA under BLP              |
| 11564 | 700   | not avail. | 22-250 REM | 16-Aug-83 | N | S    | 9-Feb-15  | 9-Feb-15  | Fired on Safe Release | Could Not Duplicate Concern                           | 491728                            | F      | Per ilion: Repair at no charge               |  |
| 11565 | 700   | not avail. | 3006 SPRG  | 2-Feb-72  | N | S    | 9-Feb-15  | 9-Feb-15  | Fired on Safe Release | Could Not Duplicate Concern                           | 490834                            | F      | Per ilion- Replace TA under BLP              |  |
| 11566 | 700   | 84015      | 3006 SPRG  | 2-Apr-14  | N | S    | 9-Feb-15  | 9-Feb-15  |                       | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 491729 | F  | Per ilion: Repair at no charge               |
| 11568 | 700   | not avail. | 22-250 REM | 29-May-74 | N | S    | 9-Feb-15  | 9-Feb-15  | Fired on Bolt Closing | Altered Adjustments or Components                     | 491741                            | F      | Per ilion- Replace TA under BLP              |  |
| 11569 | 700   | 27474      | 243 WIN    | 14-May-96 | N | S    | 9-Feb-15  | 9-Feb-15  |                       | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components | 491615 | F  | Per ilion: Repair at no charge               |
| 11570 | 710   | 27410      | 3006 SPRG  | 14-Dec-05 | Y | PD/S | 9-Feb-15  | 14-Apr-15 | Fired on Bolt Closing | Other - Unspecified or Undetermined - Firearms        | 494426                            | F      | Repair @ n/c - goodwill gesture              |  |
| 11571 | 700   | 84218      | 308 WIN    | 8-Dec-10  | N | S    | 10-Feb-15 | 10-Feb-15 | Fired on Safe Release | Could Not Duplicate Concern                           | 491738                            | F      | Per ilion- Repair at no charge under recall. |  |
| 11572 | 700   | 25818      | 308 WIN    | 11-Aug-89 | N | S    | 10-Feb-15 | 10-Feb-15 | Fired on Bolt Closing | Could Not Duplicate Concern                           | 491737                            | F      | Per ilion: Repair at no charge               |  |
| 11574 | 700   | not avail. | 6MM REM    | 8-Apr-71  | N | S    | 10-Feb-15 | 10-Feb-15 | Fired on Safe Release | Could Not Duplicate Concern                           | 490819                            | F      | Per ilion- Replace TA under BLP              |  |
| 11575 | 770   | 85631      | 7MM-08 REM | 27-Nov-12 | Y | S    | 10-Feb-15 | 10-Feb-15 | Fired on Bolt Closing | Could Not Duplicate Concern                           | 491498                            | F      | Per ilion: Repair at no charge               |  |
| 11576 | 700   | not avail. | 270 WIN    | 18-Dec-80 | N | S    | 10-Feb-15 | 10-Feb-15 | Fired on Bolt Closing | Could Not Duplicate Concern                           | 491553                            | F      | Per ilion- Replace TA under BLP              |  |
| 11577 | 700   | not avail. | 3006 SPRG  | 5-Oct-70  | N | S    | 10-Feb-15 | 10-Feb-15 | Fired on Safe Release | Could Not Duplicate Concern                           | 490968                            | F      | Per ilion- Replace TA under BLP              |  |
| 11578 | 700   | 25803      | 7MM REM MA | 4-Dec-92  | N | S    | 10-Feb-15 | 10-Feb-15 | Fired on Safe Release | Could Not Duplicate Concern                           | 491555                            | F      | Per ilion: Repair at no charge               |  |
| 11579 | 700   | not avail. | MA         | 1-Jul-74  | N | S    | 10-Feb-15 | 10-Feb-15 | Fired on Safe Release | Could Not Duplicate Concern                           | 491178                            | F      | Per ilion- Replace TA under BLP              |  |
| 11580 | 700   | not avail. | 3006 SPRG  | 5-Jan-72  | N | S    | 10-Feb-15 | 10-Feb-15 | Fired on Safe Release | Could Not Duplicate Concern                           | 492369                            | F      | Per ilion- Replace TA under BLP              |  |
| 11583 | 700   | 27315      | 7MM RUM    | 23-Sep-08 | N | S    | 10-Feb-15 | 10-Feb-15 |                       | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 492389 | F  | Per ilion- Repair at no charge under recall. |
| 11584 | SEVEN | 85952      | 223 REM    | 10-Jan-08 | N | S    | 10-Feb-15 | 10-Feb-15 |                       | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 491977 | F  | Per ilion- Repair at no charge under recall. |

RAC001219

## Confidential

|       |       |            |            |           |   |      |           |           |   |                                   |        |   |  |
|-------|-------|------------|------------|-----------|---|------|-----------|-----------|---|-----------------------------------|--------|---|--|
| 11588 | 700   | not avail. | 3006 SPRG  | 29-Jul-74 | N | S    | 11-Feb-15 | 11-Feb-15 | Other - Firearms                                      | Sent in for Evaluation            | 492319 | F | Per Ilion- Replace TA under BLP  |
| 11589 | 788   | not avail. | 243 WIN    | 14-Jun-81 | Y | S    | 11-Feb-15 | 11-Feb-15 | Fired on Bolt Opening                                 | Improper Maintenance              | 492375 | F | Per Ilion: Repair as needed.   |
| 11590 | 700   | 29737      | 7MM-08 REM | 17-May-93 | N | S    | 11-Feb-15 | 11-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation            | 492146 | F | Per Ilion: Repair at no charge   |
| 11591 | 700   | 25746      | 308 WIN    | 16-Feb-93 | N | S    | 11-Feb-15 | 11-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 491896 | F | Per Ilion: Repair at no charge   |
| 11592 | 700   | 27121      | 270 WIN    | 20-Jun-13 | N | S    | 11-Feb-15 | 11-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components | 492387 | F | Per Ilion- Repair at no charge under recall.                               |
| 11593 | 700   | not avail. | 7MM REM MA | 25-Jul-75 | N | S    | 11-Feb-15 | 11-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 492366 | F | Per Ilion- Replace TA under BLP  |
| 11595 | 700   | not avail. | 3006 SPRG  | 7-Oct-70  | N | S    | 11-Feb-15 | 11-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 492550 | F | Per Ilion- Replace TA under BLP  |
| 11596 | 700   | not avail. | 3006 SPRG  | 18-Sep-84 | N | S    | 11-Feb-15 | 11-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 492551 | F | Per Ilion: Repair at no charge   |
| 11598 | 700   | 27361      | 270 WIN    | 27-Jan-12 | N | S    | 11-Feb-15 | 11-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 492372 | F | Per Ilion- Repair at no charge under recall.                               |
| 11599 | 597   | 26516      | 17 HMR     | 25-Oct-04 | N | PD/S | 11-Feb-15 | 22-Oct-15 | My Gun Blew Up  | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11600 | 700   | 25798      | 223 REM    | 25-Feb-02 | N | S    | 11-Feb-15 | 22-Oct-15 | Fired on Bolt Opening                                 | Not Examined by Product Service   | n/a    | F | Firearm not returned to Ilion for exam                                     |
| 11600 | 700   | 29735      | 243 WIN    | 13-May-93 | N | S    | 12-Feb-15 | 12-Feb-15 | Fired on Safe Release                                 | Altered Adjustments or Components | 492371 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11601 | 700   | N/A        | 270 WIN    | 12-May-75 | N | S    | 12-Feb-15 | 12-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 492501 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11604 | 700   | 84360      | 17 REM FIR | 9-Mar-07  | N | S    | 12-Feb-15 | 12-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation            | 492364 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11605 | 700   | 25939      | 270 WIN    | 1-Jun-06  | N | S    | 12-Feb-15 | 12-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 492379 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11606 | 770   | 85662      | 270 WIN    | 12-May-10 | Y | S    | 12-Feb-15 | 12-Feb-15 | Delayed Firing - Firearms                             | Could Not Duplicate Concern       | 492621 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11607 | 700   | N/A        | 3006 SPR   | 5-Oct-73  | N | S    | 12-Feb-15 | 12-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation            | 492393 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11609 | 700   | 25803      | 7MM REM MA | 11-Nov-91 | N | S    | 12-Feb-15 | 12-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 493015 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge |
| 11610 | 700   | not avail. | 243 WIN    | 1-Jul-77  | N | S    | 12-Feb-15 | 12-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 493026 | F | Per Ilion- Replace TA under BLP  |
| 11603 | 870   | 25133      | 12 GA      | 6-May-14  | N | PI/S | 12-Feb-15 | 1-Apr-15  | Excessive Recoil                                      | Sent in for Evaluation            | 492400 | F | Check over, repair if needed & test @ n/c                                  |
| 11615 | 1100  | 25414      | 28 GA      | 25-Sep-76 | N | S    | 13-Feb-15 | 13-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern       | 493036 | F | Per Ilion- Repair at 1/2 cost good will gesture                            |
| 11617 | 770   | 85634      | 308 WIN    | 27-Aug-13 | Y | S    | 13-Feb-15 | 13-Feb-15 | Jar-Off Safe ON                                       | Could Not Duplicate Concern       | 493061 | F | Per Ilion: Repair at no charge   |
| 11618 | SEVEN | 24782      | 243 WIN    | 22-Apr-83 | N | S    | 13-Feb-15 | 13-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern       | 493027 | F | Per Ilion: Repair at no charge   |

RAC001220

Confidential

|       |        |            |            |           |           |      |           |           |   |  |                                   |        |   |                                       |
|-------|--------|------------|------------|-----------|-----------|------|-----------|-----------|---|--|-----------------------------------|--------|---|---------------------------------------|
| 11619 | 700    | 25804      | 280 REM    | 3-Sep-92  | N         | S    | 13-Feb-15 | 13-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 493059                            | F      | Per Iion: Repair at no charge   |                                       |
| 11621 | 700    | not avail. | 243 WIN    | 10-Jun-76 | N         | S    | 13-Feb-15 | 13-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 493050                            | F      | Per Iion: Repair at no charge   |                                       |
| 11623 | 700    | 27480      | 7MM REM    | MA        | 21-Jun-01 | N    | S         | 13-Feb-15 | 13-Feb-15   | Fired on Safe Release                            | Could Not Duplicate Concern       | 493032 | F   | Per Iion: Repair at no charge         |
| 11624 | 700    | 85432      | 308 WIN    | 20-Jul-10 | N         | S    | 13-Feb-15 | 13-Feb-15 | Light Trigger Pull                                    | Could Not Duplicate Concern                      | 493076                            | F      | Per Iion- Repair at no charge under recall,                               |                                       |
| 11625 | 700    | 25773      | 3006 SPRG  | 27-Jul-84 | N         | S    | 13-Feb-15 | 13-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 493174                            | F      | Per Iion: Repair at no charge   |                                       |
| 11620 | 1911   | 96324      | 45 ACP     | 27-Nov-12 | N         | PD/S | 13-Feb-15 | 13-Mar-15 | Fired Out of Battery                                  | Other - Unspecified or Undetermined - Ammunition | 495010                            | F      | Per Iion, check over completely, repair as needed, and test at no charge. |                                       |
| 11627 | 700    | 85622      | 7MM REM    | MA        | 29-Nov-12 | N    | PI/S      | 13-Feb-15 | 22-Oct-15   | Unexplained Discharge Safe ON                    | Not Examined by Product Service   | n/a    | F   | Firearm not returned to Iion for exam |
| 11633 | 700    | 26169      | 7MM REM    | MA        | 10-Jun-99 | N    | S         | 17-Feb-15 | 17-Feb-15   | Fired on Safe Release                            | Could Not Duplicate Concern       | 493197 | F   | Per Iion: Repair at no charge         |
| 11634 | SEVEN  | 24789      | 308 WIN    | 9-Jun-01  | N         | S    | 17-Feb-15 | 17-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 493196                            | F      | Per Iion: Repair at no charge   |                                       |
| 11635 | 700    | not avail. | 3006 SPRG  | 2-Oct-70  | N         | S    | 17-Feb-15 | 17-Feb-15 | Fired on Bolt Closing                                 | Improper Maintenance                             | 493193                            | F      | Per Iion- Replace TA under BLP  |                                       |
| 11637 | 700    | not avail. | 270 WIN    | 15-Apr-69 | N         | S    | 17-Feb-15 | 17-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 493195                            | F      | Per Iion- Replace TA under BLP  |                                       |
| 11638 | 700    | 29717      | 3006 SPRG  | 2-Mar-93  | N         | S    | 17-Feb-15 | 17-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 493366                            | F      | Per Iion: Repair at no charge   |                                       |
| 11641 | 700    | 27478      | 3006 SPRG  | 1-Oct-01  | N         | S    | 17-Feb-15 | 17-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 493192                            | F      | Per Iion: Repair at no charge   |                                       |
| 11643 | MOKAWK | 600        | not avail. | 6MM REM   | 8-Feb-73  | Y    | S         | 17-Feb-15 | 17-Feb-15   | Fired on Bolt Closing                            | Altered Adjustments or Components | 493365 | F   | Per Iion- Replace TA under BLP        |
| 11644 | 700    | not avail. | 243 WIN    | 1-May-68  | N         | S    | 17-Feb-15 | 17-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 493302                            | F      | Per Iion: Repair at no charge   |                                       |
| 11654 | 700    | 27095      | 3006 SPRG  | 1-Nov-13  | N         | PD/S | 18-Feb-15 | 22-May-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 499441                            | F      | Check over completely, repair as needed, and test at no charge            |                                       |
| 11645 | 332    | 25237      | 12 GA      | 17-Aug-04 | Y         | S    | 19-Feb-15 | 19-Feb-15 | Action Opened on Firing                               | Sent in for Evaluation                           | 492166                            | F      | Per Iion: Repair at no charge   |                                       |
| 11647 | 700    | N/A        | 3006 SPRG  | 22-Sep-70 | N         | S    | 19-Feb-15 | 19-Feb-15 | Fired on Bolt Opening                                 | Improper Maintenance                             | 493449                            | F      | Per Iion, replace trigger assembly, check over and test fire at no charge |                                       |
| 11650 | 700    | N/A        | 25-06 REM  | 1-Mar-70  | N         | S    | 19-Feb-15 | 19-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 493681                            | F      | Per Iion, replace trigger assembly, check over and test fire at no charge |                                       |
| 11651 | 700    | 85486      | 243 WIN    | 28-Apr-12 | N         | S    | 19-Feb-15 | 19-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 493683                            | F      | Per Iion, replace trigger assembly, check over and test fire at no charge |                                       |
| 11653 | 700    | not avail. | 243 WIN    | 22-Sep-81 | N         | S    | 19-Feb-15 | 19-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 493679                            | F      | Per Iion- Replace TA under BLP  |                                       |
| 11655 | 770    | 85633      | 3006 SPRG  | 19-Jan-10 | Y         | S    | 19-Feb-15 | 19-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 493677                            | F      | Per Iion: Repair at no charge   |                                       |
| 11656 | 700    | not avail. | 3006 SPRG  | 21-Jul-77 | N         | S    | 19-Feb-15 | 19-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 493454                            | F      | Per Iion- Replace TA under BLP  |                                       |
| 11659 | 700    | 84370      | 223 REM    | 2-Sep-09  | N         | PD/S | 19-Feb-15 | 27-Mar-15 | Fired on Bolt Closing                                 | Sent in for Evaluation                           | 497115                            | F      | Check over completely, repair as needed, and test at no charge            |                                       |
| 11658 | 887    | 82502      | 12 GA      | 8-Sep-09  | N         | PD/S | 19-Feb-15 | 22-Oct-15 | Fired on Bolt Closing                                 | Not Examined by Product Service                  | n/a                               | F      | Firearm not returned to Iion for exam                                     |                                       |

RAC001221

Confidential

|       |     |            |           |           |           |      |           |           |   |   |                                   |        |   |                                |
|-------|-----|------------|-----------|-----------|-----------|------|-----------|-----------|---|---|-----------------------------------|--------|---|--------------------------------|
| 11663 | 870 | 25098      | 12 GA     | 16-Dec-08 | N         | PD/S | 24-Feb-15 | 10-Mar-15 | My Gun Blew Up  | Fired from Contact with Foreign Object                | 495356                            | F      | Per Iion, check over completely, repair as needed, and test at no charge.           |                                |
| 11664 | 887 | 82500      | 12 GA     | 18-Mar-15 | N         | S    | 25-Feb-15 | 25-Feb-15 | Delayed Firing - Firearms                             | Could Not Duplicate Concern                           | 493838                            | F      | Per Iion: Repair at no charge   |                                |
| 11665 | 700 | 27337      | 3006 SPRG | 24-May-05 | N         | S    | 25-Feb-15 | 25-Feb-15 | Fired on Safe Release                                 | Altered Adjustments or Components                     | 493807                            | F      | Per Iion: Repair at no charge   |                                |
| 11666 | 700 | 25793      | 3006 SPRG | 11-Sep-86 | N         | S    | 25-Feb-15 | 25-Feb-15 | Fired With Safe ON                                    | Could Not Duplicate Concern                           | 493805                            | F      | Per Iion: Repair at no charge   |                                |
| 11668 | 700 | not avail. | 7MM REM   | MA        | 22-Mar-72 | N    | S         | 25-Feb-15 | 25-Feb-15   | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 493821 | F   | Per Iion- Replace TA under BLP |
| 11669 | 887 | 82540      | 12 GA     | 18-Jun-12 | N         | S    | 25-Feb-15 | 25-Feb-15 | Failed to Extract                                     | Sent in for Evaluation                                | 493965                            | F      | Per Iion- Evaluate for WIP  |                                |
| 11670 | 700 | 25791      | 270 WIN   | 20-Jun-86 | N         | S    | 25-Feb-15 | 25-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Improper Maintenance                                  | 493922                            | F      | Per Iion: Repair at no charge   |                                |
| 11671 | 700 | 85362      | 223 REM   | 23-Jun-07 | N         | S    | 25-Feb-15 | 25-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation                                | 493899                            | F      | Per Iion, check over completely, replace trigger assembly under recall at no charge |                                |
| 11672 | 700 | N/A        | 270 WIN   | 27-Oct-88 | N         | S    | 25-Feb-15 | 25-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                           | 493872                            | F      | Per Iion, replace trigger assembly, check over and test fire at no charge           |                                |
| 11674 | 597 | N/A        | 17 HMR    | 15-Nov-06 | N         | PD/S | 25-Feb-15 | 25-Feb-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms        | 493990                            | F      | Call Center sent customer \$200   |                                |
| 11675 | 700 | 25793      | 3006 SPRG | 16-Dec-86 | N         | S    | 25-Feb-15 | 25-Feb-15 | Fired With Safe ON                                    | Could Not Duplicate Concern                           | 493952                            | F      | Per Iion, replace trigger assembly, check over and test fire at no charge           |                                |
| 11677 | 700 | 84371      | 308 WIN   | 5-Jun-13  | N         | PD/S | 25-Feb-15 | 27-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                           | 496994                            | F      | Repaired rifle @ n/c under XMP recall   |                                |
| 11678 | 660 | not avail. | 222 REM   | 1-Jan-68  | Y         | S    | 26-Feb-15 | 26-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                           | 493273                            | F      | Per Iion- Replace TA under BLP  |                                |
| 11680 | 700 | 29694      | 300 WIN M | 27-Apr-93 | N         | S    | 26-Feb-15 | 26-Feb-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                           | 494348                            | F      | Per Iion: Repair at no charge   |                                |
| 11681 | 700 | not avail. | 264 WIN   | MA        | 4-Oct-77  | N    | S         | 26-Feb-15 | 26-Feb-15   | Fired on Bolt Closing                                 | Altered Adjustments or Components | 494338 | F   | Per Iion- Replace TA under BLP |
| 11682 | 700 | 26010      | 300 RUM   | 2-Dec-02  | N         | S    | 26-Feb-15 | 26-Feb-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components                     | 494162                            | F      | Per Iion: Repair at no charge   |                                |
| 11683 | 700 | 25791      | 270 WIN   | 21-Jan-89 | N         | S    | 26-Feb-15 | 26-Feb-15 | Fired on Bolt Closing                                 | Improper Maintenance                                  | 494186                            | F      | Per Iion: Repair as needed.   |                                |
| 11685 | 700 | not avail. | 270 WIN   | 13-Oct-76 | N         | S    | 26-Feb-15 | 26-Feb-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                           | 494318                            | F      | Per Iion- Replace TA under BLP  |                                |
| 11686 | 700 | 26139      | 300 RUM   | 28-Apr-01 | N         | S    | 26-Feb-15 | 26-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                           | 494193                            | F      | Per Iion: Repair at no charge   |                                |
| 11687 | 700 | not avail. | 243 WIN   | 2-Aug-83  | N         | S    | 26-Feb-15 | 26-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                           | 494202                            | F      | Per Iion: Repair at no charge   |                                |
| 11688 | 700 | 25793      | 3006 SPRG | 3-Nov-91  | N         | S    | 26-Feb-15 | 26-Feb-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                           | 494199                            | F      | Per Iion: Repair at no charge   |                                |

RAC001222

Confidential

|       |     |            |            |           |   |         |           |           |   |  |        |   |   |
|-------|-----|------------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|---|
| 11689 | 700 | not avail. | 7MM REM MA | 31-Mar-78 | N | S       | 26-Feb-15 | 26-Feb-15 | Fired on Bolt Closing                                 | Improper Maintenance                             | 494196 | F | Per Illion- Replace TA under BLP  |
| 11691 | 700 | not avail. | 7MM REM MA | 17-Jan-73 | N | S       | 2-Mar-15  | 2-Mar-15  | Unknown Claim   | Altered Adjustments or Components                | 494563 | F | Per Illion- Replace TA under BLP  |
| 11692 | 700 | 26133      | 7MM REM MA | 14-Mar-01 | N | S       | 2-Mar-15  | 2-Mar-15  | Fired on Safe Release                                 | Altered Adjustments or Components                | 494561 | F | Per Illion: Repair at no charge   |
| 11693 | 700 | not avail. | 7MM REM MA | 1-May-67  | N | S       | 2-Mar-15  | 2-Mar-15  | Fired With Safe ON                                    | Altered Adjustments or Components                | 494559 | F | Per Illion- Replace TA under BLP  |
| 11694 | 700 | 25771      | 270 WIN    | 30-Sep-97 | N | S       | 2-Mar-15  | 2-Mar-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 494558 | F | Per Illion: Repair at no charge   |
| 11695 | 700 | 20000      | 35 WHELEN  | 28-Jul-88 | N | S       | 2-Mar-15  | 2-Mar-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 494555 | F | Per Illion: Repair at no charge   |
| 11696 | 700 | not avail. | 270 WIN    | 1-Mar-72  | N | S       | 2-Mar-15  | 2-Mar-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 494552 | F | Per Illion- Replace TA under BLP  |
| 11697 | 700 | not avail. | 3006 SPRG  | 1-Mar-65  | N | S       | 2-Mar-15  | 2-Mar-15  | Fired on Bolt Closing                                 | Improper Maintenance                             | 494554 | F | Per Illion- Replace TA under BLP  |
| 11700 | 597 | 26516      | 17 HMR     | 21-Jan-03 | N | PD/S    | 2-Mar-15  | 27-Mar-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Ammunition | 497434 | F | Replace with Ramac 70723 in exchange  |
| 11701 | 887 | 82502      | 12 GA      | 21-Jan-14 | N | S       | 3-Mar-15  | 3-Mar-15  | Failed to Extract                                     | Sent in for Evaluation                           | 494665 | F | Per Illion: Repair at no charge   |
| 11704 | 700 | not avail. | 3006 SPRG  | 1-Nov-66  | N | S       | 3-Mar-15  | 3-Mar-15  | Unexplained Discharge - No Mention of Safety Position | Improper Maintenance                             | 494638 | F | Per Illion- Replace TA under BLP  |
| 11705 | 700 | 26010      | 300 RUM    | 18-Dec-02 | N | S       | 3-Mar-15  | 3-Mar-15  | Went Automatic  | Could Not Duplicate Concern                      | 494669 | F | Per Illion: Repair at no charge   |
| 11709 | 597 | 26536      | 17 HMR     | 27-May-03 | N | PI/PD/S | 3-Mar-15  | 17-Mar-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms   | 495824 | F | Converting to 22 WMR as requested by customer                               |
| 11710 | 700 | not avail. | 270 WIN    | 21-Apr-77 | N | S       | 5-Mar-15  | 5-Mar-15  | Fired on Safe Release                                 | Altered Adjustments or Components                | 495085 | F | Per Illion- Replace TA under BLP  |
| 11711 | 700 | 29717      | 3006 SPRG  | 6-Nov-03  | N | S       | 5-Mar-15  | 5-Mar-15  | Fired on Bolt Closing                                 | Improper Maintenance                             | 495088 | F | Per Illion: Repair at no charge   |
| 11713 | 597 | 26516      | 17 HMR     | 24-Jul-03 | N | PI/PD/S | 5-Mar-15  | *         | My Gun Blew Up  | Other - Unexamined                               |        | F |   |
| 11715 | 700 | not avail. | 3006 SPRG  | 8-Feb-78  | N | S       | 6-Mar-15  | 6-Mar-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 495250 | F | Per Illion- Replace TA under BLP  |
| 11716 | 700 | not avail. | 3006 SPRG  | 2-Sep-69  | N | S       | 6-Mar-15  | 6-Mar-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 495248 | F | Per Illion- Replace TA under BLP  |
| 11717 | 770 | 85658      | 300 WIN MA | 10-Feb-09 | Y | S       | 6-Mar-15  | 6-Mar-15  | Fired on Safe Release                                 | Other - Unspecified or Undetermined - Firearms   | 495261 | F | Per Illion: Repair at no charge   |
| 11721 | 700 | not avail. | 308 WIN    | 13-Feb-76 | N | S       | 10-Mar-15 | 10-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 495293 | F | Per Illion- Replace TA under BLP  |
| 11722 | 700 | not avail. | 7MM REM MA | 1-Dec-80  | N | S       | 11-Mar-15 | 11-Mar-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 495468 | F | Per Illion- Replace TA under BLP  |
| 11723 | 700 | N/A        | 243 WIN    | 21-Apr-72 | N | S       | 11-Mar-15 | 11-Mar-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components                | 495469 | F | Per Illion, replace trigger assembly, check over and test fire at no charge |
| 11724 | 700 | 25851      | 270 WIN    | 22-Apr-03 | N | S       | 11-Mar-15 | 11-Mar-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 495386 | F | Per Illion, replace trigger assembly, check over and test fire at no charge |
| 11726 | 700 | 25771      | 270 WIN    | 25-Jan-84 | N | S       | 11-Mar-15 | 11-Mar-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 495458 | F | Per Illion, replace trigger assembly, check over and test fire at no charge |

RAC001223

## Confidential

|       |              |            |            |           |   |         |           |           |   |  |        |   |  |
|-------|--------------|------------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|--|
| 11727 | 700          | 84207      | 308 WIN    | 13-May-08 | N | S       | 11-Mar-15 | 11-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 495464 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                 |
| 11728 | 597          | 26516      | 17 HMR     | 3-Oct-06  | N | PD/S    | 11-Mar-15 | 11-Mar-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 495459 | F | Sending \$200 coupon in exchange for gun.  |
| 11733 | 700          | 27523      | 308 WIN    | 5-Apr-02  | N | S       | 12-Mar-15 | 12-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 495650 | F | Per Ilion: Repair at no charge   |
| 11734 | 700          | 25777      | 7MM REM MA | 23-Jul-85 | N | S       | 12-Mar-15 | 12-Mar-15 | Fired on Safe Release                                 | Sent in for Evaluation                         | 495652 | F | Per Ilion: Repair at no charge   |
| 11735 | 700          | not avail. | 3006 SPRG  | 10-Mar-77 | N | S       | 12-Mar-15 | 12-Mar-15 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 495661 | F | Per Ilion- Replace TA under BLP  |
| 11736 | 700          | 25771      | 270 WIN    | 1-Jul-85  | N | S       | 12-Mar-15 | 12-Mar-15 | Fired on Bolt Closing                                 | Improper Maintenance                           | 495649 | F | Per Ilion: Repair at no charge   |
| 11739 | 700          | 26410      | 300 RUM    | 18-Feb-03 | N | S       | 12-Mar-15 | 12-Mar-15 | Fired on Safe Release                                 | Improper Maintenance                           | 495648 | F | Per Ilion: Repair at no charge   |
| 11741 | 700          | 25811      | 270 WIN    | 18-May-89 | N | S       | 16-Mar-15 | 16-Mar-15 | Fired With Safe ON                                    | Improper Maintenance                           | 495659 | F | Per Ilion: Repair at no charge   |
| 11742 | 700          | N/A        | 3006 SPRG  | 9-Apr-73  | N | S       | 16-Mar-15 | 16-Mar-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 495923 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                 |
| 11743 | 700          | N/A        | 7MM REM MA | 20-Nov-81 | N | S       | 16-Mar-15 | 16-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 495813 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                 |
| 11744 | 700          | 26039      | 7MM REM MA | 25-Feb-97 | N | S       | 16-Mar-15 | 16-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 495814 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                 |
| 11746 | 870          | 81062      | 12 GA      | 17-Feb-15 | N | PD/S    | 16-Mar-15 | 25-Mar-15 | Action Opened on Firing                               | Sent in for Evaluation                         | 497215 | F | Per Ilion, check over completely, repair as needed, and test at no charge.                 |
| 11749 | 700          | N/A        | 270 WIN    | 12-May-75 | N | S       | 17-Mar-15 | 17-Mar-15 | Safety not working properly                           | Could Not Duplicate Concern                    | 496309 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                 |
| 11750 | 700          | N/A        | 3006 SPRG  | 16-Jun-71 | N | S       | 17-Mar-15 | 17-Mar-15 | Fired on Safe Release                                 | Altered Adjustments or Components              | 496192 | F | Per Ilion, replace trigger assembly, check over and test fire at no charge                 |
| 11751 | 700          | 85446      | 243 WIN    | 18-Sep-12 | N | S       | 17-Mar-15 | 17-Mar-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 496261 | F | Per Ilion- Repair at no charge under recall.   |
| 11752 | 700          | 25793      | 3006 SPRG  | 22-Jun-12 | N | S       | 17-Mar-15 | 17-Mar-15 | Fail to Fire  | Could Not Duplicate Concern                    | 496260 | F | Per Ilion: Repair at no charge   |
| 11753 | 700          | 27476      | 270 WIN    | 27-Feb-95 | N | S       | 17-Mar-15 | 17-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 496257 | F | Per Ilion: Repair at no charge   |
| 11755 | 597          | 26516      | 17 HMR     | 15-Nov-06 | N | S       | 17-Mar-15 | 17-Mar-15 | Other - Firearms                                      | Other - Unspecified or Undetermined - Firearms | 496255 | F | Per Ilion- Rebate Coupon mailed to consumer.   |
| 11754 | 597          | 26536      | 17 HMR     | 19-Jun-03 | N | S       | 17-Mar-15 | 28-Apr-15 | Other - Firearms                                      | Other - Unspecified or Undetermined - Firearms | 496269 | F | Replace w/70723 in exchange Check over completely, repair as needed, and test at no charge |
| 11756 | Pardner Pump | 72312      | 12 GA      | 4-Feb-14  | N | PI/PO/S | 17-Mar-15 | 6-Apr-15  | Fired Out of Battery                                  | Other - Unspecified or Undetermined - Firearms | 497678 | F | Check over completely, repair as needed, and test at no charge                             |
| 11761 | 870          | 25568      | 12 GA      | 26-Aug-08 | N | S       | 19-Mar-15 | 19-Mar-15 | Unknown Claim   | Other - Unspecified or Undetermined - Firearms | 496332 | F | Per Customer- Return as received   |
| 11762 | 700          | not avail. | 7MM REM MA | 17-Mar-79 | N | S       | 19-Mar-15 | 19-Mar-15 | Other - Firearms                                      | Improper Maintenance                           | 496632 | F | Per Ilion- Replace TA under BLP  |
| 11763 | 700          | 84344      | 220 SWIFT  | 15-Jun-09 | N | S       | 19-Mar-15 | 19-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 496633 | F | Per Ilion- Repair at no charge under recall.   |

RAC001224

## Confidential

|       |          |            |            |           |   |         |           |           |   |  |        |   |  |
|-------|----------|------------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|--|
| 11764 | 788      | not avail. | 223 REM    | 3-Jul-75  | Y | S       | 19-Mar-15 | 19-Mar-15 | Fired on Safe Release                                 | Improper Maintenance                             | 496636 | F | Per Iion: Repair at no charge  |
| 11765 | 700      | 26311      | 300 WSM    | 5-Oct-05  | N | S       | 19-Mar-15 | 19-Mar-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 496634 | F | Per Iion: Repair at no charge  |
| 11766 | 1911     | 96335      | 45 ACP     | 4-Sep-13  | N | S       | 19-Mar-15 | 19-Mar-15 | Safety not working properly                           | Aft Mkt Safety                                   | 496493 | F | Per Iion-Quote to repair at discount.  |
| 11773 | 700      | not avail. | 270 WIN    | 27-Sep-76 | N | PI/S    | 19-Mar-15 | 17-Aug-15 | Fired on Safe Release                                 | Sent in for Evaluation                           | 499358 | F | Davis Release agreement - Item# 83205, Doran Release Agreement - Item# 60037     |
| 11769 | 700      | 27269      | 3006 SPRG  | 6-May-05  | N | S       | 20-Mar-15 | 20-Mar-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 496635 | F | Per Iion, replace trigger assembly, check over and test fire at no charge        |
| 11770 | 770      | 85633      | 3006 SPRG  | 28-May-13 | Y | S       | 20-Mar-15 | 20-Mar-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 496954 | F | Per Iion: Repair at no charge  |
| 11771 | 721      | N/A        | 3006 SPRG  | 1-Aug-50  | Y | S       | 20-Mar-15 | 20-Mar-15 | Unexplained Discharge Safe OFF                        | Sent in for Evaluation                           | 496915 | F | Per Iion, check over completely, replace trigger assembly under BLM at no charge |
| 11774 | 700      | N/A        | 270 WIN    | 15-Jul-77 | N | S       | 20-Mar-15 | 20-Mar-15 | Unexplained Discharge Safe OFF                        | Altered Adjustments or Components                | 496957 | F | Per Iion, replace trigger assembly, check over and test fire at no charge        |
| 11778 | 700      | not avail. | 17 REM     | 3-May-74  | N | S       | 23-Mar-15 | 23-Mar-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 496986 | F | Per Iion- Replace TA under BLP   |
| 11780 | 700      | N/A        | 3006 SPRG  | 3-Jun-75  | N | S       | 23-Mar-15 | 23-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 496990 | F | Per Iion, check over completely, replace trigger assembly under BLM at no charge |
| 11781 | 700      | 25795      | 308 WIN    | 1-Sep-94  | N | S       | 23-Mar-15 | 23-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 496987 | F | Per Iion, replace trigger assembly, check over and test fire at no charge        |
| 11782 | 700      | N/A        | 3006 SPRG  | 24-Feb-76 | N | S       | 23-Mar-15 | 23-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 496989 | F | Per Iion, replace trigger assembly, check over and test fire at no charge        |
| 11784 | 770      | 85635      | 7MM REM    | 10-Jun-11 | Y | S       | 23-Mar-15 | 23-Mar-15 | Delayed Firing - Firearms                             | Sent in for Evaluation                           | 497052 | F | Per Iion: Repair at no charge  |
| 11785 | 700      | 27391      | 7MM-08 REM | 25-Sep-09 | N | S       | 23-Mar-15 | 23-Mar-15 | Unexplained Discharge Safe ON                         | Could Not Duplicate Concern                      | 496991 | F | Per Iion, replace trigger assembly, check over and test fire at no charge        |
| 11786 | 597      | not avail. | 17 HMR     | 21-Jan-03 | N | PI/PD/S | 23-Mar-15 | 20-May-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Ammunition | 499699 | F | Convert to 22 WMR - customer request   |
| 11788 | 770      | 85632      | 270 WIN    | 5-Nov-09  | Y | S       | 25-Mar-15 | 25-Mar-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 497189 | F | Per Iion: Repair at no charge  |
| 11789 | 700      | not avail. | 222 REM    | 1-Jan-67  | N | S       | 25-Mar-15 | 25-Mar-15 | Fired on Bolt Closing                                 | Improper Maintenance                             | 497214 | F | Per Iion- Replace TA under BLP   |
| 11790 | 597      | 26513      | 22 LR      | 28-Oct-13 | N | S       | 25-Mar-15 | 25-Mar-15 | Unknown Claim   | Other - Unspecified or Undetermined - Firearms   | 497122 | F | Per Iion: Repair at no charge  |
| 11792 | XM15-E25 | not avail. | 223/5.56   | 30-Jan-06 | N | S       | 25-Mar-15 | 25-Mar-15 | Went Automatic  | Could Not Duplicate Concern                      | 497218 | F | Per Iion: Repair at no charge  |
| 11795 | XM15-E25 | not avail. | 223/5.56   | 30-Jan-06 | N | S       | 25-Mar-15 | 25-Mar-15 | Went Automatic  | Could Not Duplicate Concern                      | 497219 | F | Per Iion: Repair at no charge  |
| 11804 | 700      | 25791      | 270 WIN    | 2-Feb-84  | N | S       | 27-Mar-15 | 27-Mar-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 497283 | F | Per Iion: Repair at no charge  |
| 11805 | 700      | 25773      | 3006 SPRG  | 21-Jan-89 | N | S       | 27-Mar-15 | 27-Mar-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 497290 | F | Per Iion: Repair at no charge  |

RAC001225

Confidential

|       |           |            |            |           |           |      |           |           |   |  |                             |        |   |                                   |
|-------|-----------|------------|------------|-----------|-----------|------|-----------|-----------|---|--|-----------------------------|--------|---|-----------------------------------|
| 11806 | 700       | not avail. | 270 WIN    | 12-Jan-72 | N         | S    | 27-Mar-15 | 27-Mar-15 | Unknown Claim   | Sent in for Evaluation                 | 497431                      | F      | Per Iion- Replace TA under BLP  |                                   |
| 11807 | 700       | 25801      | 17 REM     | 29-Feb-96 | N         | S    | 27-Mar-15 | 27-Mar-15 | Fired on Safe Release                                 | Altered Adjustments or Components      | 497367                      | F      | Per Iion: Repair at no charge   |                                   |
| 11808 | 700       | 27478      | 3006 SPRG  | 5-Sep-95  | N         | S    | 27-Mar-15 | 27-Mar-15 | Fired on Safe Release                                 | Could Not Duplicate Concern            | 497297                      | F      | Per Iion: Repair at no charge   |                                   |
| 11813 | 597       | 26560      | 22 WMR     | 12-Aug-14 | N         | S    | 31-Mar-15 | 31-Mar-15 | Fail to Fire  | Sent in for Evaluation                 | 497489                      | F      | Per Iion: Repair at no charge   |                                   |
| 11818 | 700       | not avail. | 3006 SPRG  | 10-May-72 | N         | S    | 31-Mar-15 | 31-Mar-15 | Fired With Safe ON                                    | Altered Adjustments or Components      | 497548                      | F      | Per Iion- Replace TA under BLP  |                                   |
| 11821 | 700       | not avail. | 222 REM    | 1-May-64  | N         | S    | 31-Mar-15 | 31-Mar-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern            | 497568                      | F      | Per Iion- Replace TA under BLP  |                                   |
| 11822 | 700       | 25811      | 270 WIN    | 17-Oct-86 | N         | S    | 31-Mar-15 | 31-Mar-15 | Delayed Firing - Firearms                             | Sent in for Evaluation                 | 497494                      | F      | Per Iion: Repair at no charge   |                                   |
| 11823 | 700       | not avail. | 222 REM    | 11-Jan-71 | N         | S    | 31-Mar-15 | 31-Mar-15 | Fired on Safe Release                                 | Altered Adjustments or Components      | 497549                      | F      | Per Iion- Replace TA under BLP  |                                   |
| 11824 | 700       | 27311      | 7MM REM MA | 4-Jun-12  | N         | PI/S | 31-Mar-15 | 23-Apr-15 | Fired on Safe Release                                 | Could Not Duplicate Concern            | 498612                      | F      | Check over completely, repair as needed, and test at no charge                    |                                   |
| 11825 | 788       | not avail. | REM        | 22-250    | 18-Apr-80 | Y    | S         | 31-Mar-15 | 13-May-15   | Fired on Safe Release                  | Could Not Duplicate Concern | 497567 | F   | Clean TA @ n/c - goodwill gesture |
| 11816 | 788       | not avail. | 243 WIN    | 6-Feb-78  | Y         | S    | 31-Mar-15 | 13-May-15 | Fired on Safe Release                                 | Improper Maintenance                   | 497518                      | F      | Clean TA @ n/c - goodwill gesture   |                                   |
| 11837 | 700       | 84370      | 223 REM    | 28-Mar-13 | N         | PD/S | 31-Mar-15 | 16-Jul-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern            | 499015                      | F      | Per Release - Repair rifle @ n/c under XMP recall & reimbursement check for \$443 |                                   |
| 11836 | 700       | 84528      | 300 RUM    | 17-Aug-10 | N         | S    | 2-Apr-15  | 2-Apr-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern            | 497681                      | F      | Ilion repaired at n/c   |                                   |
| 11838 | 78        | 26162      | 270 WIN    | 19-Nov-85 | Y         | S    | 2-Apr-15  | 2-Apr-15  | Fired on Safe Release                                 | Altered Adjustments or Components      | 497707                      | F      | Per Iion, replace trigger assembly, check over and test fire at no charge         |                                   |
| 11839 | 700       | 26263      | 7MM REM MA | 28-Feb-97 | N         | S    | 2-Apr-15  | 2-Apr-15  | Fired on Safe Release                                 | Could Not Duplicate Concern            | 497711                      | F      | Check over completely, repair as needed, and test at no charge                    |                                   |
| 11844 | 1187      | 29819      | 12 GA      | 27-May-95 | N         | S    | 7-Apr-15  | 28-Apr-15 | Fired Out of Battery                                  | Fired from Contact with Foreign Object | 497831                      | F      | Per Iion- Repair at 1/2 cost  |                                   |
| 11846 | 700       | not avail. | 6MM REM    | 30-Aug-76 | N         | S    | 7-Apr-15  | 7-Apr-15  | Fired on Safe Release                                 | Could Not Duplicate Concern            | 497867                      | F      | Per Iion- Replace TA under BLP  |                                   |
| 11852 | 700       | 27363      | 3006 SPRG  | 17-Nov-08 | N         | S    | 8-Apr-15  | 8-May-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern            | 499364                      | F      | Per Iion, replace trigger assembly, check over, and test fire at no charge        |                                   |
| 11854 | CARBON 15 | 91037      | 223/5.56   | 6-Mar-14  | N         | S    | 9-Apr-15  | 9-Apr-15  | Jar-Off Safe ON                                       | Sent in for Evaluation                 | 498080                      | F      | Per Iion: Repair at no charge   |                                   |
| 11857 | 700       | 25845      | 260 REM    | 10-May-01 | N         | S    | 9-Apr-15  | 9-Apr-15  | Other - Firearms                                      | Sent in for Evaluation                 | 497975                      | F      | Per Iion: Repair at no charge   |                                   |
| 11858 | 700       | 25815      | 7MM REM MA | 12-Jul-83 | N         | S    | 9-Apr-15  | 9-Apr-15  | Fired on Safe Release                                 | Could Not Duplicate Concern            | 498018                      | F      | Per Iion: Repair at no charge   |                                   |
| 11860 | 710       | 27408      | 270 WIN    | 17-Feb-04 | Y         | S    | 9-Apr-15  | 9-Apr-15  | Fired on Safe Release                                 | Altered Adjustments or Components      | 498077                      | F      | Per Iion: Repair at no charge   |                                   |
| 11862 | 700       | not avail. | 3006 SPRG  | 24-Sep-76 | N         | S    | 14-Apr-15 | 14-Apr-15 | Fired on Bolt Closing                                 | Sent in for Evaluation                 | 498152                      | F      | Per Iion- Replace TA under BLP  |                                   |
| 11863 | 700       | 84164      | 300 WIN MA | 18-Dec-14 | N         | S    | 14-Apr-15 | 14-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern            | 498169                      | F      | Per Iion- Repair at no charge under recall.                                       |                                   |
| 11864 | 700       | not avail. | 3006 SPRG  | 15-Sep-71 | N         | S    | 14-Apr-15 | 14-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern            | 498274                      | F      | Per Iion- Replace TA under BLP  |                                   |
| 11865 | 700       | not avail. | 308 WIN    | 9-May-78  | N         | S    | 14-Apr-15 | 14-Apr-15 | Fired on Safe Release                                 | Could Not Duplicate Concern            | 498219                      | F      | Per Iion- Replace TA under BLP  |                                   |
| 11866 | 700       | not avail. | 270 WIN    | 31-Aug-70 | N         | S    | 14-Apr-15 | 14-Apr-15 | Fired on Safe Release                                 | Could Not Duplicate Concern            | 498221                      | F      | Per Iion- Replace TA under BLP  |                                   |

RAC001226

Confidential

|       |       |            |            |           |           |         |           |           |   |  |                             |        |   |  |
|-------|-------|------------|------------|-----------|-----------|---------|-----------|-----------|---|--|-----------------------------|--------|---|--|
| 11868 | 770   | 85634      | 308 WIN    | 26-Apr-07 | Y         | S       | 14-Apr-15 | 14-Apr-15 | Fired on Bolt Closing                                 | Sent in for Evaluation                         | 498250                      | F      | Per Iion: Repair at no charge                 |  |
| 11867 | 597   | 26516      | 17 HMR     | 31-Jul-03 | N         | S       | 14-Apr-15 | 22-May-15 | Other - Firearms                                      | Other - Unspecified or Undetermined - Firearms | 498278                      | F      | Rebate coupon mailed to consumer              |  |
| 11870 | 597   | N/A        | 17 HMR     |           | N         | PI/PD/S | 14-Apr-15 | *         | My Gun Blew Up  | Other - Unexamined                             |                             | F      |   |  |
| 11876 | 710   | 27408      | 270 WIN    | 12-Mar-05 | Y         | S       | 16-Apr-15 | 27-Apr-15 | Fired on Bolt Closing                                 | Sent in for Evaluation                         | 498332                      | F      | Call Center replaced at no charge w/Model 783 |  |
| 11877 | 700   | 84645      | 243 WIN    | 2-Aug-12  | N         | S       | 16-Apr-15 | 16-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 498447                      | F      | Per Iion- Repair at no charge under recall.   |  |
| 11878 | 700   | not avail. | 270 WIN    | 1-Jan-63  | N         | S       | 16-Apr-15 | 16-Apr-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 498305                      | F      | Per Iion- Replace TA under BLP                |  |
| 11879 | 7400  | 24716      | 3006 SPRG  | 23-Jan-85 | Y         | PD/S    | 16-Apr-15 | 16-Apr-15 | Failed to Extract                                     | Rotated Barrel Extension                       | 498324                      | F      | Per Iion: Repair at no charge                 |  |
| 11880 | 700   | not avail. | 7MM REM    | 7MM REM   | 1-Dec-79  | N       | S         | 16-Apr-15 | 16-Apr-15   | Fired on Safe Release                          | Could Not Duplicate Concern | 498283 | F   | Per Iion- Replace TA under BLP                                 |
| 11881 | 700   | not avail. | 6MM REM    | 19-Sep-78 | N         | S       | 16-Apr-15 | 16-Apr-15 | Fired on Safe Release                                 | Improper Maintenance                           | 498284                      | F      | Per Iion- Replace TA under BLP                |  |
| 11882 | 700   | not avail. | 243 WIN    | 25-Sep-79 | N         | S       | 16-Apr-15 | 16-Apr-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 498459                      | F      | Per Iion- Replace TA under BLP                |  |
| 11885 | 1187  | 83617      | 12 GA      | 18-Nov-11 | N         | S       | 20-Apr-15 | 20-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 498570                      | F      | Per Iion: Repair at no charge                 |  |
| 11888 | 700   | 20000      | 22-250 REM | 20-May-71 | N         | S       | 20-Apr-15 | 20-Apr-15 | Other - Firearms                                      | Rotated Barrel Extension                       | 498474                      | F      | Per Iion: Repair at no charge                 |  |
| 11889 | 887   | 82540      | 12 GA      | 17-Jul-10 | N         | S       | 20-Apr-15 | 20-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 498549                      | F      | Per Iion: Repair at no charge                 |  |
| 11890 | 597   | 26516      | 17 HMR     | 10-Jul-05 | N         | S       | 20-Apr-15 | 20-Apr-15 | Other - Firearms                                      | Other - Unspecified or Undetermined - Firearms | 498520                      | F      | Per Iion: Repair at no charge                 |  |
| 11891 | 700   | not avail. | 270 WIN    | 22-Sep-71 | N         | S       | 20-Apr-15 | 20-Apr-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 498485                      | F      | Per Iion- Replace TA under BLP                |  |
| 11892 | 887   | 82502      | 12 GA      | 19-Jul-13 | N         | S       | 20-Apr-15 | 20-Apr-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 498482                      | F      | Per Iion: Repair at no charge                 |  |
| 11894 | 700   | not avail. | 25-06 REM  | 1-Apr-76  | N         | S       | 22-Apr-15 | 22-Apr-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 498613                      | F      | Per Iion- Replace TA under BLP                |  |
| 11895 | 700   | not avail. | 3006 SPRG  | 21-Feb-77 | N         | S       | 22-Apr-15 | 22-Apr-15 | Fired on Safe Release                                 | Altered Adjustments or Components              | 498660                      | F      | Per Iion- Replace TA under BLP                |  |
| 11896 | 700   | 26063      | 3006 SPRG  | 11-May-93 | N         | S       | 22-Apr-15 | 22-Apr-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 498574                      | F      | Per Iion: Repair at no charge                 |  |
| 11897 | 700   | not avail. | 25-06 REM  | 1-Oct-74  | N         | S       | 22-Apr-15 | 22-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 498658                      | F      | Per Iion- Replace TA under BLP                |  |
| 11903 | 700   | not avail. | 3006 SPRG  | 29-Jul-76 | N         | S       | 24-Apr-15 | 24-Apr-15 | Fired on Safe Release                                 | Altered Adjustments or Components              | 498796                      | F      | Per Iion- Replace TA under BLP                |  |
| 11904 | 700   | not avail. | 270 WIN    | 13-Sep-77 | N         | PD/S    | 24-Apr-15 | 24-Apr-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 498791                      | F      | Per Iion- Replace TA under BLP                |  |
| 11906 | 700   | 84218      | 308 WIN    | 1-Oct-14  | N         | S       | 24-Apr-15 | 24-Apr-15 | Fired on Bolt Closing                                 | Rotated Barrel Extension                       | 498767                      | F      | Per Iion- Repair at no charge under recall.   |  |
| 11907 | 742   | not avail. | 3006 SPRG  | 1-Aug-76  | Y         | S       | 24-Apr-15 | 24-Apr-15 | Other - Firearms                                      | Sent in for Evaluation                         | 498792                      | F      | Per Iion- Return As Received                  |  |
| 11908 | 700   | not avail. | 222 REM    | 18-Dec-75 | N         | S       | 24-Apr-15 | 24-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 498766                      | F      | Per Iion- Replace TA under BLP                |  |
| 11911 | 700   | not avail. | 25-06 REM  | 20-Mar-72 | N         | S       | 24-Apr-15 | 24-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 498736                      | F      | Per Iion- Replace TA under BLP                |  |
| 11913 | 700   | 27169      | 7MM REM    | MA        | 17-Aug-06 | N       | PD/S      | 24-Apr-15 | 15-Jun-15   | Unexplained Discharge Safe OFF                 | Could Not Duplicate Concern | 500402 | F   | Check over completely, repair as needed, and test at no charge |
| 11920 | SEVEN | 24782      | 243 WIN    | 3-Dec-96  | N         | S       | 28-Apr-15 | 28-Apr-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 498908                      | F      | Per Iion: Repair at no charge                 |  |

RAC001227

## Confidential

|       |             |            |           |           |   |         |           |           |                       |   |                                   |        |  |   |
|-------|-------------|------------|-----------|-----------|---|---------|-----------|-----------|-----------------------|---|-----------------------------------|--------|--|---|
| 11921 | 597         | 26536      | 17 HMR    | 24-Mar-03 | N | S       | 28-Apr-15 | 28-Apr-15 | Other - Firearms      | Other - Unspecified or Undetermined - Firearms        | 498907                            | F      | Per Iion: Repair at no charge  |   |
| 11922 | 700         | 85435      | 308 WIN   | 5-Mar-14  | N | S       | 28-Apr-15 | 28-Apr-15 | Fired on Safe Release | Altered Adjustments or Components                     | 498909                            | F      | Per Iion: Replace with Ramac #81048  |   |
| 11925 | 887         | 82500      | 12 GA     | 29-Jun-12 | N | PI/S    | 28-Apr-15 | 29-May-15 | Fired on Bolt Closing | Could Not Duplicate Concern                           | 499815                            | F      | Check over, repair if needed & test @ n/c  |   |
| 11923 | Handi Rifle | 72652      | 223 REM   | 6-Nov-13  | N | S       | 28-Apr-15 | 14-May-15 | Exploded              | Ammunition Sent in for Evaluation                     | 499369                            | F      | Refunded purchase price in Consumer Service,   |   |
| 11937 | 700         | 25630      | 270 WIN   | 17-Jan-86 | N | S       | 1-May-15  | 27-May-15 | Fired on Safe Release | Sent in for Evaluation                                | 499989                            | F      | Per Iion, replace trigger assembly, check over, and test fire at no charge                         |   |
| 11935 | 700         | not avail. | 3006 sprg | 16-Feb-70 | N | S       | 1-May-15  | 1-May-15  | Fired on Bolt Closing | Could Not Duplicate Concern                           | 499014                            | F      | Per Iion- Replace TA under BLP   |   |
| 11936 | 700         | 27123      | 3006 SPRG | 18-Mar-06 | N | S       | 1-May-15  | 22-May-15 | Fired on Safe Release | Could Not Duplicate Concern                           | 499013                            | F      | Per Iion - Repair at n/c - goodwill  |   |
|       |             |            |           |           |   |         |           |           |                       |   |                                   |        | Per Iion, quote to check over completely, repair as needed, and test, replace trigger at no charge |   |
| 11938 | 700         | 25773      | 3006 SPRG | 7-Nov-89  | N | S       | 1-May-15  | 27-May-15 | Fired on Safe Release | Could Not Duplicate Concern                           | 499996                            | F      | Per Iion- Replace with Ramac   |   |
| 11934 | 710         | 27408      | 270 WIN   | 23-Aug-02 | Y | S       | 1-May-15  | 1-May-15  | Fired on Bolt Closing | Altered Adjustments or Components                     | 499034                            | F      | #85844   |   |
| 11932 | 710         | 27410      | 3006 sprg | 20-May-05 | Y | S       | 1-May-15  | 1-May-15  | Fired on Bolt Closing | Could Not Duplicate Concern                           | 499029                            | F      | Per Iion- Replace with Ramac #85846  |   |
| 11942 | 700         | 84217      | 243 WIN   | 22-Mar-13 | N | S       | 5-May-15  | 5-May-15  | Fired on Bolt Closing | Could Not Duplicate Concern                           | 499202                            | F      | Per Iion: Repair at no charge  |   |
| 11943 | 700         | 27363      | 3006 SPRG | 17-Apr-09 | N | S       | 5-May-15  | 5-May-15  | Fired on Bolt Closing | Sent in for Evaluation                                | 499203                            | F      | Per Iion- Repair at no charge under recall.  |   |
| 11940 | 887         | 82502      | 12 GA     | 6-Apr-10  | N | S       | 5-May-15  | 5-May-15  | Fired Out of Battery  | Sent in for Evaluation                                | 499204                            | F      | Per Iion, check over completely, repair as needed, and test at no charge.                          |   |
| 11941 | SEVEN       | 24782      | 243 WIN   | 25-May-90 | N | S       | 5-May-15  | 5-May-15  | Fired on Safe Release | Could Not Duplicate Concern                           | 499199                            | F      | Per Iion: Repair at no charge  |   |
| 11944 | 597         | 26514      | 17 HMR    | 17-Jun-04 | N | PI/PD/S | 5-May-15  | 10-Aug-15 | My Gun Blew Up        | Other - Unspecified or Undetermined - Firearms        | 500821                            | F      | Replace with Ramac 27491 in exchange   |   |
| 11948 | 700         | 84408      | 300 RUM   | 6-Feb-09  | N | PD/S    | 6-May-15  | 7-May-15  |                       | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | n/a    | Check for \$954.56 CA \$5 for truck damage   |   |
| 11946 | 700         | N/A        | 270 WIN   | 14-Jan-81 | N | PD/S    | 6-May-15  | 2-Jun-15  | Fired on Safe Release | Altered Adjustments or Components                     | 500106                            | F      | Check over completely, repair as needed, and test at no charge                                     |   |
| 11950 | 700         | not avail. | 243 win   | 1-Mar-67  | N | S       | 8-May-15  | 8-May-15  |                       | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components | 499359 | F  | Per Iion- Replace TA under BLP              |
| 11954 | 700         | 27094      | 270 WIN   | 16-Jan-06 | N | S       | 8-May-15  | 8-May-15  | Fired With Safe ON    | Could Not Duplicate Concern                           | 499366                            | F      | Per Iion: Repair at no charge  |   |
| 11957 | 700         | 25971      | 300 RUM   | 15-Mar-01 | N | S       | 8-May-15  | 8-May-15  | Fired on Safe Release | Could Not Duplicate Concern                           | 499357                            | F      | Per Iion: Repair at no charge  |   |
| 11955 | 700         | 25807      | 300 WIN   | 16-Apr-93 | N | S       | 8-May-15  | 8-May-15  | Fired on Safe Release | Improper Maintenance                                  | 499319                            | F      | Per Iion: Repair at no charge  |   |
| 11952 | 700         | not avail. | 308 WIN   | 17-Sep-71 | N | S       | 8-May-15  | 8-May-15  |                       | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern       | 499367 | F  | Per Iion- Repair at no charge under recall. |
| 11951 | 700         | not avail. | 7MM REM   | 8-Mar-72  | N | S       | 8-May-15  | 8-May-15  | Fired on Safe Release | Could Not Duplicate Concern                           | 499365                            | F      | Per Iion- Replace TA under BLP   |   |

RAC001228

Confidential

|       |         |            |           |           |           |         |           |           |  |  |                                   |        |  |                                |
|-------|---------|------------|-----------|-----------|-----------|---------|-----------|-----------|--|--|-----------------------------------|--------|--|--------------------------------|
| 11964 | 770     | 85634      | 308 WIN   | 29-Apr-14 | Y         | S       | 12-May-15 | 12-May-15 | Fail to Fire                                 | Could Not Duplicate Concern                      | 499379                            | F      | Per Iion: Repair at no charge  |                                |
| 11962 | 887     | 82502      | 12 GA     | 28-Mar-14 | N         | S       | 12-May-15 | 12-May-15 | Unexplained Discharge - No Mention of Safety | Rotated Barrel Extension                         | 499402                            | F      | Per Iion: Repair at no charge  |                                |
| 11959 | 597     | 26514      | 17 HMR    | 23-Feb-05 | N         | PI/PD/S | 12-May-15 | 9-Jun-15  | My Gun Blew Up                               | Other - Unspecified or Undetermined - Firearms   | 500403                            | F      | Converting to 22 W/MR as requested by customer                             |                                |
| 11968 | 597     | 26536      | 17 HMR    | 26-Mar-03 | N         | PI/PD/S | 12-May-15 | 9-Jun-15  | My Gun Blew Up                               | Other - Unspecified or Undetermined - Ammunition | 500404                            | F      | Replace with Ramac 70723 in exchange                                       |                                |
| 11973 | 700     | 84207      | 308 WIN   | 25-Oct-13 | N         | PD/S    | 12-May-15 | 4-May-16  | Fired on Safe Release                        | Not Examined by Product Service                  | n/a                               | F      | Rifle not returned to Iion for exam  |                                |
| 11971 | 700     | N/A        | 3006 SPRG | 29-Nov-72 | N         | PD/S    | 13-May-15 | 17-Jun-15 | Fired on Safe Release                        | Could Not Duplicate Concern                      | 500657                            | F      | Check over completely, repair as needed, and test at no charge             |                                |
| 11974 | 700     | not avail. | 3006 SPRG | 1-Feb-68  | N         | S       | 15-May-15 | 15-May-15 | Fired on Bolt Closing                        | Could Not Duplicate Concern                      | 498910                            | F      | Per Iion- Replace TA under BLP   |                                |
| 11975 | 721     | not avail. | 270 WIN   | 1-Nov-73  | Y         | S       | 15-May-15 | 15-May-15 | Fired on Safe Release                        | Sent in for Evaluation                           | 499587                            | F      | Per Iion - Replace TA @ n/c  |                                |
| 11978 | SPR 210 | 89524      | 12 GA     | 19-Dec-05 | Y         | PI/S    | 19-May-15 | 28-Aug-15 | Personal Injury while using firearm          | Could Not Duplicate Concern                      | 501093                            | F      | Returned as Received as requested by customer                              |                                |
| 11982 | 700     | 27333      | 300 WSM   | 14-Feb-06 | N         | S       | 20-May-15 | 20-May-15 | Fired on Safe Release                        | Could Not Duplicate Concern                      | 499702                            | F      | Per Iion: Repair at no charge  |                                |
| 11985 | 700     | not avail. | 3006 SPRG | 15-Oct-69 | N         | S       | 20-May-15 | 20-May-15 | Fired on Safe Release                        | Could Not Duplicate Concern                      | 499716                            | F      | Per Iion- Replace TA under BLP   |                                |
| 11981 | 700     | 26449      | 6.8MM SPC | 21-Sep-05 | N         | S       | 20-May-15 | 20-May-15 | Fired on Safe Release                        | Altered Adjustments or Components                | 499714                            | F      | Per Iion: Repair at no charge  |                                |
| 11983 | 700     | not avail. | 7MM REM   | MA        | 1-Sep-64  | N       | S         | 20-May-15 | 20-May-15                                    | Fired With Safe ON                               | Altered Adjustments or Components | 499718 | F  | Per Iion- Replace TA under BLP |
| 11980 | 788     | not avail. | 6MM REM   | 18-Sep-78 | Y         | S       | 20-May-15 | 20-May-15 | Fired on Safe Release                        | Improper Maintenance                             | 499693                            | F      | Per Iion: Repair at no charge  |                                |
| 11979 | 887     | 82502      | 12 GA     | 13-Aug-10 | N         | S       | 20-May-15 | 20-May-15 | Unexplained Discharge - No Mention of Safety | Could Not Duplicate Concern                      | 499694                            | F      | Per Iion: Repair at no charge  |                                |
| 11986 | 700     | N/A        | 3006 SPRG | 1-Mar-61  | N         | S       | 20-May-15 | 4-Jun-15  | Light Trigger Pull                           | Could Not Duplicate Concern                      | 500188                            | F      | Per Iion, check over completely, repair as needed, and test at no charge.  |                                |
| 11995 | 700     | not avail. | 25-06 REM | 5-May-75  | N         | S       | 22-May-15 | 22-May-15 | Fired on Bolt Closing                        | Altered Adjustments or Components                | 499853                            | F      | Per Iion- Replace TA under BLP   |                                |
| 11993 | 700     | not avail. | 270 WIN   | 27-Jul-79 | N         | S       | 22-May-15 | 22-May-15 | Fired on Bolt Closing                        | Broken or Missing Parts                          | 499816                            | F      | Per Iion- Replace TA under BLP   |                                |
| 11996 | 700     | not avail. | 3006 SPRG | 24-Feb-76 | N         | S       | 22-May-15 | 22-May-15 | Fired on Safe Release                        | Altered Adjustments or Components                | 499820                            | F      | Per Iion- Replace TA under BLP   |                                |
| 11994 | 700     | 25833      | 308 WIN   | 9-Jan-92  | N         | S       | 22-May-15 | 22-May-15 | Fired on Bolt Closing                        | Altered Adjustments or Components                | 499818                            | F      | Per Iion: Repair at no charge  |                                |
| 11997 | 700     | 27480      | 7MM REM   | MA        | 31-Aug-99 | N       | S         | 22-May-15 | 22-May-15                                    | Fired on Bolt Closing                            | Could Not Duplicate Concern       | 499819 | F  | Per Iion: Repair at no charge  |
| 11998 | 1911R1  | 96323      | 45 ACP    | 18-Feb-14 | N         | S       | 22-May-15 | 22-May-15 | Went Automatic                               | Could Not Duplicate Concern                      | 499851                            | F      | Per Iion: Repair at no charge  |                                |
| 11999 | 597     | 26536      | 17 HMR    | 25-Oct-02 | N         | PI/PD/S | 22-May-15 | *         | My Gun Blew Up                               | Other - Unexamined                               |                                   | F      |  |                                |
| 12006 | 597     | 26513      | 22 LR     | 13-Mar-14 | N         | S       | 27-May-15 | 27-May-15 | Fired Out of Battery                         | Other - Unspecified or Undetermined - Firearms   | 499906                            | F      | Per Iion: Repair at no charge  |                                |
| 12009 | 700     | 25793      | 3006 SPRG | 5-Mar-85  | N         | S       | 27-May-15 | 27-May-15 | Fired on Bolt Closing                        | Could Not Duplicate Concern                      | 499893                            | F      | Per Iion, replace trigger assembly, check over, and test fire at no charge |                                |

RAC001229

Confidential

|       |       |            |                  |           |   |      |           |           |   |  |        |   |  |
|-------|-------|------------|------------------|-----------|---|------|-----------|-----------|---|--|--------|---|--|
| 12007 | 870   | 26462      | 20 GA            | 5-Jun-14  | N | S    | 27-May-15 | 27-May-15 | Jar-Off - No Mention of Safety Position               | Could Not Duplicate Concern                    | 499939 | F | Per llion: Repair at no charge                                 |
| 12010 | SEVEN | 85952      | 223 REM          | 8-Jan-08  | N | S    | 27-May-15 | 27-May-15 | Other - Firearms                                      | Sent in for Evaluation                         | 499894 | F | Per llion: Repair at no charge                                 |
| 12008 | 597   | 26537      | 22 LR            | 15-Aug-09 | N | PI/S | 27-May-15 | 24-Jul-15 | Fired Out of Battery                                  | Other - Unspecified or Undetermined - Firearms | 501168 | F | Replace w/26537 in exchange                                    |
| 12014 | 597   | 26537      | 22 LR            | 4-Sep-14  | N | PD/S | 27-May-15 | 21-Oct-15 | Unexplained Discharge - No Mention of Safety Position | Other - Unspecified or Undetermined - Firearms | 504642 | F | Check over completely, repair as needed, and test at no charge |
| 12017 | 597   | N/A        | 17 HMR           |           | N | PD/S | 29-May-15 | *         | My Gun Blew Up  | Other - Unexamined                             |        | F |  |
| 12022 | 700   | 25793      | 3006 SPRG        | 5-Mar-85  | N | S    | 1-Jun-15  | 1-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation                         | 500103 | F | Per llion: Repair at no charge                                 |
| 12021 | 700   | 25775      | 308 WIN          | 6-Sep-91  | N | S    | 1-Jun-15  | 1-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500102 | F | Per llion- Repair at no charge under XMP recall,               |
| 12018 | 700   | 27325      | 7MM-08 REM       | 30-May-03 | N | S    | 1-Jun-15  | 1-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation                         | 500108 | F | Per llion- Repair at no charge under XMP recall,               |
| 12020 | 710   | 27410      | 3006 SPRG        | 19-Jul-06 | Y | S    | 1-Jun-15  | 17-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 500101 | F | Replace w/85631 in exchange thru SNC                           |
| 12031 | 700   | 84214      | 204 RUGER 22-250 | 19-Dec-11 | N | S    | 4-Jun-15  | 4-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500233 | F | Per llion- Repair at no charge under XMP recall,               |
| 12026 | 700   | not avail. | REM              | 17-Feb-78 | N | S    | 4-Jun-15  | 4-Jun-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 500247 | F | Per llion- Replace TA under BLP                                |
| 12024 | 700   | 26915      | 3006 SPRG        | 15-Dec-93 | N | S    | 4-Jun-15  | 4-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500160 | F | Per llion- Repair at no charge under XMP recall,               |
| 12027 | 700   | not avail. | 3006 SPRG        | 17-Sep-76 | N | S    | 4-Jun-15  | 4-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Improper Maintenance                           | 500158 | F | Per llion- Replace TA under BLP                                |
| 12028 | 700   | not avail. | 3006 SPRG        | 13-Jul-76 | N | S    | 4-Jun-15  | 4-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500157 | F | Per llion- Repair at no charge under XMP recall,               |
| 12032 | 700   | not avail. | 3006 SPRG        | 7-May-74  | N | S    | 4-Jun-15  | 4-Jun-15  | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 500227 | F | Per llion- Replace TA under BLP                                |
| 12030 | 700   | not avail. | 7MM REM MA       | 3-Oct-87  | N | S    | 4-Jun-15  | 4-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation                         | 500165 | F | Per llion: Repair at no charge                                 |
| 12023 | 887   | 82502      | 12 GA            | 26-Aug-09 | N | S    | 4-Jun-15  | 4-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500159 | F | Per llion: Repair at no charge                                 |
| 12029 | 887   | 82502      | 12 GA            | 2-Aug-10  | N | S    | 4-Jun-15  | 4-Jun-15  | Fired on Bolt Opening                                 | Sent in for Evaluation                         | 500144 | F | Per llion: Repair at no charge                                 |

RAC001230

## Confidential

|       |           |            |            |           |           |      |   |           |           |   |  |        |   |   |
|-------|-----------|------------|------------|-----------|-----------|------|---|-----------|-----------|---|--|--------|---|---|
| 12041 | 700       | not avail. | 22-250 REM |           | 14-Jan-79 | N    | S | 8-Jun-15  | 8-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500347 | F | Per Iion- Replace TA under BLP  |
| 12042 | 700       | not avail. | 3006 SPRG  | 2-Mar-80  | N         | S    |   | 8-Jun-15  | 8-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500346 | F | Per Iion: Repair at no charge   |
| 12043 | 700       | not avail. | 3006 SPRG  |           | N         | S    |   | 8-Jun-15  | 8-Jun-15  | Fired on Safe Release                                 | Altered Adjustments or Components                | 500342 | F | Per Iion- Replace TA under BLP  |
| 12045 | 700       | 25793      | 3006 SPRG  | 7-Dec-83  | N         | S    |   | 8-Jun-15  | 8-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500349 | F | Per Iion- Repair at no charge under XMP recall.                               |
| 12047 | 597       | 26516      | 17 HMR     | 12-Feb-03 | N         | PD/S |   | 8-Jun-15  | 21-Aug-15 | My Gun Blew Up  | Other - Unspecified or Undetermined - Ammunition | 500946 | F | Replace with Ramac 70712 in exchange  |
| 12051 | 710       | 27410      | 3006 sprg  | 17-Mar-02 | Y         | S    |   | 9-Jun-15  | 9-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components                | 500415 | F | Per Iion- Replace with Ramac #85849   |
| 12049 | 887       | 82502      | 12 GA      | 11-Jul-11 | N         | S    |   | 9-Jun-15  | 9-Jun-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500389 | F | Per Iion: Repair at no charge   |
| 12050 | VERSA MAX | 81042      | 12 GA      | 10-Jan-12 | N         | S    |   | 9-Jun-15  | 9-Jun-15  | Jamming/Feeding issues                                | Choke Tube Concentricity                         | 500401 | F | Per Iion: Repair at no charge   |
| 12065 | 597       | 26537      | 22 LR      | 25-Mar-13 | N         | PD/S |   | 10-Jun-15 | 10-Jun-15 | Fired on Bolt Closing                                 | Other - Unspecified or Undetermined - Firearms   | 500444 | F | Per Iion: Repair at no charge   |
| 12059 | 700       | not avail. | 223 REM    | 1-Jul-63  | N         | S    |   | 10-Jun-15 | 10-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500348 | F | Per Iion, replace trigger assembly at no charge, replace bolt at 25% discount |
| 12057 | 700       | 85372      | 243 WIN    | 9-Apr-08  | N         | S    |   | 10-Jun-15 | 10-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500441 | F | Per Iion: Repair at no charge   |
| 12058 | 700       | not avail. | 270 WIN    | 1-Dec-87  | N         | S    |   | 10-Jun-15 | 10-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500440 | F | Per Iion- Repair at no charge under XMP update.                               |
| 12060 | 700       | not avail. | 3006 SPRG  | 21-Aug-79 | N         | S    |   | 10-Jun-15 | 10-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500451 | F | Per Iion- Repair at no charge under XMP update.                               |
| 12062 | 700       | not avail. | 3006 SPRG  | 4-Mar-80  | N         | S    |   | 10-Jun-15 | 10-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500453 | F | Per Iion- Repair at no charge under XMP update.                               |
| 12063 | 700       | 25773      | 3006 SPRG  | 16-Apr-93 | N         | S    |   | 10-Jun-15 | 10-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500452 | F | Per Iion- Replace TA under BLP  |
| 12061 | 700       | not avail. | 7MM REM    | MA        | 1-Jul-62  | N    | S | 10-Jun-15 | 10-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500442 | F | Per Iion- Replace TA under BLP  |

RAC001231

Confidential

|       |       |            |           |           |   |      |           |           |   |  |        |   |   |
|-------|-------|------------|-----------|-----------|---|------|-----------|-----------|---|--|--------|---|---|
| 12056 | SEVEN | 24793      | 243 WIN   | 16-Mar-01 | N | S    | 10-Jun-15 | 10-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Improper Maintenance                             | 500482 | F | Per Iion: Repair at no charge<br>Per Iion: Replace TA under BLP |
| 12066 | 700   | not avail. | 3006 SPRG | 1-Oct-74  | N | S    | 12-Jun-15 | 12-Jun-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                      | 500587 | F | Per Iion- Repair at no charge under XMP update.                 |
| 12067 | 700   | not avail. | 3006 SPRG | 15-May-69 | N | S    | 12-Jun-15 | 12-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation                           | 500536 | F | Per Iion- Repair at no charge under XMP update.                 |
| 12069 | 700   | 25793      | 3006 SPRG | 16-Aug-11 | N | S    | 12-Jun-15 | 12-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500538 | F | Per Iion- Repair at no charge under XMP update.                 |
| 12070 | 700   | not avail. | 6MM REM   | 26-Feb-71 | N | S    | 12-Jun-15 | 12-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation                           | 500535 | F | Per Iion- Repair at no charge under XMP update.                 |
| 12068 | 700   | not avail. | 7MM REM   | 28-Oct-76 | N | S    | 12-Jun-15 | 12-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation                           | 500537 | F | Per Iion- Replace TA under BLP                                  |
| 12071 | 597   | 26516      | 17 HMR    | 15-Mar-05 | N | PD/S | 12-Jun-15 | *         | My Gun Blew Up  | Other - Unexamined                               |        | F |   |
| 12078 | 597   | 26516      | 22 WMR    | 28-Aug-03 | N | PD/S | 16-Jun-15 | 16-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Other - Unspecified or Undetermined - Ammunition | 500601 | F | Per Iion: Repair at no charge<br>Per Iion- Replace TA under BLP |
| 12074 | 700   | not avail. | 270 WIN   | 23-Apr-76 | N | S    | 16-Jun-15 | 16-Jun-15 | Fired on Bolt Closing                                 | Improper Maintenance                             | 500675 | F | Per Iion- BLP   |
| 12077 | 700   | not avail. | 270 WIN   | 29-Mar-72 | N | S    | 16-Jun-15 | 16-Jun-15 | Fired on Bolt Closing                                 | Altered Adjustments or Components                | 500613 | F | Per Iion- Replace TA under BLP                                  |
| 12079 | 700   | not avail. | 270 WIN   | 1-Mar-64  | N | S    | 16-Jun-15 | 16-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500660 | F | Per Iion- Repair at no charge under XMP update.                 |
| 12080 | 700   | not avail. | 270 WIN   | 16-Oct-75 | N | S    | 16-Jun-15 | 16-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500659 | F | Per Iion- Replace TA under BLP                                  |
| 12075 | 700   | 25813      | 3006 SPRG | 3-Sep-96  | N | S    | 16-Jun-15 | 16-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500676 | F | Per Iion- Repair at no charge under XMP update.                 |
| 12081 | 1100  | 25330      | 12 GA     | 10-Feb-75 | N | S    | 16-Jun-15 | 16-Jun-15 | Fired Out of Battery                                  | Could Not Duplicate Concern                      | 500666 | F | Per Iion- Repair at 1/2 cost                                    |
| 12092 | 597   | 80850      | 22W/MR    | 11-Dec-14 | N | S    | 18-Jun-15 | 18-Jun-15 | Cartridge Cases Damaged during firing                 | Wrong Ammunition Fired in Gun                    | 500744 | F | Per Iion- Repair as needed at no charge.                        |
| 12087 | 700   | 25773      | 3006 SPRG | 30-Dec-94 | N | S    | 18-Jun-15 | 18-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500798 | F | Per Iion- Replace TA under XMP update                           |
| 12093 | 700   | Not Avail. | 6MM REM   | 5-Apr-72  | N | S    | 18-Jun-15 | 18-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                      | 500769 | F | Per Iion- Repair at no charge                                   |
| 12088 | 887   | 82500      | 12GA      | 27-Apr-11 | N | S    | 18-Jun-15 | 18-Jun-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                      | 500729 | F | Per Iion- Repair at no charge                                   |

RAC001232

## Confidential

|       |     |            |            |           |   |         |           |           |   |  |        |   |  |
|-------|-----|------------|------------|-----------|---|---------|-----------|-----------|---|--|--------|---|--|
| 12091 | 710 | 27418      | 243 WIN    | 8-Nov-06  | Y | S       | 18-Jun-15 | 17-Jul-15 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 500768 | F | Replace with Ramac 85842 in exchange   |
| 12095 | 870 | 25098      | 12 GA      | 8-Apr-10  | N | PI/PD/S | 18-Jun-15 | 18-Aug-15 | Fired Out of Battery                                  | Slow to Peak                                   | 502312 | F | Check over completely, repair as needed, and test at no charge               |
| 12103 | 700 | not avail. | 243 WIN    | 1-Nov-62  | N | S       | 23-Jun-15 | 23-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500839 | F | Per Iliion- Repair at no charge under XMP update.                            |
| 12102 | 700 | 27173      | 270 WSM    | 17-Nov-09 | N | S       | 23-Jun-15 | 23-Jun-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 500833 | F | Per Iliion- Repair at no charge under XMP update.                            |
| 12099 | 700 | 87882      | 300 WIN MA | 27-Jun-13 | N | S       | 23-Jun-15 | 23-Jun-15 | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 500802 | F | Per Iliion: Repair at no charge  |
| 12098 | 700 | not avail. | 308 WIN    | 16-Jun-81 | N | S       | 23-Jun-15 | 23-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500819 | F | Per Iliion- Repair at no charge under XMP update.                            |
| 12101 | 710 | 27408      | 270 WIN    | 19-Sep-05 | Y | S       | 23-Jun-15 | 23-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500820 | F | Per Iliion, replace with Ramac 85844 in exchange                             |
| 12100 | 770 | 85656      | 3006 SPRG  | 1-Jun-09  | Y | S       | 23-Jun-15 | 21-Jul-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500840 | F | Per Iliion: Replace w/85846 @ no charge                                      |
| 12111 | 887 | 82500      | 12 GA      | 18-Feb-10 | N | PD/S    | 25-Jun-15 | 25-Jun-15 | Broken Part   | Sent in for Evaluation                         | 500947 | F | Per Iliion: Repair at no charge  |
| 12109 | 700 | 84600      | 223 REM    | 5-Sep-12  | N | S       | 25-Jun-15 | 25-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500948 | F | Per Iliion- Repair at no charge under XMP update.                            |
| 12106 | 700 | not avail. | 3006 SPRG  | 4-Feb-78  | N | S       | 25-Jun-15 | 25-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500923 | F | Per Iliion- Replace TA under BLP   |
| 12107 | 700 | not avail. | 3006 SPRG  | 20-Aug-75 | N | S       | 25-Jun-15 | 25-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 500924 | F | Per Iliion- Repair at no charge under XMP update.                            |
| 12108 | 700 | not avail. | 7MM REM MA | 7-Mar-78  | N | S       | 25-Jun-15 | 25-Jun-15 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 500925 | F | Per Iliion- Replace TA under BLP   |
| 12110 | 870 | 25549      | 12 GA      | 27-Mar-14 | N | S       | 25-Jun-15 | 25-Jun-15 | Fail to Fire  | Sent in for Evaluation                         | 500968 | F | Per Iliion: Repair at no charge  |
| 12114 | 700 | 84600      | 223 REM    | 12-Sep-13 | N | PD/S    | 30-Jun-15 | *         | Fired on Bolt Closing                                 | Other - Unexamined                             |        | F |  |
| 12117 | 597 | 26536      | 17 HMR     | 24-Oct-02 | N | PD/S    | 1-Jul-15  | 1-Jul-15  | My Gun Blew Up  | Other - Unspecified or Undetermined - Firearms | 501062 | F | Per Iliion, converting to 22 WMR as requested by customer.                   |
| 12118 | 700 | 26909      | 270 WIN    | 3-Dec-93  | N | S       | 1-Jul-15  | 1-Jul-15  | Delayed Firing - Firearms                             | Could Not Duplicate Concern                    | 501052 | F | Per Iliion, replace trigger assembly, check over, and test fire at no charge |
| 12115 | 700 | N/A        | 3006 SPRG  | 25-May-78 | N | S       | 1-Jul-15  | 1-Jul-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 501060 | F | Per Iliion, replace trigger assembly, check over, and test fire at no charge |

RAC001233

## Confidential

|       |        |            |            |           |   |   |           |           |   |  |        |   |   |
|-------|--------|------------|------------|-----------|---|---|-----------|-----------|---|--|--------|---|---|
| 12116 | 700    | N/A        | 3006 SPRG  | 26-Jul-76 | N | S | 1-Jul-15  | 1-Jul-15  | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 501061 | F | Per Ilion, replace trigger assembly, check over, and test fire at no charge                 |
| 12119 | 700    | 25934      | 3006 SPRG  | 8-Feb-12  | N | S | 1-Jul-15  | 1-Jul-15  | Other - Firearms                                      | Sent in for Evaluation                         | 501053 | F | Per Ilion, replace trigger assembly, check over, and test fire at no charge                 |
| 12120 | 700    | 27269      | 3006 SPRG  | 19-Sep-11 | N | S | 1-Jul-15  | 1-Jul-15  | Unexplained Discharge - No Mention of Safety Position | Sent in for Evaluation                         | 501054 | F | Per Ilion, replace trigger assembly, check over, and test fire at no charge                 |
| 12121 | 700 ML | 27589      | 50 CAL     | 17-Oct-02 | N | S | 6-Jul-15  | 6-Jul-15  | Fired on Bolt Closing                                 | Sent in for Evaluation                         | 501095 | F | Per Ilion, replace trigger assembly, check over, and test fire at no charge                 |
| 12126 | 700    | N/A        | 7MM REM MA | 13-Oct-70 | N | S | 7-Jul-15  | 7-Jul-15  | Unexplained Discharge - No Mention of Safety Position | Improper Maintenance                           | 501270 | F | Per Ilion, replace trigger assembly, check over, and test fire at no charge                 |
| 12128 | 710    | 27410      | 3006 SPRG  | 3-Apr-03  | Y | S | 7-Jul-15  | 28-Jul-15 | Fired With Safe ON                                    | Sent in for Evaluation                         | 501273 | F | Per Ilion - Replace w/85846 - goodwill  |
| 12129 | 887    | 82500      | 12 GA      | 9-Nov-09  | N | S | 7-Jul-15  | 7-Jul-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 501182 | F | Per Ilion - Repair at n/c   |
| 12124 | 1187   | 29591      | 20 GA      | 26-Oct-99 | N | S | 7-Jul-15  | 7-Jul-15  | Safety not working properly                           | Could Not Duplicate Concern                    | 501277 | F | Per Ilion - Repair at n/c - goodwill  |
| 12125 | ACR    | 90838      | 223/5.56   | 3-Oct-13  | N | S | 7-Jul-15  | 7-Jul-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 501219 | F | Per Ilion, check over completely, repair as needed, and test at no charge.                  |
| 12133 | 700    | 25798      | 223 REM    | 13-Dec-94 | N | S | 8-Jul-15  | 8-Jul-15  | Fired on Bolt Closing                                 | Could Not Duplicate Concern                    | 501271 | F | Per Ilion - Repair at n/c   |
| 12132 | 700    | 27363      | 3006 SPRG  | 7-Mar-05  | N | S | 8-Jul-15  | 8-Jul-15  | Fired on Bolt Closing                                 | Altered Adjustments or Components              | 501274 | F | Per Ilion - Repair at n/c   |
| 12131 | SEVEN  | 24786      | REM        | 24-Sep-91 | N | S | 8-Jul-15  | 8-Jul-15  | Fired on Bolt Opening                                 | Altered Adjustments or Components              | 501272 | F | Per Ilion - Repair at n/c   |
| 12134 | 770    | 85634      | 308 WIN    | 5-Mar-08  | Y | S | 8-Jul-15  | 17-Aug-15 | Fired on Safe Release                                 | Altered Adjustments or Components              | 501268 | F | Per Ilion - Replace w/85847 in exchange & ck for \$26.50 (transfer fee)                     |
| 12143 | 597    | 26514      | 17 HMR     | 20-Nov-06 | N | S | 10-Jul-15 | 10-Jul-15 | Other - Firearms                                      | Other - Unspecified or Undetermined - Firearms | 501383 | F | Converting to 22 WMR as requested by customer   |
| 12146 | 700    | 84226      | 22-250 REM | 24-Jul-12 | N | S | 10-Jul-15 | 10-Jul-15 | Other - Firearms - XMP Update                         | Could Not Duplicate Concern                    | 501377 | F | Per Ilion, replace trigger assembly, replace action, check over, and test fire at no charge |
| 12145 | 700    | not avail. | 243 WIN    | 27-Nov-79 | N | S | 10-Jul-15 | 10-Jul-15 | Unexplained Discharge - No Mention of Safety Position | Could Not Duplicate Concern                    | 501403 | F | Per Ilion - Replace TA & test @ n/c   |
| 12147 | 700    | 25771      | 270 WIN    | 7-May-84  | N | S | 10-Jul-15 | 10-Jul-15 | Fired on Safe Release                                 | Could Not Duplicate Concern                    | 501342 | F | Per Ilion - Replace TA & test @ n/c   |
| 12144 | 700    | not avail. | 3006 SPRG  | 31-May-74 | N | S | 10-Jul-15 | 10-Jul-15 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 501280 | F | Per Ilion - Replace TA @ n/c  |
| 12149 | 700    | N/A        | 3006 SPRG  | 29-Mar-76 | N | S | 10-Jul-15 | 10-Jul-15 | Unexplained Discharge - No Mention of Safety Position | Altered Adjustments or Components              | 501407 | F | Per Ilion, replace trigger assembly, check over, and test fire at no charge                 |

RAC001234